CDC E3E351

Structural Journeyman

Volume 4. Electric Arc Welding



Air Force Career Development Academy The Air University Air Education and Training Command

> E3E351 04 1508, Edit Code 01 AFSC 3E351

Author: MSgt Joshua D. Horton 366th Training Squadron 366 TRS/TRR 727 Missile Road Sheppard AFB, Texas 76311 DSN: 7365816 E-mail addressjoshua.horton@usf.anil

Instructional Systems

Specialist: Steve McCarver

Editor: Maxine Baldwin

Air Force Career Development Academy (AFCDA) Air University (AETC) Maxwell AFB, GunterAnnex, Alabama 3614-3107

Material in this volume is reviewed annually for technical accuracy, adequacy, and currency. For SKT purposes the examinee should check the Weighted Airman Promotion System Catalog to determine the correct references to study.

THIS VOLUME covers the electric arc welding and cutting processes and equipment that are required for the structural career field.

Unit 1 covers shielded metal arc welding equipment, preparation, challenges, positions, and applications including hard surfacing to 2 and unit 3 covertungsten inert gas (TIG) welding and metallic inert gas (MIG) welding equipment, preparation, challenges, positions, and applications. Unit 4 covers arc cutting using plasma and shielded metal arc welding equipment.

A glossary is included for your use.

Code numbers on figures are for preparing agency identification only.

The use of a name of any specific ma**ctuíæ**r, commercial product, commodity, or service in this publication does not imply endorsement by the Air Force.

To get a response to your questions concerning subject matter in this course, or to point out technical errors in the text, unit review exes, or course examination, call or write the author using the contact information on the inside front cover of this volume.

NOTE: Do not use the IDEA Program to submit corrections for printing or typographical errors.

If you have questions that your sopieor, training manager, enducation/training office cannot answer regarding course enrollment, course material, or administrative issues, please contact Air University Educational Support Services at <u>http://www.aueducationsupport.Bens</u>ureyour request includes your name, the last four digits of your sectalrity number, address, and course/volume number.

This volume is valued at 12 hours apploints.

NOTE:

In this volume, the subject matter is divided into-**self** tained units. A unit menu begins each unit, identifying the lesson headings and numbers. After reading the unit menu page and unit introduction, study the section, answer thef **stels** questions, and compare your answers with those given at the end of the unit. Theorem let the unit review exercises.

| | Page |
|--|-------------|
| Unit 1. Shielded Metal Arc Welding | |
| 1–1. SMAW Principles and Equipment | 11 |
| 1–2. SMAW Electrodes and Machine Setup | 1-12 |
| 1–3. SMAW Procedures | 1-26 |
| 1–4. Hard Surfacing | |
| Unit 2. Tungsten Inert Gas Welding | |
| 2–1. Principles and Equipment | 2-1 |
| 2–2. Application Procedures | 2-8 |
| Unit 3. Metallic Inert Gas Welding | |
| 3–1. Principles and Equipment | 3-1 |
| 3–2. Application procedures | 3-7 |
| Unit 4. Arc Cutting | |
| Glossary | <u>G-</u> 1 |

| Electrical Terms | | | | | | |
|------------------|--|--|--|--|--|--|
| Term | Definition | | | | | |
| Circui t | The path taken by an electric current in flowing through a conductor from one terminal of the source of supply to the other. | | | | | |
| | It starts from the negative terminal of the power supply where the current is produced, moves along the wire or cable to the load or working source, and then returns to the positive terminal (fig. 1–1). | | | | | |
| | Figure 1 –1. Arc welding circuit. | | | | | |
| Voltage | The force that causes current to flow in a circuit. | | | | | |
| | Voltage does not flow; only current flows. Voltage pushes the current through the wires similar to a pump providing the pressure used to make water flow through pipes. | | | | | |
| Ampere | Also known as Amp is a unit of measure for electricity that expresses the quantity or number of electrons flowing through a conductor per unit of time. | | | | | |
| Ohm | An electrical circuit has a certain amount of resistance. | | | | | |
| | An ohm is the amount of resistance in an electrical circuit. | | | | | |
| | One ohm is the result of 1 volt applied across a resistance that allows 1 amp to flow through it. | | | | | |
| Arc length | In shielded metal arc welding, the proper length of arc is necessary to make good welds. | | | | | |
| | An arc that is too long produces an unstable welding arc, increases splatter, reduces penetration, causes flat and wide beads, and prevents the gas shield from protecting the molten pool from atmospheric contamination. | | | | | |
| | If too short of an arc is used, the arc does not create enough heat to melt the base metal, the electrode has a tendency to stick, penetration is poor, and beads are uneven with irregular ripples. | | | | | |

Current

When a circuit carrying a current breaks, the current continues to flow across the gap between the terminals until it is no longer able to jump the gap. Superheated gases from the atmosphere and particles of metal from the terminals carry the current allowitogbridge this gap. This action causes an intensely bright light called an electric **Since** the resistance is very high in the arc, a great deal of electrical energy is converted into heat, both in the arc and at the points where it enters and leaves the terminals. The proper arc length causes the metal exposed to it to melt instantly.

The direct current (DC) anvelding machine, used for electric arc welding, gets its electrical power from a generator driven by an electric motor, gas, or diesel engine. The generator voltage usually varies from 8 to 36volts across the arc, although settings may vary with changes in arc length. Welding machines available capable of handling current output from 50 to 600 amperes to accommodate various arc welding requirements. Generator is most welding machines is a variable voltage type arranged automatically adjust he voltage to the demands of the arc. Some machines allow you to manually adjust the direct currents amperage by flipping a selector switch or a series of plug receptacles. When you can manually adjust both the voltage and amperage of the welder, the machine is known as a direct type.

Advantages direct curreate welding has over ternating current are:

- x Better at low currents and with small diameter electrodes.
- x All classes of covered electrodes can be used with satisfactory results.
- x Arc starting is generally easier.
- x Maintaining a short arc is easier.
- x Easier to use for outf-position welding because lower currents can be used.
- x Easier to use for weldingheet metal.
- x Generally produces less weld spatter.

Polarity

Polarity indicates the direction of the current flow in that circuit and is a term used to describe whether an item is positely or negatively chargedIn arc welding, the electrical circuit has a negative and positive terminal or police. a DC circuit, the current flows in one direction only. You must change polarity for certain welding operations. Heat can be concervited re it is needed (amount of heat going into the base metal) by changing the polarity. The amount of heat going into the base metal) by changing the polarity.

Straight polarity

Straight polarity (ig. 1–2) directs more heat to the metal being welder electrode is connected to the negative pole at the welding machine and the work is connected to the positive is also known as direct current negative (DCS traight polarity is used when heavy deposits of metal are required

Figure 1 –2. Arc welding circuit, straight polarity.

Reverse polarity

When arc welding, you need to have the heat concentrated where it will do the most good. This is where we sometimes use reverse polarity. The welding machine is hooked up with the work connected to the negative side and the electrode to the positive side. The machine is set so that the current flows from negative to positiveThis polarity is also known asirect current positiveDC+). The reverse polarity concentrates the heat more on the electrode than the material to be welded. (Bigboovs-the reverse polarity circuit.) Reverse polarity is a good choice when you need to keep the material to be welded as cool as possible, such as weldeastron or when welding overhead.

Alternating current

When you use an alternating current (AC) welding machine, you've no choice of polarity since a characteristic of ACis to change its polarity twice during each cycle (current flows in one direction the first half of the cycle and in the posite direction for the second half). For this reason, it is not possible to use AC machines for all types of weddAlternating current welding has one advantage over DC welding in AC welding, the polarity charegovith each cycle reduces magnetic arc blow. Alternating current is well suited for the welding of thick sections using large diameter electrodes. Alternating current's epth of penetration deposition rates are generally intermediate between those of DC electrode positive and DC electrode negative.

Weld metal deposition

When you are shielded metal arc welding, you have to adjustite force and dist forces that are responsible for the transfer, or depositing, of molten filler metal and molten slag to the base metal. These forces are identified and explained in the following table

| Weld Metal Deposition Forces | | | | | |
|------------------------------|--|--|--|--|--|
| Force | Definition | | | | |
| Gravity | Gravity is the main force responsible for filler metal transfer in flat-position welding | | | | |
| | In other positions, smaller electrodes must be used to avoid excessive loss of weld metal and slag, since gravity's influence on the surface tension is unable to retain a large molten metal volume and molten slag in the weld crater. | | | | |
| Gas expansion | In arc welding, gasses are produced from the burning of the electrode covering. | | | | |
| | The heat generated by the electrical current causes the electrode tip to boil. This action rapidly expands the gases, projecting the electrode's metal and slag in globular form away from the solid electrode tip and into the molten crater. | | | | |
| | The coating extending beyond the electrode's metal tip controls the gas expansion direction and directs the molten metal globule into the weld crater formed in the base metal. | | | | |
| Electromagnetic | The electrode tip acts as an electrical conductor; the molten metal globule is also an electrical conductor and is affected by magnetic forces with the greatest influence at 90° to the direction of the current flow. | | | | |
| | These forces produce a pinching effect on the metal globules and act to speed up the molten metal separation from the electrode end. | | | | |
| | This effect is particularly helpful in transferring metal in horizontal-, vertical-, and overhead-position welding. | | | | |
| Surface tension | Surface tension is the force that keeps the molten metal and slag globules in contact with molten base or weld metal in the crater. | | | | |
| | It also helps to retain the molten metal in horizontal, vertical, and overhead welding and also to determine the shape of the weld contours. | | | | |

Magnetic arc blow

A phenomenon of DC arc welding is the arc's tendency to waver as though an air**bde**ase **is** lown against it. This tendency is often encounters been welding in corners and at the start and end of butt joints. The arc is forcibly moved by a magnetic field set up in the work by the flow of the welding current The direction and arbeending amount depend on the magnetic field direction and strength. Welders use arrious methods to try to eliminate this interference. The goal is to minimize or counteract the magnetic field at the point at which it is desired to hold the arc. Changing the ground plate position with reference to the arc may change the electrical current path through the work and eliminate the magnetic field surrounding the arc. Changing the electrode angle to the work is helpful

in some cases. It is impossible to lay down definite rules be **sousse**ny factors are involved. When welding with AC, there are practically no magnetic arc disturbances.

NOTE: Magnetic arc blow results in excessive splatter and breaks the continuity of the deposited metamaking it necessary to refill the crater, which can leave weak spots.

Heat's effect on arc webing

When you are arc welding, electrical energy changes into heat. The lifest so the base metals grain structure is divided into three heaterted zones.

| Heat-Affected Zones | | | | |
|----------------------------------|--|--|--|--|
| Zone | Zone Description | | | |
| Very hot zone | This is next to the molten filler metal. | | | |
| | It shows a transition from the molten filler metal to the annealed zone. | | | |
| Annealed zone | This is next to the heated base metal. | | | |
| | It shows a transition from the heated base metal to the annealed zone. | | | |
| Zone next to the cold base metal | This shows a transition from annealed zone to the unchanged cold base metal. | | | |

The rate that heat is applied to the plates is greater in arc welding than it is in oxyacetylene welding; this causes a higher heat concentration at a particular **bintesult** is steeper heat gradient with less metal affected by the heat. The electrode that you use has a big impact on affected tarea. When you use a normated metal electrode, such as stainless steel, the affected zone is small. When you use a heavopated steel electrode, the heat area is larger.

Heat affectingfactors

The heataffected area increases with the welding energy used in arc welding. The challenge is to get the current set right because the generated welding heat is directed to the voltage and amperage settings. Greater penetration for arc welds is not necessarily obtained with an increase in the heataffected area. This increase is in width rather than detathally, the smaller the heat affected area, the more rapid the heat removal from the affected area. You can increase the heat affected area in arc welding by:

- x Maintaining a constant current while decreasing the welding speed.
- x Maintaining a constant welding speed while increasing the current.
- x Maintaining a constant welding speed while going from a thick plate sectiohight plate section.
- x Increasing the arc length while settings on the welding machine remain unchanged.
- x Preheating the area to increase the-bffacted area.

Hardness in arowelding

The heataffected area ishielded metal arc welding produces a greater concentrated hardness than that produced with oxyacetylene welding he challenge is to keep the weld from cracking as it cools. In general, the greater the hardness the likely the weld is to crack when the molten metal solidifies. Arc welds on plate containing 35 or higher percentage of carboon a greater increase in hardness than steels containing a lower bon amount. In some alloy steels, carbon elements are added to increase the strength, but the carbon also increases the hardness. The carbon content in easily welded plate is usually kept low to prevent excessive hardness in the welding operation. In plain carbon steels having 25 percent carbon or less, welde by either arc or gas welding do not change hardness, ductility; tensile strength to a noticeable degree.

602. Selecting and maintaining SMAW equipment

In this lesson, we look at the different types of power sources and accessories for SMAWesnach you may use. There are slight variations between manufacturers; however, the general characteristics and maintenance procedures are similar. Let's begin with the different types of power sources.

Welding power sources

Arc welding machines get electrical current from a commercial source, such as an electrical power line, or from a portable sourceuch as an engine driven generator. These machines allow you to adjust the electrical current to match your arc welding needs. Some allow you to changerthe AC DC. Let's look at some of the general characteristics of different arc welding machines.

Weldingmachinesizes

Welding machines are rated according to their approximate amperage capacity at a state of the cycle. The various sizes of machines may be 2050, 250-300, or 400600 amps. The size of the welding machine be used is governed largely by the kind of welding that is to be done. The following tableserves as a general guide to size and service.

| Welding Machine Sizes | | | | |
|-----------------------|---|--|--|--|
| Size | Used For | | | |
| 150-200 | Light to medium duty welding. | | | |
| Ampere | Excellent for all fabrication purposes and rugged enough for continuous operation on light or medium production work. | | | |
| 250-300 | Average welding requirements. | | | |
| Ampere | Used in plants for production, maintenance, repair, tool room work, and all general shop welding. | | | |
| 400-600 | A machine for heavy duty welding with large capacity and for a wide range of purposes. | | | |
| Ampere | It is used extensively in heavy structural work, fabricating heavy machine parts, heavy pipe, and tank welding, and for cutting scrap, and cast iron. | | | |

Machine classification

We classify wilding machines into two main groups sonstant potential on constant current Constant potential welding machines are used primarily for metallic inert gasime, which we discuss later.

Constant current/velding machines are designed primarily for Shielded Metal Arc Welding, sometimes referred to as "stick welding". Constant current welding machines produce austiplydy s of current over a wide range of weldi voltages regardless of changes in arc length. Since it is difficult to continuously hold the arc length at a prescribed distance while welding, constant current machines have smadurrent changes with changes in arc length. Welding heat and electroedeffb rate are influenced very little, which allewhewelder to maintain good control of the weld puddle. A constant current welding machine has a sloping avoid characteristic which allows for easier arc starting with all types of electrodes. The acateristic allows the welder to slightly vary the heat while welding

Alternating current transformers

These welding machines drawrrent only when in usthe machines are remarkably economical in electric power consumption. They're easy to adjuthedrequired current settings and require little maintenanceTransformer welding machines are equipped with an arc booster switch that supplies a burst of current for easy arc startiag soon as the electrode touches the wafter the arc is struck, the current automatically returns to the amount set for the job

Advantages of a transformer machinelude

- x Least expensive, lightestnd smallest of the welding machines.
- x Produces AC current.
- x Low operating cost, high overællectricalefficiency.
- x Noiseless operation.
- x Free from magnetic arc blow.

Direct current transformerrectifiers

These welding machines æquipped with rectifierandoperate by changing œctifying AC to DC for welding and are usually constant current ducatorial type. These machines produce DC current in straight and reverse polarity. The polarity depends on the kind of electrode used and the material to be welded. Welders use awitch to manually change polarity. The welder can use two control knobs to adjust the welding the welding provides an approximate or second provided for second control is for fine adjustment of the welding ampe@ther controls are provided for changing the welding current to the open circuit voltage and to the desiredypollaeitmain advantage of this type is thatallows greater flexibility for welding materials of different thicknesses by changing the slope of the output current to produce a soft or harsh arc. Other advantages include:

- x The ability to adjust to produced agging arc for deeper penetration into thick metals.
- x The ability to adjust to produce a soft or quiet arc for welding light gauge metals.

Alternating current-direct current transformer-rectifiers

These welding machines are essentially a transformer that contains an electrical device which changes alternating current into direct current. They may be constant current or constant potentialing on the design of the machine. These machines provide and DC current when the output terminals are changed by a switch between the transformer and rectifier. AC/DC transfectifieers are more electrically efficient and quiet than the generator type. They are very versatile and can handle a great variety of welding tasks. You can choose AC or straight current control as the welders as switch to set the desired current range and a dial for fine adjust Figure 1-4 shows a typical transformer current fire used in Air Force welding shops.

Alternating current-direct current enginedriven generator

When an electrical power source is not available, a gasolinessed **die**gine is used to drive the welding generatorThe engine is equipped with a govertheat controls the demand on the generator. The complete unit usually is mounted on a trailer chassis that can be towed to the work location.

Accessories

All arc-welding machines require certain accessories to make up a complete weldin **Gent#itally** these include welding cables, electrode holders, ground clamps, and cable connectors. We'll look at each of these in more detail in the following paragraphs.

Welding cables

The cables carry the current to and from the work. **Cable** runs from the welding machine to the electrode holder, and the other cable is attached to the work or bench. The cable connected to the work is called the ground cable. When the welding machine is turned on and the electrode in the holder comes in contact with the work, a circuit is forn the allows the electricity to flow. It is important to use the correct diameter categories for the welding machine.

NOTE: If the cable is too sall for the current, it overheats and power is lost. A larger cable is necessary to carry a required voltage any distance from the mathematise, there will be an excessive voltage drop ut must take precautionst to exceed the recommended lengthstary larger diameter cables cause the voltage drop will lower the efficiency of your welding.

Check with the welding machine manufacturer for the proper cable size and for specific lengths and usages. Welding cable sizes depend on the welding curretterwelding cable length. The following areexamples of correct sizes and lengths for cable:

- x Cablelengths up to 100 feet **20**0 welding currentequire a #2 cable.
- x Cable lengths up to 100 featt300 welding currentequirea #1cable.
- x Cable length sup to 100 feet at 400 welding current require #1or #0 cable

Use ubbercovered, multistrand copper cable made specifically for arc welding. The more strands in a given size cable makes the welding leads more flexible and tealsteridle.

All welding leadconnections must be tight because loose connections cause the lug, lead, or clamp to overheat. A loose connection may also produce arcing at the conn**Kei** would be leads clean and handle hemso that you avoid daming the insulation.

NOTE: Preventwelding cables from coming in contact with hot metal, water, oil, or grease, and **a**tp corners.

Oil and grease breakdown the rubber surrounding the wire. Bare wires could cause you to get shocked. Keep cables in an orderly manner to prevent them from the from the hazard.

Electrodeholder

An electrode holder is essentially a clamping device for holding the electrode securely in any position. The welding cable passes through the hollow, insulated handle holder. Having an insulated holder is an advantage because it allows you to touch any part of the work without danger of short circuiting. It also allows you to change the electrodes quickly and esigns to match the electrode's size and weltering Werlding with a machine having a 300 mpere rating requires a larger holder than when welding with a 100-ampere unit. Using holder that is smaller than specified will cause it werheat. Make sure that all exposed surfaceincluding the jaws, are protected by insulation.

NOTE: Be sure the jaws of the electrode holder are properly insulated. Laying the uninsulated jaw of the holder on the bench while the machine is running will cause a flash.

Ground clamp

The work must beconnected to the welding machine. This is done with a second cable. For best results, mount a brass grounding clamp to the grounding cable. Brass is an excellent ground for electrical current and with a little care, provide excellent service for a longitie. Youcan also fasten ground cables to the work or bench with a C clamp, a special ground clamp, or by bolting or welding the lug on the end of the cable to the bench.

Cable connectors

If you must extend a welding lead, join the two welding cables together with cable connectors like those shown in figure-5. These connectors fit tightly together for a good connection between the two welding leads. They also insulate the welding lead where the connection is made.

Figure 1 –5. Cable connectors.

Joining welding cables with devices other than cable connectors is not safe. An example of an unsafe connection is joining welding leads with two ground clamps. In this situation the ulated lamps could tout the welding circuit, creating an electrical arc and possible fire. Another possibility is your touching the uninsulated clamps, making you part of the welding circuits could causeou to receive a serious shock.

Operator maintenancerequirements for arc welding machines

Welding machines require routine maintenance to keep them operating safely and properly. One primary tasks to always remove dust and grit after use. Although you can perform routine maintenance, you should have a qualified eleiatriperform any extensive repair or adjustment

The following periodic maintenance schedule should help to prevent a major breakdown and prolong the arc welding machine life. You can find maintenance requirements in your shop's machine maintenance guides the owner's manual keep an inspection record for each machine, noting all maintenance performed and dates performed.

Cleaning and inspection

Review and follow your shop's maintenance schedule to keep the welding machine in good operating condition. On a daily or assed basis, check the cables, ground, and electrode holder for bare wires and loose connections. On a weekly basis, check the welding machine for loose nuts, bolts, screws, or parts. These work loose due to the vibrations caused by the cooling fan and generator.

Air is drawn into the machine by the cooling fan and circulated through passages and around the windings. An accumulation of dust in these areas **canse** ased operating temperatures. Clean out the machine with dry compressed aff the machine is greasy, take it apart and thoroughly clean it as needed or on a monthly basis.

Electrical parts

Using the monthly inspection, check the brushes and commutator. Also check the switch contact points and bearings o assure posite brush contact, replace brushes that have worn enough to reduce their spring tension, and brush springs that have been weakened from overheating.

Each time the brushes are replaced, check the commutator for cleanliness and wear. A commutator in good condition has a deep bronze color. Remove ridges or pockets on the commutator surface by turning it down on the lathe. Sand electrical switch contacts smooth if they're pitted. Replace badly burned contacts.

NOTE: The electrical parts maintenance, repair, repair, reputacement mentioned, is usually done by vehicle maintenance or another trained professional. If done incorrectly, it could cause serious injury or even deates well as damage the machine.

Lubrication

Usually, we lubricate a welding machine's movingts based on the hours that it is in operation. find out, check the manufacturer's maintenance schedule. It's a good idea to make sure that the machine is lubricated at least every 46 tononths even if its not used much. When lubricating the welder, be surthat you don't use too much grease. Excess grease can be thrown on the commutator or windings, causing the insulation to deteriorate and possibly ngaus hort circuit. Use the grease specified by the manufacturer on the data plate the insulation and the insulation is the insulation in the insulation is deteriorate.

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

601. SMAW principles

- 1. Briefly explain each of the following terms:
 - a. Circuit.
 - b. Voltage.
 - c. Ampere.
 - d. Ohm.
- 2. Why is along arc length undesirablehen performing arc welding?
- 3. What polarity is present when the electricity flows from the electrode to the work
- 4. List the four forces responsible for transferring the molten metal when arc welding.

- 5. What conditioncauses arc blow?
- 6. What three heatiffected zones do you encounter when arc welding?
- 7. Does greater penetration mean you'll have a largeratifeetted area? Why?
- 8. How does the arc length affect the haffected area?
- 9. How is the heataffected area changed when you keep the current constant but decrease the welding speed
- 10. Comparing arc welding to oxyacetylene welding, which produces greater hardness in-the heat affected zone?

602. Selecting and maintaining SMAW equipment

- 1. What size welding matine is used foaverage welding requirements and in plants for production, maintenance, and all general shop we?ding
- 2. Welding machines are classifiention what two main groups
- 3. Which welding machine is the least expensive, lightest, and smallest?
- 4. Which welding machine can provide AC and DC straight and reverse polarity welding current?
- 5. What can we use to produce welding current when we were king in the field where no commercial source of electrical power is available?
- 6. What is the advantage of having an insulated electrode holder
- 7. When you are joining welding cableshat do you use to extend them

- 8. Where can you find detailed instructions about the maintenance of arc welding machines?
- 9. What four electrical parts must you check movi?hl
- 10. How often do you lubricate a welding machimenoving parts?

1-2. SMAW Electrodes and Machine Setup

In this section, we discuss the different types of electrodes, machine **and up**eld preparations. You must be able to determine which electrodessaited for different welding tasks and how to properly setup a SMAW machine and prepare metal for specific jobs. Let's begin with SMAW electrodes.

603. Selecting SMAW electrodes

When selecting an electrode for a,jobu must know the electrodespecific characteristics, properties, welding current, polarity, and position, as well as properties of the base metal, diameter of the electrode, and type of joinMany electrode classification charts list the basic characteristics or differences in electrodes to help you to determine the best electrode to use. The electrode you select must be able to produce the required characteristics network determine electrode provides base characteristics:

- x Smooth and constant
- x Smooth weld bead with maximum streingtind minimum spatter.
- x Able to fill in the crater for the required amperage used.
- x Easy slag removal.

When selecting an electrode you always consider the properties of the base metal. The electrode used must produce a weld with approximately the same mechanical properties as the base metal. The electrode must produce must be matched to be welded.

Proper diameter is importantial selecting the appropriate electrode for a **Toble** electrode you select must be larger than the thickness of the welded

NOTE: The largest diameter that you use for overhead and vertical possitions inch.

You must alsoconsider welding current and polaritwhen selecting an electrode. Electrodes are designed to be used with AC, DC straight DC reverse polaritySome manufacturers designate DC electrodes as DE lectrode Negative (DEN) and DGE lectrode Positive (DEP). This designation helps to minimize electrode polarity confusion.

Some electrodes are made to produce better results in cerstations As you make your lectrode selection matchit to the position as well as the job.

Electrode classification

The most commonly used electrodes in the structures career field are **One** E 6011, E 6013, and the E7018. Before you can select **dece** rode, you need to know how it's classified the Air Force uses two common classification methods. The first is the American Welding Society (AWS)

classification number and color code method (the industry standard). The other is the military specification method. Let's take a closer look at these classifion methods.

American Welding Society classification

The AWS classifies electrodes with letters, numbers, or a combination of there and the electrode along with the electrode along with the electrode along with the electrode acolor coating. The AWS number code can have either for the five digits. The (E) at the beginning signifies electric weld in the recommended welding position and current use.

Four-digit number electrodes

Most mild steel and low alloy electrodes use a code with a **digut** number, such as -16010, E-7014, and ± 7018 . The four digit electrode number, -16010, is broken down as follows:

| Breakdown of 4 Digit Electrode Number: E -6010 | | | | |
|--|--------------------------------------|--|--|--|
| Digits | Meaning | | | |
| 1 st & 2 nd | Tensile strength in thousands of psi | | | |
| 3 rd | Recommended welding position. | | | |
| 4 th | Special characteristics. | | | |

As the chart shows, always read the first two digits toget filterey designate tensile strength in thousands of pounds per square inch (psi). The E electrode, for instance, has a 60,060-strength; whereas 2014 has 70,000 si strength. The third digit (the 1 in E-6010) specifies the position (or positions) in which you can use the electrode most satisfactorily. This d2gibr 3, indicates the recommended welding position as follows:

| Digits Indicating Recommended Welding Position | | | |
|--|--------------------------------|--|--|
| Digit | Recommended We Iding Position | | |
| 1 | All positions. | | |
| 2 | Flat and horizontal positions. | | |
| 3 | Flat position only. | | |

The fourth digit can be from 0 through 8. It identifies special characteristics such as the electrode coating, weld quality, arc required, weld penetration amound pawer supply needed. The following tableshows an example of what the fourth represents:

| What the Electrode's Fourth Digit Represents | | | | | |
|--|---|--------|--|--|--|
| Number | Meaning | Number | Meaning | | |
| 0 | DC reverse polarity when the third digit is 1 | 4 | AC or DC reverse polarity or straight polarity | | |
| 0 | AC or DC when the third digit is 2 or 3 | 5 | DC reverse polarity low-hydrogen | | |
| 1 | AC or DC reverse polarity | 6 | AC or DC reverse polarity low-hydrogen | | |
| 2 | AC or DC straight polarity | 7 | AC or DC (iron powder plus low hydrogen sodium covering) reverse polarity or straight polarity | | |
| 3 | AC or DC reverse polarity | 8 | AC or DC (iron powder plus low hydrogen sodium covering) reverse polarity | | |

Five-digit numberelectrodes

We read electrodes with five igit numbers slightly different than we totour digit numbers The difference is that for these you read the first three digits toget if er example, E10010 designates an electrode having a 100,000 psi tensile strength. The fourth digit specifies the welding position (or positions). The fifth digit indicates specificateristics. Here is a breakdown for the ting it number E-10010.

| Breakdown of Five Digit Number: E -10010 | | | | |
|---|---|--|--|--|
| Digits Indication | | | | |
| 1 st , 2 nd , & 3 rd | st , 2 nd , & 3 rd Tensile strength in thousands of psi. | | | |
| 4 th | th Recommended position or positions. | | | |
| 5 th | Current type. | | | |

Filler groupclassification

The AWS uses a filler group classification to identify electrodes by filler material. The category divides electrodes into groups that share certain filler mat**ena**Itable below explains the filler group classifications.

| Filler Groups | | | | | | |
|---------------|--|--|--|--|--|--|
| Class | Explanation | | | | | |
| F–1 | Alloy steel electrodes are used in welding chrome molybdenum and chrome nickel molybdenum steels when heat treatment is required. | | | | | |
| | The corresponding AWS electrode specifications would be E–7020 or E–10020. These electrodes are generally used with straight polarity, but may also be used with AC. | | | | | |
| | Only the smaller diameter electrodes, $\frac{5}{64}$ - and $\frac{3}{32}$ - inch, are adaptable to all positions. | | | | | |
| | The larger diameter electrodes are generally used for horizontal fillets and flat work where deep penetration is not required. | | | | | |
| F–2 | Corresponds to the AWS electrodes whose last two digits are 12 or 13, such as E–6012 or E–6013. | | | | | |
| F–3 | Corresponds to the AWS electrodes whose last two digits are 10 or 11, such as E–6010 or E–6011. | | | | | |
| | These electrodes are used with DC reverse polarity, except when specified as an AC electrode. | | | | | |
| | Penetration is deep, which is normally preferred for good fit-up and vertical or overhead welding. | | | | | |
| | These electrodes are not used when heat treatment is required. | | | | | |
| F–4 | Companion electrodes to the class C electrodes under the same specification and are used when deeper penetration is required. | | | | | |
| | They're used to weld chrome molybdenum (4135 and 41400) and chrome nickel molybdenum (8735 and 8740) steels (with preheat of the parts to 400 to 500 °F). The corresponding AWS electrode specifications would be E–7030 or E–10030. | | | | | |
| | These electrodes are generally used with reverse polarity, but they may also be used with AC. They're all-position electrodes. | | | | | |

American Welding Society colocode

This code uses three markings: (1) primary, (2) secondary, and (3) group. (See the electrode color identification data chart belowT)he primary and secondary color indicates the electrode composition, while the color group indicates the curty end. The electrode's primary color is on the electrode's top or on its grip end. The electrode's secondary color is located on the grip end midway between the electrode's end and its flux coating.

The group color is located on the flux coating **justice** with electrode's grip end. We show the color coding for some common electrodes in the following table.

| ELECTRODE COLOR IDENTIFICATION DATA | | | | | |
|-------------------------------------|--------|------------|--------------------|---------|-----------|
| Mild Steel | | | | | |
| Coating Color | End | Spot | Group | Special | AWS Class |
| White | | | | | E–6010 |
| Brick Red | | | | | E–6010 |
| Tan | | White | | | E-6012 |
| Gray | | White | | | E-6012 |
| White | | Blue | | | E–6011 |
| Dark Tan | | Brown | | Green | E-6013 |
| Gray Brown | Black | Brown | | | E-7014 |
| | | | | | E-6014 |
| Tan | | White | | Green | E-6012 |
| Brown | | Blue | | | E–6011 |
| Dark Gray | Black | Yellow | | | E-7024 |
| | | | | | E-6024 |
| Red Brown | | Silver | | | E-6027 |
| Gray | Black | Yellow | | Green | E-7024 |
| | | | | | E-6024 |
| Gray | Black | Orange | Green | | E-7018 |
| | | | | | E–6018 |
| Gray Brown | Black | Black | | | E-7028 |
| | | | | | E-6028 |
| | | Low Alloy, | High Tensile Steel | | |
| Pink | Blue | White | | | E-7010-A1 |
| Pink | Blue | | | Green | E–7010–G |
| Dark Red | Blue | Yellow | Silver | | E-7020-A1 |
| Gray | | | | 9018 | E–9018–G |
| Gray | | | | 11018 | E–11018–G |
| Stainless Steel | | | | | |
| Pale Green | Yellow | | Black | 308–15 | E-308-15 |
| Gray | Yellow | | Yellow | 308–16 | E-308-16 |
| Gray | Brown | | Yellow | 308L-16 | E-308L-16 |

| ELECTRODE COLOR IDENTIFICATION DATA | | | | | |
|-------------------------------------|--------|--------|--------------|---------|-----------|
| | | Ν | /ild Steel | | |
| Pale Green | Red | | Black | 310–15 | E-310-15 |
| Gray | Red | | Yellow | 310–16 | E-310-16 |
| Gray | Brown | White | Yellow | 316L–16 | E-316L-16 |
| Pale Green | Yellow | Green | Black | 318–15 | E-318-15 |
| Pale Green | Yellow | Blue | Black | 347–15 | E-347-15 |
| Gray | Yellow | Blue | Yellow | 347–16 | E-347-16 |
| | | Bronze | e & Aluminum | | |
| Peach | Yellow | Blue | Blue | | E-CuSn-C |
| Peach | | | | | AI-43 |
| Cast Iron | | | | | |
| Light Tan | Orange | | | | Est |
| Black | Orange | Blue | White | | Eni |

As you can see in the table of all electrodes have all three markings. Also, some electrodes have a special marking at their center. This marking, which is usually three spots, is a manufacturer's trademarkIf you want more information on AWS, check their worldwide website http://www.aws.org/w/a

Military specifications

Military specifications use a code such as MEL15599, type 6010, C1 1 to identify electrothers specific welding tasks. Figure 6-shows a sample page taken from Technical Order (TO) 34W3, section D, Operator Manual Welding Theory and Application. It shows some military specifications codes and explains what you can weld with the electrode. It also references the military specification with federal stock number to make it easy to order electrodes through the federal supply system. You can get more details on military specifications by reviewing TO 34W54

Figure 1-6. Electrode specifications.

Electrode coatings

When heated to high temperat**stee**Ireadily combines with the oxygen and nitrogen in the air surrounding the arc. This results in oxide and nitride formation, cabsittleness in the weldTo control this, an electrode's wire core is coated with a substance that prevents the oxides and nitrides from forming during the welding process. The coatings on metal arc welding electrodes range from fluxing agents, such as the fluxes used in certain oxyacetylene welding applications, to chemical compositions for specific arc welding applications. These coatings produce a gas that excludes air from the arc and forms a slag, which acts as a blanket on the pool of moltemetperifesit. These coatings provide easier arc starting, stabilizenth better, reduce splatter, and permit better penetrationThe flux gases protect the weld from outside atmospheric contaminants.

The flux forms a slag over the deposited metalich further protects the weld until the metal cools sufficiently sothat it is no longer affected by outside atmospheric contamination. The slag also slows the cooling rate of the deposited metalerebypermitting a more ductile weld to form.

Metal arc electrodes may be classified tables of the set of the se

| Metal Arc Electrode Classifications | | | |
|-------------------------------------|---|--|--|
| Туре | Description | | |
| Light-coated electrodes | Light-coated electrodes are made from wire. | | |
| | The material used to make the wire has a definite composition that is designed to maintain quality throughout. The wire surface has a thin coating that is applied by washing, dipping, or drawing. These coatings are chiefly of iron oxide and titanium dioxide. | | |
| | The use of light-coated electrodes is very limited because these electrodes are very difficult to weld with and they produce brittle welds with low strength. | | |
| | Practically all welding is done with heavy-coated or shielded metal arc electrodes. | | |
| Heavy-coated electrodes | Like the light-coated electrodes, shielded metal arc or heavy-coated electrodes are also made from wire. The material used to make the wire has a definite composition, which is designed to maintain quality throughout. The wire is then wrapped with a heavy coating instead of having the coating applied. | | |
| | The heavy coatings are divided into three classifications: | | |
| | x Cellulose. | | |
| | x Mineral. | | |
| | x Cellulose and mineral (mixed together in various amounts). | | |
| | The cellulose coatings are made from wood pulp, sawdust, cotton, or various compositions obtained from the manufacture of rayon and are used on reverse polarity electrodes. | | |
| | The mineral coatings are made of metallic oxides or silicates and are used on straight polarity electrodes. | | |

Electrode characteristics

The electrode type**s**tat you use have their own special characteristics, which either help or hinder your welding job. You must know these characteristics in order to select the correct electrode for a job. The table below covers four of the five electrodes and their chaistictenthe more detailed discussion of the heavgoated electrodes follows the table.

| Electrode Types and Characteristics | | |
|-------------------------------------|---|--|
| Туре | Characteristics | |
| Fast-freeze electrodes | E 6010 and E 6011 electrodes both produce a snappy, deep penetrating arc and fast- freezing deposits. They have little slag and produce flat beads. | |
| | Fast-freeze electrodes are used for all types of all-position welding. | |
| Fill-freeze electrodes | E 6012, E 6013, E 7014, E 7016, and E 7018 electrodes all produce a moderately forceful arc with a deposit rate between the fast-freeze and fast-fill electrodes. These electrodes provide complete slag coverage and weld beads with distinct, even ripples. | |
| | Fill-freeze electrodes are general purpose electrodes and can be used in all positions. | |
| Fast-fill electrodes | t-fill E 6020, E 6027, E 7024, and E 7028 electrodes all produce a soft arc and have a deposit rate. These electrodes all have a heavy slag and produce exceptionally smoot weld beads. | |
| | Fast-fill electrodes are generally used for production welding. | |
| Light-coated electrodes | These electrodes have a light protective coating, but usually do not produce slag. The electrodes that do produce slag produce only a very thin layer, which does not give very much protection to the weld. | |

Heavy-coated electodes

The heavycoated electrodes are the ones most commonly used because their coating improves the weld's physical properties. The coatings also control arc stability and increase welding speed and improve welding control in the vertical and overhead tions This control is produced because the heavy coated electrode (filler metal rod) actually burns (melts) about the inside of the coating. Figure 1–7shows how heavy coated electrodes provide shielding.

The cellulosecoated electrode depends on a gaseous shielding, or a covering,textion. The mineral-coated electrode uses the slag as a shield. The slag is mainly silixide dind aluminum oxide, which forms a blanket over the weld deposit to reduce the molten metal's cooling rate. Some common heavycoated electrode'characteristics in the AWS class are described in the following paragraphs.

E-6010 electrode

The E-6010electrode is a widely used shielded metal arc welding (SMAW) electrode, mainly because it can be used in all positions: Weld deposit has physical properties as good as other electrodes and is considered fatheze. We sometimes refer to as the cellulose type because the coating contains a considerable amount of cellulose, such as wood flour or paper flour, combined with other ingredients which are added to get certain qualities, such as slag volume and fluidity. The arc heat causes the coating to burn and generate gasses in large volumes, which effectively shield the molten metal from ait/huspreventing harmful oxides and nitrides from forming. This electrode has good penetration, as well as quick weld metal slag cooling, which makes it ideal for vertical and overhead workThe E6010 electrode is designed primarily for welding mild and low alloy steel. Use it where there is an absolutely goodufit due to its deep penetrating arc characteristics.

E-6011 electrode

The E-6011 is a fastfreeze tectrode and is designed to perform the same work with alternating current that the E6010 performs on reverse polarity direct current. It is apostlition electrode with somewhat more slag than the E6010. The coating contains gas, sharging ingredients, and other material for sustaining the arc when both current and voltage are alternating from maximum positive values through zero to maximum negative values. The welding current range for various electrodes that can be used satisfactorily is naveo than in the case of E010, which means that the welding current controls must be more exact.

E-6012 electrode

The E-6012 electrode is used with DC straight polarity but does very well with AC, as is the case with most straight polarity electrodes. It is an padisition electrode that is used for fast welding and produces less splatter than most other types. The penetration is not deep; consequent(9),12 he E electrode has many advantages on jobs where the fixt poor or where lightgauge materials used. Its tendency to burn through the materialless than that of the E6010 or E-6011. The bead profile is not as flat as that of the E6010, but it is often desirable for producing horizontal fillets with good weld appearance.

E-6013 electrode

The E-6013fill -freeze electrode, operating on AC, serves the same purpose as the Endotre Experimentary on DC straight polarity. Although it is satisfactory with DC straight polarity, its original intent was to pair it with E-6011, as the E012 pairs with the E010. The E-6013 isan all position electrode used most effective for welding lightweight tubular assemblies a sheet metaThe coating contains a high percentage of material for stabilizing and maintaining avaintaining the arc and slag removal are easier, spatter loss is low, and the bead is flatter and smoother with shallower penetration that hat usually obtained with the E6012.

E-7018electrode

The E-7018 fill-freeze electrodis a low-hydrogen, all position high speed, fast depositionelectrode designed to pass the most severary xequirements when applied in all welding positions, using either AC or DC reverse polarity s puddle fluidity permits gases to escape when the lowest currents are used for out-position welding. The penetration and deposition rate are both typically moderate.

Conserving and storingelectrodes

You must be concerned with using mauch of an electroches possible prevent being wasteful to not discard electrodes until they are down to 1 ½ itro 2 eslong. Ensure you always storle etrodes in a dry place Keep mild steel and iron powder electrodes at a normal room temperature and 50 percentmaximum relative humidity. Lowlydrogen electrodes are especially vulnerable to moisture after you remove them from their container, store them in a ding oven at a temperature between 250 and 400 F.

NOTE: Do not bump, bend, or step on electrodes. This **sabe**coating to weaken and fall off.

604. SMAW machine setup and general safety procedures

There are maynways to set up arc welding equipment. Your goal is to always do it safely. Let's take a look at ways that you can set up for arc welding and always work safely.

Setup

The common setup factors include:

- x Welding task.
- x Welding machine type.
- x Electrode skection.
- x Current selection.
- x Safety procedures.

Before welding, consider all five factors; they're dependent on each other and enable you to correctly set up and produce a quality weld. The welding task that you must perform will influence your electrode selection. This affects the current and voltage and helps determine the welding machine that you use. If your work requires deep penetration and is on thick plate, you need a different electrode thanthat requiredor a shallow penetration weld. At the same time, the proper welding current and polarity selection depends on the electrode, plate thickness, and the position of weld. When welding in the flat position with an electrode of the same size, you can use higher current than when you weld in vertical or overhead positions. Since these relationship factors affect each other, we can only use generalized data, such as we show in figure 1–8, to aid us in setting up for arc welding. Consequently, you may set up for arc welding in a slightly different way than others because of individual preferences. However, there is one factor that we all must always be aware of an **CialFevr**Y!

Safety precautions

Many accidents are caused by defective equipment, not following safety precautions, and by not knowing safety rules or practices. In an emergency not covered by the rules listed here, follow your supervisor's instructions, shop safety guides, and any *AireFO*ccupational Safety and Health (AFOSH) safety standards.

Electrical shock hazards

The AC and DC open circuit voltages are low in comparison with voltages used for lighting circuits and motordriven shop tools and, normally, cause neither injury norkshowever, these voltages can cause severe shock when your body or clothing is wet. You must always consider this every time you weld, particularly in hot weather when you are sweating sequently, always check the welding equipment to make certain that the electrode connections and the insulation on the electrode holders and cables are in good condition. Keep your hands and body insulated from the work, metal electrode, and holder. Avoid standing on wet floors or coming in contact with grounting surveys.

Check your welding cables to make sure their rated electrical current capacity is capable of handling your welding task. Excessive current creatent in the cables, which damages the insulation and can lead to severe electric shocks or fines pect the cables periodically for loose connections, defects due to wear, or other damage. Defective or loose cables can cause a fire or an electrical shock. Replace defective electrode holders and always tighten connections to the holder.

Protection from toxic fumes

When welding on metals that are coated with or contain materials that emit toxic fumes, you must protect yourself from their effects. Some materials that emit toxic fumes are paint and galvanizing or plating material. Always comply with alafety precautions concerning toxic fumes. If you are unsure, check your shop's welding safety procedures or ask your supervisor before you do any welding.

A good way to reduce or eliminate toxic fumes is to clean the toxic material from the metal's surface before you begin welding. If you cannot remove the toxic material, some common ways to protect yourself are by using local exhaust or dilution ventilation or by wearing asupiplied respirator.

Dilution ventilation

Dilution ventilation is nothe most effective for controlling fumes. It works by diluting the contaminated air in the work area by circulating it with cleaner air. You can do this by opening windows or using fans to move the air around. If fans move air around within the work area, there must be some fresh outside air brought in or the air must be filtered. If the air in the workspace is moved around without introducing any outside or filtered air, the entire workspace eventually becom**g** filled with toxic fumes.

Local exhaust ventilation

Local exhaust ventilation is the most effective method for controlling toxic furthes method is designed to collect air contaminants close to the welding operation and remove them from the workspace. There are many local exhaust systems available ylinclude the movable exhaust collector, the cross araft table, and the downdraft table.

Whichever exhaust systeyou use, there is one rule to always keep in mANdOID BREATHING THE FUME PLUME! The fume plume is the cloud of contaminated air that rises from the arc and molten weld pool. It contains such toxic gases as carbon monoxide, phosgene, and nitrogen oxides. To limit your exposure, position the work, your head, and the exhaust equipment in such a way that the fume plume stays clear from the air you breatthe aust effectiveness tests have shown that fume removal is more effective if the airflow is across the welder's face, instead of from behind the welder.

Eyes

Safety precautions that you take to protect your eyes are critical when aircgweidensider the helmet your most important safety equipment it are safety as shaded lens to filter out the harmful light produced during arc welding the following chart shows the different shade numbers and the welding amperage range in which are used.

| Lens Shade N umber | Amperage Range |
|--------------------|--------------------|
| 10 | 75 to 200 amperes |
| 12 | 200 to 400 amperes |
| 14 | Over 400 amperes |

During the welding process, small particles of metal fly upward from the work and may lodge on the lens To protect your eyes, always insert a clear plastic lens inside the welding helmet.

NOTE: Since you must have clear vision at all times during welding, always replace the cover lens wheaccumulated spatter interferent your vision.

Since the arc rays are also harmful to the eyes of anyone in the area, you must protect people from looking at the arc by welding in a booth or behind a welding curtain. When you must do welding in the open, warn persons in the area about the arc welding hazedisically mention the possible eye damage caused by looking directly at the arc. If possible, people should stay out of the welding area. If they must stain the area, we recommend that they protect their eyes with tinted safety goggles or shields.

Because the welding helmet does not provide **tota** ection, wear goggles or safety glasses at all times when welding. While removing slag, tiny particles are often deflected upward. Without proper eye protection, these particles may cause a serious eye injury.

Clothing

Welding permit

When you weld outside of the welding shop area, you must get written permission using an AF Form 592, USAF Welding, Cutting, and Brazing Per**W** use this form to ensure that adequate precautions for fire and pensal safety have been taken.

The AF Form 592 is usually issued by the fire protection flight's technical service element (base fire department). It is your responsibility to make sure you have this permit in your possession before you start any sparkroducing operations. This form also notifies the fire department that you'll be performing a hazardous operation and that the possibility of fire is greater where you are working.

When you are welding, you must have an additional persone as a fire stch. The fire watch duty person standby with a fire extinguisher handy. This individuation of the store of the mediately put out a fire if one occurs. This personmust also standby and observe the weld area to make sure that it cools to the point that fire has no chance to start. The fire watch standing is based on the welding type and on the material subject to combustion near the weld.

Before welding or cutting on drums, tanks, or other containers that previously stored flammable materials, puge themand testhem for flammable material and gas presence. Refer to AFOSH Standard 91–5, Welding, Cutting, and Braziliog specific purging and testing procedures.

Self-Test Questions

After you complete these questions, you may check your answers betend of the unit.

603. Selecting SMAW electrodes

- 1. How does the American Welding Society classify electrodes?
- 2. In a four-digit electrode number, what does the third number ate?
- 3. What do the first three numbers a five-digit electrode number dicate?
- 4. Electrode E-7020 belong to which filler group class?
- 5. Using the Electrode Color Identification Data chart, indicate the color costingon each of the following electrodes:

a. E–7018.

b. E–6012.

c. E–6028.

d. E–11018G.

6. How do electrode coatings prevent brittleness in the weld?

7. Associate the following terms with lightwated or heavy coated electrodes by writing the corresponding terrby eachone.

_____a. Cellulosecoated.

<u>____b</u>. Improves welding control in the vertical position.

_____<u>c</u>. E–6010.

<u>d</u>. Controlled gaseous shield.

8. Which electrodes have little slag, produce flat beads, and are used for all typessoftial welding?

604. SMAW machine setup and general safety procedes

- 1. List the five factors you must consider when setting up for arc welding.
- 2. When are you particularly susceptible to severe shock from AC and Dcippein voltages?
- 3. What ventilation rule mustou keep in mind when welding?
- 4. To provide eye care when welding, what feature of your helmet do you check?
- 5. How can you effectively protect your hands when welding?
- 6. What form must youbtain before welding, cutting, or brazing outside of the shop area?

1-3. SMAW Procedures

Sometimes you need to week metal component to a flat metal surface, but the area where they join does not allow using a single bead weld to join them together. In this situation, one approach is to build up the flat surface to allownaking a good weld join The lessons in this ection explain what you need to do to accomplish that.

605. Bead welding and padding flat surfaces

You can correct minor welding fit up challenges when flat surfaces are inv**th**ateds, if you know how to build them up. In this lesson, we discuss how you can do that by running welding beads on flat surfaces through a process called padeling re commonly known as surfacing

Beadwelding

Your first requirement for bead welding is to make sure that you have clean working subjaces dirt, and other foreign matter on the metal to be welded can cause welding defects such as lack of fusion, porosity, or slag inclusions. Next, you must select the proper electrode for the welding task. When welding, we recommenyou tilt the electrode 15 to 30° in the welding travel directionand 90° transverse (work angles shown in figure 1–9. Tilting the electrode gives you a clearer crater view and helps to control the molten slag. The proper arc length or gap between the end of the electrode and the plateoshid be approximately equal to the electrode diameter. However, when striking the arc (fig. 1–10) and starting the weld, hold a long arc momentarily to preheat the base metal and permit fusion at the beginning of the weld. At the end of the weld, shortence thength to prevent forming a crater or depression. If the current, polarity, and length of the arc are correct, the metal melts forring a pool of molten metal at the point where the arc strikes the plate. Molten metal is forced out of the pool by there blast. A small depression forms in the base metal and the molten metal piles up around it; this arc craiseshown in figure 1-11. The crater size and depth depend on the current setting, travel speed, electrode diameter, and arc Tengtonaer depth allows you to observe and control the penetration or depth to which thenelits into the base metalhe penetration depth should not be less tharinch.

Figure 1–9. Electrode angle for wel ding beads.

The travel speed depends on the bead desired, current value, and electrode sizeh cover speed by observing the crater's trailing edge. By closely watching the crater and its trailing edge, you can determine the penetration and reinforcement width and height. Since the travel speed and current setting are related factors in determing the weld quality, you must learn to recognize the weld appearance resulting if either factor is wrong. Figure 21shows the results of using various welding speeds and current values.

Figure 1–12. Arc welding results.

Padding

Padding or surfacin(building up) is a welding operation we use to increase metal thickness (T). You can use ito build up worn parts to their original dimensions or to build up a flat surface. Padding large parts isgenerally doe in stringer bead layers welded at right angles to each (bitg) et –13. Padding small parts issually done in a thin metal layer or layers. You can produce it by weaving your electrode to produce a wide and thin cross section bead.

Electrode selection padding

Use a heavycoated electrod de dense, ductile, hard, or corrosionersistant properties are required in the deposited metal. There are many factors for yourtsider for electrode selection. Perhaps the most important is the material size, example, the mass of artich diameter shaft would permit you to use a larger electrode with higher current values than you would incla diameter shaft.

Welding procedures for padding

In padding **i** is essential to merge (overlap) successive and adjacent stringer beads. When laying each pass, hold the electrode so that it fuses into the base metal and adjacent beads at the **signe** time (1–14) When the beads are no**erg**ed in this manner, defects show up as voids and slag inclusions (fig. 1–15). You usually have a choice of running the beads either parallel or at right angles to the longest work dimension. You normally weld parallel to the work because it permits a longer time interval before the concentrated arc heat comes back to the starting point. This procedure minimizes welding stresses by giving the weld area more time to dissipate arc heat.

Figure 1-14. Excellent p adding example.

Figure 1–15. Poor padding example.

We usually encirclente part edges being padded with a welding bead (fig.) **1to 116** ake welding stringer beads easider also reduces crater cracks any metheating caused by the work edges being melted away.

Figure 1–16. Padding, first step.

To do the padding, hold a long arc momentarily in starting each pass. Fill all craters and carefully avoid overheting the edges. When you use coated electrodes, you must clean every bead. You can use a chipping harmer and wire brush to cleamer When one bead layer is deposited, turn the plate so that the next layer is deposited at a right angle to the pseujoer. Quench the plate often enough to keep it from becoming too hottilt the electrode 5° to 15° in the welding direction of travel and 90° transverse (work angle). However, in order to obtain a clearer view of the molten puddle, crater, and arctilt the electrode 15° to 30° in the welding travel direction and 90° transverse (work angle)

NOTE: For multiple pass welds eachead deposited must overlap each preceding bead by 1/4 of the bead width all welding types and positions

606. Flat positionwelding

In this lesson, we will discuss flat welding proceduides flat position is usually the best position for preparing and welding into because it gives you good control over gravity and other conditions. Your first concern is selecting the best position to use. The selection is sometimes dictated by welding location, blue prints, or other written specifications very often a choice is possible. Of course, the best joint is the most economical one that will stand up under intended usage.

Joint consideration

In making the selection, you must consider three main factors:

- x The load and unload characteristics under compression, tension, bending, fatigue, impact stress, or any combination of them.
- x The manner in which the load is applied. It is describes steady, variable, or sudden.
- x The joint preparation cost and the actual welding.

Other considerations are warping effects, welding ease, and joint smoothness. In this lesson, we discuss the four most common joints: (1) lap, (2) tee, (3) butt, ared (). We also see how each one is affected by the three factors stated above.

Lap joint

The lap joint has two plates where one overlaps the other. You complete the joint by welding the edge of one plate to the surface of the other plate. The lap joint is not required. Its preparation and welding ease makes it an ideal joint for structural work.

The two most common arc welded lap joints are the single fillet lap joint (fig. 1–17) and the double fillet lap joint (fig. 1–18). Thesingle fillet lap joint used more frequently, since it requires no preparation to the plate edges. If the loading is not too severe, this joint is suitable for welding all plates; but if fatigue or impact loads are encountered, co**atechts**tress can occur at the welded plate edges. Under tension, the plates will pull out of line, thus subjecting the root to bending and possible joint failure. Theoublefillet lap joint is more suitable for these and more severe loading conditions tharcan be met by the singfielet lap joint. A lap joint isnot desirable under fatigue or impact conditions, but it is capable of developing high efficiency under shear and tension stresses.

Figure 1–17. Sing le-fillet lap joint, welded (flat position).



Tee joint

A tee joint is formed when the edge of one plate is joined approximately perpendichteafacet of another plate (two pieces of metal at a 90° angleforming this you use a fillet weld theat approximately triangular in a cross section. A tee joint is only welded on one side and sholed not used if it is subjected to heavy sustefrom the opposite direction of the weld. If you must use a tee joint, you can weld both sides to make the joint more stress resistant.

A square edge or plain tee joint is used for joining metals \mathfrak{V}_{Pe} -tionch thick in which no edge preparation require(fig. 1–19, view A). If extra strength is desired, you can make the fillet weld wider. When thicker metal is involved, up \mathfrak{V}_{Pe} inch, use a single bevel, as shown in view B of figure 1–19, and weld the joint from one side. A doubtevel tee joint is such on steel over-trach thick, with the joint welded from both sides (fig. 1–19, view C).
Lap joint welding procedure

The amount of overlap depends on the thickness of the plates and the strength required of the welded pieces. Standard overlap is five times the thickness (5T) of the thinnest piece or no lessthan When you are joining metal greater than thick, the plate edges should overlap maximately three to four times the metal thickness e metal should be tack welded as often as required to hold it in proper alignment. The number of tack welds used is optional. If you must force the fit up by means of fit-up dogs(fig. 1–20, shot welds are preferred to tack welds. Lap joints subject to heavy bending stresses should be welded on both sides (double lap).

Figure 1 –20. Using fit up dogs (flat position).

Hold the electrode at a 45 inglefrom vertical, and tilt the top of the electrode to a 30° angle in the weld travel direction. When you start the weld hold a long arc momentarily to ensure adequate penetration. Thick metal plates conduct heat away more quickly than light metal sheets; therefore, the welding travel speed should be slower for the thick plates. For the same reason, higher current values may be used on thick plates. Direct the arc so that penetration to both the upper and lower plates. When one pass or bead not provide the proper weld size, make a multiples fillet weld. In making lap joints on plates of a different thickness, hold the electrode at a 20° to 30° angle from vertical. Take care not to overheat or undercut the thinner plate edge.

Multiple pass fillet welding is recommended on heavy plateins thick and over and when an exceptionally strong lap joint is required. Multiple pass consists of two or more layers of bead overlapping the previous bead. Deposit the root pass using a whipping mut a 30° travel angle, clean the weld, and then proceed to welding the second pass while holding the electrode at a 30° angle from vertical, and tilt the top of the electrode to a 15° angle in the weld travel direction (fig. 1-21); weave the electrode, pausing for an instant at the toe of the weave to deposit extra metal. Make sure to maintain a consistent bead width along the plate.

Tee joint welding procedures

A tee joint may be welded in the flat, horizontal, vertical, or overhead positions. Make the fillet weld in a tee joint by depositing multiple stringer bead pa**(fige**s1–22), or by weaving the electrode to form a wide bea**(**fig. 1–23). The electrode should be held at a 45° angle to both plates and at a 30° angle to the welding travel directi**(**fig. 1–24) Stringer beads are generally preferred for fillet welds of maximum strength and ductility, since each successive bead layer tends to refine it welds grain structure layerUse a slight whipping motion. The multiple ss flat fillet welds first three passes are shown in figure 1–22. After depositing the root bead, remove all the slag. Proceed by holding the electrode at a work angle of 70° and a travel angle of 30°. Deposit the first intermediate weld pass to partly cover the root bead. Remove the slag completely. Hold the electrode at a work angle of 30° and travel angle of 30°. Deposit the second intermediate weld pass to partly cover the root bead and partly cover the first pass. Remove the slag completely. If more weld material is required, make additional passes using the different bead configurations from the first three passes. A cover pass can be added to a multipass fillet Tjoint, if required, by weaving the electrode.

Figure 1 –22. Multiple welding bead passes (flat position).

Figure 1 –23. Electrode weave motion (flat position).

Figure 1 –24. Electrode angle for a tee joint (flat position).

Figure 1-25 shows several weave motions for depositing a weave bead (overlay) to cover the stringer beads of a multipleass flat fillet weld. A weave this a slight pause at each apex angle is easy for you to learn and it is a good one for beginners to start(traithview of fig 1-25). The other views show more advanced motions, including each starting point.

Figure 1 –25. Weave motions (flat position).

Lap joint welding requirements

When the lap weld (figs. 11-7 and 1-1-8) is properly made, the upper leg equals the metal thickness. The lower leg equals 1¹/₂ times the metal thickness, while the throat thickness should equal the base metal thickness.

The weld specifications for metals of unequal thickness are based on the thinner sheet thickness. Penetration for metals -inch thick should be/₁₆-inch. For thinner gauges, the penetration should be 30 to 50 percent of the metal thickness. The face on lap joints should be slightly convex in shape, permitting a smooth stress line flow through the weld face. Any abrupt change in face shape, such as undercutting or overlapping at the edge or toe of the weld, will cause stress point concentration, thus reducing the weld strength. Figure 1–26 shows proper and improper stress distribution. In manycases, the welded joint strength is affected by the weld location in relation to the parts joined. Other factors being equal, welds that have their linear dimensions transverse to the stress lines are approximately 30 percent stronger than welds with **linear** ensions parallel to the stress lines. Figure 1-27, B illustrates this condition. In welds that have their linear dimensions approximately parallel to the force line, the stress on the weld is in the shear. The shear, in this case, is greater at the weld ends than in the middle. In certain cases, to get greater resistance to the weld tearing action, it is advisable to hook the bead around the jo(fings 1-28).

Figure 1 –27. Weld location in relation to t he line of stress (flat position) .

Figure 1 –28. Welding around corners to resist tearing (flat position).

Tee joint welding requirements

The requirements for tee joints are expressed by their nomen(**fag**ure-29) Regardless of whether stringer or weave beads are used in making a tee joint, the weld size remains the same. The term "leg" is used to measure a tee joint fillet weld. A "leg" is the distance from the root of the joint to the toe of the fillet weld. You can compute the size by using an isosceles triamed the weld cross section, 1½, Thown by the dashed lines in fig. 1–30 he leg lengths and the thickness of the throat are based on the base metal thickness, also shown in **fig0re** 1

Figure 1 –30. Tee joint specifications (flat position).

When welding tee joints, undercutting is a frequent defect that occurs along the toe of the upper leg. This defect is a groove melted in the base metal adjoining the toe of the shoeled on the right in fig. 1–31) A welding current that is too high and improper electrode angle is the usual cause Correcting the current setting and changing the electrode angle and manipulating the electrode to wash molten metal up to the toe of the vertical leg usually corrects this defect. Good and bad tee joint characteristics are shown in figure 31.

Figure 1 – 31. Good and bad tee- joint characteristics.

Butt joints

A butt joint is used to join two plates having surfaces in approximately the same **Stare** al edge preparation methods can be used to make butt joint welds **flattpe**sition. The termgroove describes edge preparation methods that you can use. We cover the basic types shown-i62 tigure 1

Butt joint preparation

There are many factors that can influence the way that you prepare a butt joint for welding. The factors for you to consider include plate thickness, groove selection, and preparation equipment. After considering these factors, prepare joint edges by flame cutting, shearing, flame grooving, machining, chipping, or grinding

| Butt Joint Preparation | | |
|---|--|--|
| Metal | Preparation | |
| Sheets up to ¹ / ₈ -inch thick | Preparing metal sheets up to ¹ /8-inch thick requires that you make sure that plate edges to be welded are square and clean. | |
| | You do not have to bevel either plate edge prior to welding. | |
| | In fact, the term used to identify this butt joint connection is the square groove (fig. 1–32, view A). | |
| Plates ¹ / ₈ - to ¹ / ₄ -inch thick | Preparing metal plates $\frac{1}{8}$ inch to $\frac{1}{4}$ inch can be done in many ways. We cover three that you can make. | |
| | The easiest is the square groove provided that you weld both plate sides (top and bottom). | |
| | If you can only weld on one side, use the single groove or the single "V" groove. The single groove has one plate that has a 30° bevel (fig. 1–32, view B). | |
| | The single "V" groove has both plates with a 30° bevel (fig. 1–32, view D). Preparing a bevel increases the fusion area and strength in the weld. | |
| Plates ¼-inch thick and thicker | Plates ¼- inch and thicker require you to groove (bevel) one or both plate sides. | |
| | There are various grooves that you can use; we'll look at two, the single "V" groove and the double "V" groove. The included angle can range from 60° to 90°. This means that each plate has a 30° to 45° bevel. The bevel that you make varies with the plate thickness. Generally, the thicker the plate, the greater the bevel. | |
| | To make the single "V" groove, you bevel each plate on one side (fig. 1–32, view D). | |
| | To make the double "V" groove you bevel each plate on both sides (fig. 1–32, view E). | |

NOTE: Butt joints prepared from both sides and then welded are usually stronger, produce less distortion, and ensure better welletal qualities than joints prepared from one side only.

Butt joint weld requirements

The butt joint welding requirements include metal thickness and edge preparation. For example, metal sheets that arte-inch or less in thickness usually require that you weld the two metal sheets together on one side. On plate that 'is-inch or geater in thickness, you may be required to weld on one or both plate sides. Another factor is the groove degree bevel (angle) that you use on the plate edges to prepare them for welding. The welds shown in figures 1–33 and 1–34 illustrate the specificatio requirements for butt joints on low carbon steel plates.

Figure 1 –33. Butt joint specifications (sheets).

Figure 1 –34. Butt joint specifications (plates).

The fusion zone width for thick plates is governed by the way that you prepare the Vibient you bevel the edges, the weld should be approximately children wider than the width of the included bevel. The fusion depth into the beveled joint edges should be at least. A ¹/₈-inch height reinforcement is usually sufficient for thick plate. The penetration for butt welds must be 100 percent, regardless of the plate thickness double deged penetration; you get 50 percent penetration from each side to produce the required full base metal penetration. In general, butt joints prepared from both sides permit easier welding, produce less distortion, result ebetter weld metal qualities in heavy sections than joints prepared from one side onl

Butt joint weldingprocedure

A primary butt joint welding procedure concern is holding contraction stresses to a minimum while maintaining the desired shape and strength. The following example shows a typical contraction problem/solution. When you are working long seams, the metal deposited at the joint can contract and cause the edges to pull together and possibly lapve? Ou can adjust for the contraction by using a wedge to hold the edges apart. Move the wedge forward as you weld. If you use a wedge for spacing, you must remember that it is based on the metal that you are using and its thickness. Metal less than $1/_{16}$ - inch thick may be welded by flanging the edges. When flanging, tack the metal at intervals along the seam before welding.

You can also use jigs to hold metal parts in position for welding. You can align most points and hold them in place with angle iron pieces and angle mps, or you may have to use special jigs and clamps for some jobs

When the joint edges are beveled, the spacingletime exactly the same as the shoulder thickness at the joint edge bottom. Tack weld the parts in place at short intervals along the seam. Look for slag deposits after each tack weld. If slag is found, you must remove it before you make another tack weld. You must keep slag from contaminating your tack welds. To make the root bead, use a small diameter electrode that gives good penetration and fusion at the joint baseoA⁵/₃₂- inch diameter electrode is suitable for this purpose. Remember, the point base layer that you deposit must seal the space between the two plates and provide fusion at the root of the joint.

To get penetration when starting to weld a butt joint, hold a long arc momentarily. Tilt the top of the electrode slightly in the weldavel direction the holding time depends on the electrode and the current setting. After making the first pass, remove the slag from the root bead by chipping and wire brushing. You must do this after each pass to make a proper weld $\frac{5}{16}$ set $\frac{3}{16}$ inch electrode to make additional filler metal layers in the joint.

A weaving motion makes it possible to deposit more metal in a single pass when you are welding in a "V" on thick plates. The electrode movement is semicircular across the line of weld, and a slight pause in electrode movement at the toes of the weld will aid in preventing undercutting. The layers that you deposit depend on the metal thickness that you are welding. To do this, you build up (padding) a series of small stringer or weave **betace**ping the heat input and the hard zone formation in the base metal to a minimum. Each bead or layer will refine the grain in the weld immediately beneath it and will anneal or soften the hardness produced in the base metal by the previous bead.

To web thick sections beveled from both sides, deposit the weave beads alternately on one side and then on the other to reduce distortion that might occur in the welded structure ughly clean each bead or layer of weld metal, and remove all scale scale bead uniform you deposit any additional metal. Control the electrode motion to make each bead uniform in thickness and to prevent undercutting or overlap at the weld edges.

NOTE: For multiple pass welds achbead deposited must overlap each preceding by ¼ of the bead width in all welding types and positions.

Welding heat concerns

The heat developed at a joint by welding causes the metal to expand and, upon cooling, to contract. The uneven expansion and contraction can cause disto(ffigons-35). This distortion is caused by a greater amount of hot metal at the top of the weld than at the root, thus causing more contraction across the top of the weld joinfit the parts to be welded are restrained to where they cannot expand or contact propey, the parts can buckle, warp, or distort.

Figure 1 –35. Distortion caused by heat.

Welding thick metal presents many challenges. To meet the weld requirements for thick metal plate, prepare the joint edgesy beveling. This aids in getting 100 percent root penetration for the joint. Since the plate is thick and the bevel adds to the welding area, welds cannot be made by a single weld bead, so a series of either stringer or weave beads is used. Pass is refuting ethod used to deposit weld metal in multiplepasses. It is used in welding thick plates to avoid carrying a large molten metal pool, which can cause slag inclusions or cold spots in the *weba* ge molten metal pool is difficult to control, requires high heat with a slow weld travel speed, which results in excessive grain growth and unnecessary joint face melting.

By using multiplepass welds on thick plates, you can concentrate on getting good penetration at the weld root in the first pass. On succeeding layers, you can concentrate on getting good fusion with the bevel sides on and in the preceding layer. You can easily control the final layer to get a good, smooth surface. The weld metals lower layer often cools to a black heat and the**s tehæte**mperature that permits grain refinement (a form of heat treatment). The metal depth affected by this action depends on the welding heat penetration. In some welding work, when grain refinement in the welded joint top layer is needed, you can deposit an extra weld metal layer on the finished weld and then machine it off after cooling. The extra welding pass supplies additional welding heat to further refine the weld metal in the final layer at the joint surface.

When all else fails, perhaps then pieces thing to do (before welding) is to angle the pieces slightly in the opposite direction in which contraction is to take place. Then, upon cooling, the contraction forces will pull the pieces back into position.

Edge joint

The edge joint is used toijothe edges of parallel plates and weld thin sheet metal to reinforcing plates on -beams or angle iron. The procedures for setting up and welding edge joints are basically the same procedures used to set up and weld butt joints.

Edge jointpreparation

Preparing edge joints on lightauge metals, up to inch, requires that you clean the edge joint area and make sure that it is suitable for welding. To prepare metal that is or thicker, you most likely need to prepare the edge joint **tov**ide good fusion. You can prepare the edge joint in various ways. The usual way to prepare metal to 3/8-inch thick is to make a single bevel in one plate edge. For metal ove 3/8-inch thick, you can make a double "V" groove. You can do this by making a bevel in each platewhen you position them for welding, they form a "Wy preparing joints as described, you can increase the fusion area into the base metal resulting in a stronger weld joint.

Edge joint weldrequirements

The weld shown in figure-B6 illustrates the weld requirements for edge joints on sheet metal. When welding on lightgauge sheet metal, the penetration into the base metal should be 30 to 50 percent of T. Reinforcement should be 25 percent of T and the weld should be as wide as the thickness of the two metal sheets.

Figure 1 –36. Edge joint specifications (sheets).

Figure 1-37 shows the requirements for welds on thick metal plate sections such as angle iron and flat bar. These requirements are for metals that are not and greater. Penetration into the base metal should be at least t_{16} -inch, and reinforcement should be inch. The weld width is approximately $1/_8$ -inch wider than the beveled joint edges, bout wider than the thickness of the two plates.

Figure 1–37. Edge joint specifications (plates).

Edge joint welding procedure

When welding edge joints, clamp the sections together. This will reduce distortion as you weld. Tac welding along the joint is a good way to keep long joints aligned.

The electrode is tilted slightly in the weld travel direction and can be weaved on thick metal joints. You should be able to complete most edge joints with one welding pass. But, if more than one pass is required, make sure you remove the slag from each weld layer surface before welding the next pass. If you weld over slag, you get a weak weld.

607. Horizontal position welding

Gravity and other conditions must be approached difference when welding in the horizontal position in comparison tovelding in other positions. To weld in the horizontal position, the metal parts are at a 45 incline or more from the horizontal and the line of weld runs horizon(figly1-38) In this lesson, we discuss the different joints used and how you can prepare and weld them in the horizontal position.

Figure 1-38. Horizontal welding positions.

Making lap joints

To make lap joints, tack weld two over**bap**g plates in place and deposit a fillet weld in the horizontal position along the joint. Hold the electrode to form an angle approximately 45° from the lower edge and tilt it 20° in the welding travel directioheTelectrode position to the plates illustrated figure 1–39. When performing the first pass, you must use a weaving motion. Make sure you pause at the edge of the top plate long enough to ensure good fusion and no undercounting can make satisfactory lap joints on the or thicker plate by depositing a sequence of stringer beads (fig. 1–39. To make lap joints on plates of a different thickness, hold the electrode at an angle between 20°and 30° from verticalDo not overheat or undercut the thinner plate edge. Contreol t arc to wash the molten metal to the thin plate edge.

Tee joints

The tee joint resembles the letter "You make the tee joint by poisiting the two plates at approximately right angles. You can table vertical plate edge to the horizontal plate surface (fig. 1–40. Design and preparbet horizontal tee joint the same way as you did the flat tee joint, which we discussed earlier. Use a fillet weld to make the tee joint and a short arc to provide good fusion at the root and along the legs of the weld. Hold the electrode at a 45° angle to the plate surface and incline it approximatel 20° in the weld travel directio(fig. 1–41)

Figure 1 -40. Tee joint tack welds (horizontal position).

Figure 1 –41. Electrode position for a tee joint (horizontal position).

You can weldtin metal (4-inch or less) with a fillet weld in one pass, with little or no electrode weaving. Welding thicker plates may require two or more passes, in which you make each pass after the first in a semicircular weaving motion (fig.-42). A slight pause at the end ocleaveave ensures good fusion between the weld and the base metal without any undercutting. You can make a fillet-welded tee joint of/2-inch or thickerplate by depositing stringer beads in the sequence shown in figure 1-43 fora 1/2 inch fillet. For the second pass, hold the electrode at a 70° angle to the plate surface and incline it approximately 20° in the weld travel direction. The weld angle for the third pass is 30° to the plate surface and inclined approximately 20° in the weld travel direction.

NOTE: For multiple pass welds achbead deposited must overlap each preceding bead by 1/4 of the bead width in all welding types and positions

Figure 1 –42. Multiple pass fillet -weld weave motions (horizontal position).

Figure 1-43. Fillet welds on thick plate. (horizontal position).

You can use chain or stagge intermittent fillet welding (fig1-44) for long tee joints. You can use fillet welds when high weld strength is not required. However, arrange the shorts welds finished joint is equal in strength to a fillet weld along the entired we joint length from one side only.

NOTE: Using chain intermittent welds can reduce warping and distortion in the metal parts.

Figure 1-44. Intermittent fillet welds (horizontal position).

Welding butt and edgejoints

Since butt and edge joints are so much alike, let's discuss them together. The preparation and setup for butt and edge joints in the horizontal position is the same as for the flat positieor equirements for completed weld beads are also that as in the flat position.

However, the welding procedure for butt and edge joints in the horizontal positidifferent than it is for the flat position. When welding these joints in the horizontal position, you must overcome the effect of gravityon the molten weld puddle. For multiple pass welds on the butt joint, dbeirigst pass (root), hold the electrode at 90° to both plates with the tip of the electrode angled up 5°.

NOTE: To ensure complete penetration, you must maintain a keyhble looks like an old fashioned keyhole

If you keep the diameter of the keyhole constant, the amount of penetration will be uniform. For the second pass (hot passive a slight weave bead with the electrode held at 90° to both plates with the tip of the electrode angled up and down 5° into each toe of the root pass. This pass ties the root pass into both plates and helps push the root pass through for complete joint penetration. For the first filler pass, hold he electrode at a 90° angle to boltates with the tip of the electrode angled down 10° and incline it approximately 20° in the weld travel direction. For the next filler, **bass** the electrode at a 90° angle to both plates with the tip of the electrode at a 90° angle to both plates with the tip of the electrode at a 90° angle to both plates with the tip of the electrode at a 90° angle to both plates with the tip of the electrode angled up 10° to 15° and incline it approximately 20° in the weld travel direction.

Edge joints are only suitable for very light material because are the weakest of all the joints. order toaid in fighting the effects of gravity, hold the electrode at 90° to both plates with the tip of the electrode angled up 5° and incline it approximately 20° in the weld travel direction. The following table shows three things you can do to help control the molten puddle and prevent it from sagging:

| Controlling the Molten Puddle | | |
|---|---|--|
| What You Can Do | Benefit | |
| Lower the amperage setting. | Gives you a smaller and more easily controlled puddle. | |
| Angle the electrode up 5 to 10°. | Forces the arc to hold the molten metal up. | |
| Use a narrow weave motion with the electrode. | Spreads the heat more evenly throughout the joint, which keeps the puddle smaller and gives you better weld puddle control. | |

608. Vertical position welding

Welding in the vertical position means that you weld up or dowading this lesson gives you what you need to know about viewal position welding. We cover general and specific procedures required, including electrode selection, polarity setting, arc length, weave technique, and controlling gravity.

General welding procedures forall joints

Welding on a vertical surface is more difficult than welding in the flat or horizontal position because the force of gravity tends to cause metal to flow downwad this reason, make the current settings lower than those you use for the same electrode in the flat or horizontal positid the current you use for welding upward on vertical plates slightly higher than those you use for welding downward on the same plate. The proper travel angle between the electrode and the base metal is necessary in order to deposit a good bead weld. The electrode travel angle varies for entry on types.

Electrodes

We use ill -freeze and fastreeze electrodes in the vertical position to help prevent gravity from pulling down the molten metal (sag) from the electrodes and plate freeze electrodes include E 6013 mild steel, or E7018 low hydrogen. Fastreeze electrodes include 6010 or E 6011 mild steel. The maximum electrode diameter for vertical position welding insch.

Using smaller electrodes helps to maintain a small molten pupped in pupped in the surface tension to overcome the force of gravity ou usually use the current settings recommended by the electrode manufacturer. For more details on electrodes and current settings, you can review the AWS, TO 34W4-1–5, and mitary specifications. If you do not know where to find these references, check with your supervisor.

NOTE: Make your **a**c length slightly less than the electrode diameter, the shorter arc helps minimize sagging.

Bead welds

We use bead welds to weld drier upwards or downwards in the vertical position. To begin welding upward, hold the electrode at a right angle to both plates. To help prevent sagging, angle the electrode 10° to 15° up or pus(view A, fig. 1–45) You can increase or decrease angles to control the puddle and bead size. You then move the electrode in an upward whipping motion to create the weave bead pattern (view B, fig. 1–45) We use pertical up welding in the vertical position for welding heavy gauge metal of ¹/₄nch or more in thickess Penetration is deeper than vertical down welding.

To weld downward, hold the electrode at a right angle to both plates and 15° to 30° drag with the arc pointing upward to the deposited molten metal to creatpattern(view C, fig. 1–45). You can increase or decreasegales to control the puddlend beacsize. You then move the electrode in a downward and alternating side to side movement to create a slight semicircular weaveview tern D, fig. 1–45). We use vertical down for welding light gage metals that alters than ¼inch because

penetration is shallo, which makes it easier to produce welds without burning through the metal and we can perform such a weld apidly, which is very important when it comes to production.

Figure 1-45. Bead welding (vertical position).

Specific welding procedures fordifferent joints

Each joint that you weld in the vertical position has specific procedures that yotohowsto produce a good weld. Let's takeook at the specific procedures for lap, tee, bound dege joints.

Lap joints

When welding a lap joint on metals at are ¼ nch or lessuse a single ass weld. Start by holding the electrode 45° to the joint and angled 10° to 15° into each see slight weave motionFollow the guidelines in bead welds for work angles.

When lap joints are needed on thick plates you usually must weld more than one metal layer (multiple pass weld) to provide adequate penetration and strefiggth (46) Start with root pass, by holding the electrode 45° to the joint. Thisseures even penetration into both plates. For the second pass, angle the electrode 10° to 15° into each toe of the root pass using a slight weave motion. If a third pass is required, angle electrode 10° to 15° into each toe of the second pass **eachight** weave motion. This ties the second pass into both plates. Follow the guidelines in bead welds for work angles.

Figure 1 –46. Weaving depos its in layers (vertical position).

To weld lap joints in the vertical position, move the electrode in a triangular weave (figttelrrf17). For vertical up, tart at the bottom and weld upward. Move the electrode in a triangular weaving motion. A slight pause in the weave, at the points, impactive sidewall penetration and provide od fusion at the root of the jointMake sure your lirect the electrode more toward the vertical plate marked (G). Hold a short arc and pause slightly longer at the platface. Be careful not to undercut either of the plates or to allow the molten metal to overlap at the edges of the wistake. weld metal should overheat, momentarily shift the electrode away from the crater quickly without breaking t(figarle-49). This permits the molten metal to solidify without running down. Return the electrode immediately to the weld crater to maintain the desired weld size.

Figure 1 –47. Triangular weave pattern (vertical posit ion).

A slight pause at the end of the weave developped fusion without undercutting at the plate edges. To avoid trapping slag, thoroughly clean each weld layer by removing the slag coating with a chipping hammer and wire brus The precautions outled above ensure good fusion and uniform weld-metal deposits.

Tee joints

If you are welding a single pass tee join follow the same procedures yas u didwith the lap joint. For a multiple pass tee join follow the same procedures as you did with the joint. To weld tee joints in the vertical up positions fart at the bottom and weld upward. Move the electrode in a triangular weaving motio(fig. 1–48). A slight pause in the weave at the points, as we indicate in the figure, improves the sidewall pertection and provide good fusion at the root of the joint.

Figure 1 –48. Starting fillet welds (vertical position).

If the weld metal should overheat, momentarily shift the electrode away from the crater quick without breaking the ar(fig. 1–49) This permits the molten metal to solidify without running down. Return the electrode immediately to the weld crater to maintain the desired weld size.

Figure 1–49. Shifting the electrode to control overheated weld metal.

When more than one pass is necessary to make a tee weld, use the weaving motions we show in figures 1–50and 1–51A slight pause at the end of the weave developed fusion without undercutting at the plate edges. To avoid trapping slag, thoroughly clean each weld layer by removing the slag coating with a chipping hammer and wire brush.

Figure 1–51. Half circle shaped weaving pattern (vertical position).

Butt joints

We prepare but joints on plates in the vertical position for welding in the same way that buettod joints in the flat point. To get good fusion and penetration with no undercutting, hold a short arc and carefully control its motion. The recommended method is vertical up to weld butt joints on beveled plates inch in thickness by using a triangular weave motivities weld, fig. 1–52) Make welds on ½ inch or thicker and anityle0° to 15° into each toe of the root pass. This ties the root pass into both plates and anityle0° to 15° into each toe of the root pass. This ties the root pass into both plates and anityle0° to 15° into each toe of the methel Drivit pass the same as you do the second pass, except that you must angetentee ode 10° to 15° to each toe of the hot plates third pass to fill the joint in preparation for the cover pass. For the cover pashehold t electrode just likeyou did for the other passes, except you must angle the electrode 10° to 15° into each toe of the third pas to fill the joint in preparation for the cover pass. For the cover pashehold t electrode just likeyou did for the other passes, except you must angle the electrode 10° to 15° into each toe of the third pas. Deposit the last pass (cover) with a semicircular weaving motion with a slight "whip up" and pause the electrode at the bead edge. When you use a backup strip, make the welds in the same manner.

Edge joints

To weld edge joints in the vertical position, prepare and set up the joint the same way you did edge joints in the flat position. To overcome the effect of gravity on the molten puddle, use the same technique and machine adjustment we discussed in the lesson on horizontal welding. You can reduce the amperage setting, angle the electrode upward from 5 to 10°, and use a narrow weave motion to give you better puddle control.

609. Overhead positionwelding

Welding in the overhead positiongenerally the most ifficult. It requires that you weld while looking up and often stand or kneel in an awkward position. You also have to overcome gravity, which tends to cause the molten metal to drop down orssignaweld. This makes it harder for you to make proper welding beads with good penetration. In this lesson, we discuss the general and specific procedures for welding beads and fillets in different joints.

General procedures

There are certain procedures that you must follow to produce quality welds in the overhead welding position. Probably the most important thing to do is to follow the procedures that allow you to maintain control of the molten metal pool. You control it by using an extremely short arc adjusting the current carefully, you can make and hold a short arc length. If you hold an arc that is too long, it can increase the difficulty in transferring metal from the electrode to the base metal, and large globules of molten metal candor from the electrode and base metal. If this happens, you can shorten and lengthen the arc at intervals; however, be careful not to carry too large a pool of molten metal in the weld. Usually, only a slight electrode movement is necessary to deposition the average of the problems, check your current setting and electrode angle.

Use only electrodes designed for overhead welding-freeste electrodes such as \mathbb{E} 10 and \mathbb{E} 6011 are recommended left to that ar_{416}^2 -inch diameter or less are the most the most for overhead welding Generally, the larger the electrode diameter, the more difficult it is to maintain welding control of the molten pool.

Beadwelds

For bead welding in the overhead position, hold the electrode 90° to the bas(#ignetta53), and tilt it approximately10° to 15° in the welding travel direction. This action give a better view of the arc and weld crater. The recommended way to make weave beads is with an electrode that is inch or less in diametese(e fig. 1–54 or bead pattern)A rather rapid motion is necessary at the end of each semicircular weave to control the molten metal deposit. Avoid excessive weaving because this can cause the weld deposit to overheat and also create a large molten metal pool that can be hard to control

Figure 1 –53. Electrode angles (overhead position).

Figure 1 –54. Weave motion (overhead position).

NOTE: Weld with the knuckles of the hands pointing up and palms down. This prevents hot particles from getting trapped in the palm of your glove. It also allows spatter to roll of your glove.

Fillet welds

To make fillet welds on either or tee joints in the overhead position, hold a shronwith no electrode weavingHold the electrode approximately 45° to both vertical plated move it uniformly in the welding travel direction (view B, fig. 1–55) Control the arc motion to secure good penetration to the root of the weld and good fusion with the sidewalls of the vertical and horizontal plates. If the molten metal becomes too fluid and tends to sag, whip the electrode quickly away from the crater and ahead of the weld to lengthen the arc and to allow the metal to solidify. the electrode immediately to the crater and continue welding.

NOTE: There is the possibility of some falling moltemetal. Be sure you roll down the sleeves on your welding leather **and** the collar up to the neck. Wear a protective cap under your welding hood, and wear heavy duty boots.

Fillet welds for eitherap or tegioints on thick plate in the overhead position require multiple pass welds. We show the order in which you depositese beads in view A, figure 1–55. The first pass is a stringer tead with no electrode weaving motion. Make the second, third, and fourth passes with a slight circular motion of the electrode with the tip tilted about to 15° in the direction of welding (view C, fig. 1–55). This electrode motion permits greater cohand better distribution of the weld metal being deposited. Remove all slag from the surface of each pass by chipping or wire brushing before you apply additional beads in the joint the welding passes throw mustmake with the metals thickness and intended use. However, there may be times when other requirements call for you to weld a specific number of passes on one or both plate sides.

Figure 1-55. Fillet welding (overhead position).

NOTE: To avoid falling sparks and hot metal drippings, stand to the side rather than directly underneath the arc. Minimize the weight of the cable by draping it over a shoulder.

Specific welding procedures

There are specific procedures that you must follow to produce quality welds in the overhead welding position. Let's look at some specific procedures for welding beads and fillets in different joints.

Lap joints

You prepare and set up lap joints the same way as you do for the flat position. A good method to weld lap joints is to start by tack welding the plates in position. You are now ready to make the root pass into the root of the joint. Hold the electrode 45° to both plates **eepl the electrode atta**° to 15° travel angle to produce a weld with good perticina Beforeyou make your second and third pass, make sure that you clean off all slag first. If you don't, you'll have a weak weld.

Tee joints

Prepare and set up tee joints the same way as you do for the flat position. A good method to weld tee joints is to start by tack welding the plates in position. Next, make your root pass in the root of the joint. Hold the electrode 45° to both plates and keep the electrode at a 10° to 15° travel angle to produce a weld with good penetration. Before you **reak**our second and third pass, make sure that you clean off all slag first. If you don't, you'll have a weak weld takes four total passes to make a weld with good penetration (fig.-65, view A).

Butt joints

Prepare the plates for butt welding in ther**bæa**d position in the same wayy**abu** do in the flat position. You can obtain the most satisfactory welding results by using backup strips. If the plates are beveled with a feather edge and you don't use a backup strip, th**etered** boun through repeatedly unless you are very careful. For overhead welding a butt joint, a bead pattern weld rather than weave pattern is preferred ean each bead and chip the rough areas out before depositing another layer. We show the electrode position and the order to be followed in depositing welding beads or 4 and 1/2 inch plates in views B and C, figure 56. Make the first pass with the electrode held 90° to the plate, and 10° to 15° in the direction of travew A, fig. 1–56) The electrode should not be a large because if it is, it prevents holding a short arc, which is needed for good penetration at the root of the joint. The larger electrode usually means that more current is needed which creates a very fluid puddle that is difficult to control.

Figure 1–56. Multiple pass butt joint (overhead position).

Edgejoints

Prepare and set up edge joints for overhead welding the same way you prepare and set up edge joints in the flat position. Stringer beadseapreferred to give you better puddle cont@mplete welds on light-gauge sheet metal with one pass. When you are welding on thick metal plates that have been prepared with a "V" groove, use the technique and bead deposit sequencersfigure 1–56 for multiple-pass butt joints.

1–53

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

605. Bead welding and padding flat surfaces

- 1. In bead welding what is the first step to produce good padding?
- 2. What electrode angle do you use when bead welding?
- 3. When welding beads wat is the minimumacceptable penetration?
- 4. What determines the travel speed when bead welding?
- 5. How do you deposithe layers when padding?
- 6. When padding why do you first encicle the plate edges with beads?

606. Flat position welding

- 1. Name the two most common lap joints.
- 2. How do youform a tee joint?
- 3. What is the approximate minimum late overlap when welding a lap joint in 4-inch thick steel plate?
- 4. Why are stringer teads preferretor fillet welds of maximum strength and ductility?
- 5. What are the weld requirements fdap joint?
- 6. What causestress points in lap joints?

7. What are the weld requirements for a tee joint?

8. What are the chief causes of undercutting onjointeres?

9. Define a butt joint.

10. How can you prepare edges on thick plates for butt joints?

11. What governs the fusion zone width for welding thick plates?

12. What is theminimum penetration haven welding butt joints

13. List three devices the you caruse to control contraction and keep butt joint edges aligned.

14. What can you do toeduce distortionwhen welding butt joints from the side?

15. What is the edge jointused for?

16. What joint preparation is required for an edge joint/20 inch thick metal plate?

17. How wide do you make the beadhown welding edge joints thin sheet metal

18. What do you do to prevent distortion welding edge join?s

607. Horizontal position welding

1. Why do you use a weaving motion when welding homtal lap joints?

2. When you are welding lap joints on plates of different thicknessesses angle do you hold the electrode?

- 3. When welding horizontal tee joints what angledo you hold the electrode?
- 4. How many stringer beads do you use to weld iachthick tee joint in the borizontal position?
- 5. When you weld ace joint in the horizontal position how do you hold warping to a minimum?
- 6. How does butt and edge joint preparation for horizontal welding differ from preparation for flat position weding?
- 7. When you are horizontal weldinghat three actions can you take to overcome the force of gravity on the molten puddle?

608. Vertical position welding

- 1. What force must you overcome when welding vertically?
- 2. How do the current settings for vietal welding compare with those used for welding in the flat position?
- 3. What is themaximum diameter electrode recommended/emtical position welding?
- 4. For what thickness metal do you use vertical up weldinghy?
- 5. What are the electrode angles freelding a vertical lap joint?
- 6. While welding a vertical tee joint heatcan you do when the weld overheats?
- 7. What is the recommended method vertically welding butt jointshat are 4-inch in thickness?

609. Overhead position welding

- 1. What purpose does a short arc serveoin/verhead welding?
- 2. What are the two mostommon electrodeand diameterthat you use for overhead welding?
- 3. What can excessive weaving ause in bead welding?
- 4. At what angle and in which direction do you hold an electfod filet welding?
- 5. At what angle do you hold the electrode for weldingpajoint?
- 6. When welding a tee joint in the overhead positiloon w many total passels you need in order to make a weld with good penetration?
- 7. What purpose dbackup stripsserve for butt joint's
- 8. What carexcessive currentreate when welding a butt joint?
- 9. Why are stringer beadsreferred when welding an edge joint

1-4. Hard Surfacing

We don't use the shielded metal arc on carbon steel alone, nor do witejust for welding. It is almost as versatile as the oxyacetylene flame and can be for sweet ding gray iron castings and applying hard facing alloys. In this section, we discuss procedures for performing hard surfacing

610. Performing SMAW hard surfacing

Hard surfacing or hard facing is the process of applying extremely hard alloys to a softer metal's surface to increase resistance to wear, abrasion, corrosion, or impact. You can hard surface most steel, but you cannot always hard surface metals such as brass and bronze. In most cases, you can apply hardfacing alloys to a softer metalpoint, surface, or edge by using the electric arc proverses treated with these special allogree twearing surfaces of scrapers, grader blades, trencher teeth, front end loader parts, and other parts will outwear **meated** steel.

Metal preparation

Before hard surfacing, clean the metal's surface. You can remove scale, rust, dirt, and other foreign substances by grinding, machining, or chipp**ing**ou cannot use these methods, prepare the surface by filing, wire brushing, or sandblasting. Theteatmethods can leave small particles that usually float out during hard surfacing. Make sure you round all edges, grooves, corners, and recesses to prevent overheating the base metal

Preheating

Take the same precautions in preheating the base methalfd surfacing that you'd take in preheating it for welding. Aneal steels in the hetereated condition before apply the hard-surfacing layerQuenching in water usually cracks the haudfacing layertherefore, use oil instead when you have to heat metal to the critical temperature after hard surfacing. Oil helps the metal cool without cracking. When it is impossible or undesirable to anneal high carbon steels, deposit the hard surfacing by using the transition bead method. **Disest** me method before hard surfacing low alloy steel with high tensile strength. First, deposit a thin stainless steel layer, such as 25 percent chromium and 20 percent nickel rod or 18 percent chromium and 8 percent nickel rod (columbium stabilized). Next, build up the section to approximately the original dimension, using an 11 to 14 percent manganese or highterength rod. Finally, finish by hard surfacing with a groupplay rod.

Hard-surfacing deposit thickness

In most cases, you can rebuild worn sections with-bartacing deposits. If used, these deposits range from 1/32-inch to as thick as needed whenyou need to build up worn metal more than 1/32-inch to as thick as needed whenyou need to build up worn metal more than 1/32-inch to as thick as needed whenyou need to build up worn metal more than 1/32-inch to as thick as needed whenyou need to build up worn metal more than 1/32-inch to as thick as needed whenyou need to build up worn metal more than 1/32-inch to as thick as needed with 1/32-inch to us the finished size Add the finish hard surface deposit with group 2 or 3 alloys. Allow some excess deposit to permit grinding to the desired dimensions. When you apply harder and more brittle group 4 or 5 befracting materials, either as a final deposit or in a single layer arefully control the deposit shape. This is important because impact or shock loads may be transmitted through the bart provide metal into the tougher base metal. When not backed up by tough base metal integrations, sharp edges, or built sections chip or breading in service.

Hard surfacing with shielded metal arc

You do hard surfacing by arc welding in the same marking resimilar to joining metal by arc welding, except that the added metal's characteristics are not the same as the base metal. The added metal's characteristics would be changed or impaired if it were excessively diluted by or blended with the base metal. For this reason, applying the **sarfa**cing metal with the minimum welding heat possible should restrict penetration into the base metgeneral, the current, voltage, polarity, and other conditions recommended by the electrode manufacturer are based on this factor.

You can apply every harsdurfacing metal, except some alloys in groups 4 and 5, with every electrode coating or with a bare electrode by using reverse polarity. The flux coating on coated electrodes reduces spatter loss, assures good penetration, prevents oxidation, and helps to stabilize the arc use the bare, harsdurfacing electrodes when apply a heavy bead is necessary or deprosthe metal against a copper form. For best results, use a long arc to deposit the filler metal.

On parts subject to heavy wear, you can cdwerentire surface with a hasdrfacing alloy layer. On most jobs, a hard surface cover over the point and a welded stringer bead network over other wearing surfaces are adequate.

When equipment will be exposed to the abrasive action of sand, soil, and small stones, run hardsurfacing alloy stringer beads perpendicular to the flow. Run stringels becose together along the point; then space stringer beads a small distance (angart -57). Since the hard surfaced part is usually used on road equipment, dirt gets packed between the abreaded sther protest bease metal. Figure 1 –57. Stringer beads, perpendicular to flow.

For equipment designed to handle rocks, run stringer beads parallel with the mater(##gflow58) This pattern supports the rocks while offering the least flow resist Rucceing stringer beads is more economical than hard facing the entire surface, and the beads provide a good wearing surface.

Figure 1 –58. Stringer beads, parallel to flow.

When selfcleaning beads are desired diamond pattern is recommended by Can seeni figure 1–59 how dirt would slide up and over to one side opther, thereby cleaning itself.

Figure 1 – 59. Stringer beads, Diamond pattern.

NOTE: For more details on electrodes and rent settings, you are review the AWS, TO 34W4-1-5, military specifications, and ferences listed it he STS. If you do not know where to find these references, chevit h your supervisor.

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

610. Performing SMAW hard surfacing

- 1. What are three preferred cleaning methods tused epare metal for hard surfacing?
- 2. Why do you round the corner edgelsem preparing meal for hard surfacing?
- 3. What must you do first/hen hard surfacing steel is in the hterated condition?
- 4. What effect does water quenchingve on hardsurfacing deposits?
- 5. What is theminimum thicknesseou use to build up worn metal for hard subifug?
- 6. What are the advantages of using a coated electrode for hard surfacing?

Answers to Self -Test Questions

601

- 1. a. Path taken by an electric current in flowing through a conductor from one terminal of the source of supplyto the other. It starts from the negative terminal of the power supply where the current is produced, moves along the wire or cable to the load or working source, and then returns to the positiveterminal.
 - b. The force that causes current to flow in recurit. Voltage does not flow; only current flows, voltage pushes the current through the wires similar to a pump providing the pressure used to make water flow through pipes.
 - c. Also known as Amis a unit of measure for electricity that expresses thetity an number of electrons flowing through a conductor per unit of time.
 - d. An electrical circuit has a certain amount of resistance. An ohm is the amount of resistance electrical circuit. One ohm is the result of 1 volt applied across a resistance that allows 1 amp to flow through it.
- 2. An arc that is too long produces an unstable welding arc, increases splatter, reduces penetration, causes flat and wide beads, and prevents the gas shield from protecting the molten pool from atmospheric contamination.
- 3. Straight polarity.
- 4. (1) Gravity.
 - (2) Gas expansion.
 - (3) Electromagnetidorce.
 - (4) Surface tension
- 5. A magnetic field set up in the work by the flow of the welding current.
- 6. (1) The very hozonenext to the molten filler metal, (2) the annealed zoexet to the heated base metal, and (3) the zoneext to the cold base metal.
- 7. No; because penetration applies to depth and not width, so theffeeded area should not increase.
- 8. The longer the arc length, the greather heat affected area.
- 9. The heataffected area increases when the speed decreases
- 10. Arc welding.

602

- 1. 250-300 Ampere.
- 2. Constant potential and constant current.
- 3. Alternatingcurrent transformer.
- 4. Alternating current, directurrent transformerectifier.
- 5. Alternating current/direct current enginedriven generator.
- 6. It can be touched to any part of the work without danger of structuiting.
- 7. Cable connectors.
- 8. In your shop's machine maintenance guides or the owner's manual.
- 9. (1) Brushes.
 - (2) Commutator.
 - (3) Switch contact points.
 - (4) Bearings.
- 10. At 4- to 6-month intervals, depending on the number of operating hours.

603

- 1. Letter, numbers, or a combination of both.
- 2. The recommender delding position.
- 3. The tensile strength in thousands of psi.
- 4. F–1.
- 5. a. Black end, orange spot, and green group.
 - b. White spot only.
 - c. Black end and black spot.
 - d. No colorcodes (only a manufacturer's trademark 11018).
- 6. By controlling oxide and nitride formation during the welding process.
- 7. a. Heavy-coated.
 - b. Heavy-coated.
 - c. Heavy-coated.
 - d. Heavy-coated.
- 8. E 6010 and E6011.

604

- 1. (1) Welding task.
 - (2) Welding machine type.
 - (3) Electrode selection.
 - (4) Current selection.
 - (5) Safety procedures.
- 2. In hot weather when you are sweating.
- 3. Avoid the fume plume.
- 4. The# of the shadelens.
- 5. Wear leather gauntlet type gloves.
- 6. AF Form 592, USAF Welding, Cutting, and Brazing Permit

605

- 1. Make sure you have a clean working surfactive of oil, dirt, and other foreign matter.
- 2. 15° to 30° in the welding travel direction.
- 3. ¹/₁₆-inch.
- 4. The bead desired, current value, and electrode size.
- 5. At right angles to each other.
- 6. To make welding stringer beads easier, reduce cracks, and overheating caused by the work edges being melted away.

606

- 1. Singlefillet lap joint and doublefillet lap joint.
- 2. Join the edge of one plate approximately perpendicular to the face of another plate.
- 3. $\frac{3}{4}$ to 1-inch (3 to 4 times the metal thicknets metal over $\frac{1}{8}$ inch).
- 4. Each successive weld pass refines the grain structure of the previous pass.
- 5. Upper leg-1 T; lower leg-1½ T; throat-1 T.
- 6. An abrupt change in the shape of the weld face, such as undercutting or overlapping at the toe of the weld.
- 7. Upper leg-1½ T; lower leg-1½ T; throat-1 T.
- 8. Welding current that is too high and improper electrode angle.
- 9. The welding of two plates having surfaces in approximately the same plane.
- 10. By flame cutting, shearing, flame grooving, machining, chipping, and grinding.

- 11. The way that you prepare the joint.
- 12. 100 percent.
- 13. (1) Angle iron
 - (2) C-clamps
 - (3) Special jgs.
- 14. Weld beads alternately on one side and then the other.
- 15. To join the edges of parallel sheets and to weld plates to angle irorbaachs.
- 16. Double V.
- 17. The thickness of the two pieces of metal.
- 18. Clamp the joint or tack weld along theirjb

607

- 1. To ensure good fusion and to prevent undercutting.
- 2. At an angle between 20° and 30° from vertical.
- 3. At a 45° angle to the plate surfaces and inclined approximatelin 200e direction of the weld.
- 4. Three.
- 5. By using chain intermittentrovelds.
- 6. The preparation is the same.
- 7. (1) Use a lower amperage setting.
 - (2) Angle electrode upward^o50 10°.
 - (3) Use a narrow weave motion.

608

- 1. Gravity.
- 2. Make your current settings for vertical lower than those use for flat welding.
- 3. ³/₃₂- inch.
- 4. Heavy gauge metal of Mach or moe in thickness. Because penetration is deeperwhitenvertical down welding.
- 5. Hold the electrode 45° to the joint and angloe to 15° into each toe
- 6. Shift the electrode away from the crater quickly without breaking the arc, and return the electrode immediately to the weld crater to maintain the desired size.
- 7. Vertical up, using a triangular weave motion.

609

- 1. It helps maintain control of the molten pool.
- 2. E 6010, E 6011;³/₁₆-inch or less
- 3. It can cause the weld deposit to overheat and also creating molten metal pool that can be hard to control.
- 4. 45° to both vertical plates and 10° to 1i6° the weld travel direction.
- 5. 45° to both plates and keep the electrode at a 10° to 15° travel angle.
- 6. Four.
- 7. They help make the most satisfactory welding results.
- 8. A very fluid puddle which is difficult to control.
- 9. Better puddle control.

610

- 1. (1) Chipping.
 - (2) Machining.
 - (3) Grinding.
- 2. To prevent overheating the base metal.
- 3. Anneal the base metal.
- 4. It will crack thehard surfacing deposit.
- 5. $^{1}/_{32}$ -inch.
- 6. Reduced spatter loss, good penetration, oxidation prevention, and a stabilized arc.

Do the unit review exercises before going to the next unit.

Unit Review Exercises

Note to Student: Consideall choices carefully, select the stanswer to each question, and circle the corresponding letter. When you have completed all unit review exercises, transfer your answers to the FieldScoring Answer Sheet.

Do not return your answer sheet to the Air Force Career Development Academy (AFCDA).

1. (601) The measurement of thesistance in an electrical circuit is called

- b. current.
- c. voltage.
- c. an ohm.
- d. an ampere.

2. (601) What term is used when referring to an itempositive or negative charge

- a. Poarity.
- b. Flow rate.
- c. Resistance.
- d. Neutral balance.

3. (601) Which side does most of the heat gather on when using straight polarity

- a. Electrode.
- b. Machine.
- c. Cable.
- d. Work.

4. (601) In flat-position weldinghe main force responsible for fillerental transferis

- a. gravity.
- b. gas expansion.
- c. surface tension.
- d. electromagnetic.
- 5. (601) The heats effect on the base metagrain structure is divided into how many hattected zones?
 - a. 1.
 - b. 2.
 - c. 3.
 - d. 4.
- 6. (601) The heataffected area inra welding increases if the urrent is constant the
 - a. welding speed increases.
 - b. welding speedecreases
 - c. ground clamp is recured.
 - d. ground clamp repositioned.
- 7. (601) In which welding process does the haddected area produce a greater centrated hardness
 - a. Oxyacetylene.
 - b. Metallic Inert Gas.
 - c. Tungsten Inert Gas.
 - d. Shielded Metal Arc.

- (602) Which welding machine is used extensively in heavy structural work, fabricating heavy machine parts, heavy pipe and tank welding, and foinguscrap and cast iron?
 a. 50–100Ampere.
 - b. 150–200Ampere.
 - c. 250–300Ampere.
 - d. 400-600Ampere.
- 9. (602) Welding machines are classified as constant
 - a. current and direct current.
 - b. potential and constant current
 - c. current and alternating current.
 - d. potential and alternating current.
- 10. (602) Which welding machine is the least expensive, lightest, smallest, produces AC current, has low operating cost, high overall electrical efficiency, noiseless operation, and is free from magnetic arc blow?
 - a. Alternating current transformer
 - b. Direct current transformeectifier.
 - c. Alternating currendirect current transformerectifier.
 - d. Alternating currentdirect current engindriven generator.
- 11. (602) The factors that determine welding cable diameter are the scable
 - a. length and welding current.
 - b. connectors and ohm rating.
 - c. strand size and conductor material.
 - d. amp rating and insulation thickness.
- 12. (602) What determines an arc welding machinelectrode holder size?
 - a. Voltage control.
 - b. Current selected.
 - c. Welding process.
 - d. Amperage capacity.
- 13. (602) What do you use to clean dust out of an arc welding machine?
 - a. A water hose.
 - b. Soap and water.
 - c. An oil soaked rag.
 - d. Dry compressed air.
- 14. (602) How often a welding machine moving parts are lubricated is usually determined by the machines
 - a. hours in operation.
 - b. electric capacity.
 - c. type.
 - d. age.
- 15. (603) The two methods the Air Force uses to classify welding rods are
 - a. commercial specifications and international codes.
 - b. American Welding Society and international codes.
 - c. commercial specifications and military specifications.
 - d. American Welding Society and military specifications.

- a. Current type.
- b. Tensile strength.
- c. Amperage rating.
- d. Recommended position.
- 17. (603) What classification system uses the terms primary, secondary, and group as part of a color code system?
 - a. Military specification.
 - b. National Stock Number.
 - c. American WeldingSociety.
 - d. International electrode chart.
- 18. (603) Where can you find information on military specification codes and other details on electrodes?
 - a. TO34W4 1 5.
 - b. TO 38W5 1 3.
 - c. TO44W51 5.
 - d. TO 48/V4 1 3.
- 19. (603) The two materials used for coating hearogated electrodes re
 - a. zinc and fiber.
 - b. flux and oxidizers.
 - c. cellulose and mineral.
 - d. copper and deoxidizers.
- 20. (603) What type of electrodes are 65010 and E6011?
 - a. Fastfill.
 - b. Fill freeze.
 - c. Fastfreeze.
 - d. Light-coated.
- 21. (603) An electrode that producesgaseous shielding for the molten metal is identified as a a. bare electrode.
 - b. carbon electrode.
 - c. mineralcoated electrode.
 - d. cellulosecoated electrode.
- 22. (603) Which fill-freeze electrode is a lowydrogen, all position high speed, fast deposition electrode designed to pass the most severage requirements when applied in all welding positions, using either AC or DC reverse polarity?
 - a. E 6010.
 - b. E 6011.
 - c. E 7013.
 - d. E 7018.
- 23. (604) Which exhaust ventilation rtheod is the most effective for controlling toxic fußnes
 - a. Local.
 - b. General.
 - c. Dilution.
 - d. Variable.
- 24. (604) Which exhaust ventilation method collects air contaminates close to the welding operation and removes them from the work area?
 - a. Local.
 - b. Dilution.
 - c. Special purpose.
 - d. General purpose.
- 25. (604) If people must stay in an area where welding is being performed they should wear a. gloves.
 - b. gauntlets.
 - c. tinted goggles.
 - d. a leather apron.
- 26. (604) What office usually issues an AF form 5928 AF Welding, Cutting, and Brazing Permit a. Civil Engineering customer service element.
 - b. Squadron safety element.
 - c. Fire protection flight.
 - d. Operations branch.
- 27. (605) When bead welding, crater size and depth depends on current setting, treate batter on a type, and arc width.
 - b. type, and arc length.
 - c. diameter, and arc width.
 - d. diameter, and arc length.
- 28. (605) When padding multiple bead layers, what do you generally use to clean each bead run beforewelding an additional layer?
 - a. Wire brush.
 - b. Sand blaster.
 - c. Ball peen hammer.
 - d. High pressure hose.
- 29. (605) When you are padding with multiple layer beads, the layers should be
 - a. quenched often enough to eliminate excessive heat.
 - b. quenched only after they are completely padded.
 - c. smoothed with a hand grinder after each layer.
 - d. allowed to cool slowly between layers.
- 30. (606) The two most common arc weldlad joints are the
 - a. double and full fillet.
 - b. single and triple fillet.
 - c. double and triple fillet.
 - d. single and double fillet.
- 31. (606) When starting an arc on lap joints important to
 - a. weld toward the edge.
 - b. guard against undercutting.
 - c. hold a short arc to preheat the metal.
 - d. hold a long arc to ensure penetration.
- 32. (606) You canrelieve stressin lap joint welding by
 - a. creating a flat weld face.
 - b. undercutting the weld edge.
 - c. undercutting the toe of the weld.
 - d. creating a slightly convex weld face.

- 33. (606) What term is used to describe a butt joint connectiade in¹/₈-inch thick metal plate? a. Flat groove.
 - b. Square groove.
 - c. Double vee groove.
 - d. Single edge groove.
- 34. (606) What is the required penetration percentargheen welding a butt joint?
 - a. 25.
 - b. 50.
 - c. 75.
 - d. 100.
- 35. (606) How do you obtain penetration at the beginning of a butt?joi
 - a. Preheat the edge.
 - b. Preheat the center.
 - c. Hold a long arc momentarily.
 - d. Hold a short arc momentarily.

36. (606) When welding a joint, the contraction is greatesthe joints

- a. top.
- b. toe.
- c. root.
- d. bottom.
- 37. (606) When you are weldinghick plates, a large molten metal pool can cause a. slag inclusions.
 - b. faster weld travel speed.
 - c. decreased contamination.
 - d. lowered heat requirement.
- 38. (606) In welding, you use the edge joinot join plates that are
 - a. lapped.
 - b. butted.
 - c. paralle.
 - d. perpendicular.
- 39. (606) How much penetration is required to weld edge joints/inch thick metal?
 - a. ¼ inch.
 - b. ³/₁₆ inch.
 - c. ¹/₈ inch.
 - d. ¹/₁₆ inch.
- 40. (607) When you use a weaving motion **lap** joints in the horizontal positiona slight pauset the top plate edge
 - a. causes overlap.
 - b. ensures firmness.
 - c. causes undercutting.
 - d. ensures good fusion.
- 41. (607) What plate thickness allows you to make satisfactory lap joints positing a sequence of stringer beads?
 - a. $^{1}/_{8}$ inch.
 - b. ¼ inch.
 - c. ³/₈ inch.
 - d. 1/2 inch.

- 42. (607) How do you hold the electrode when you are welding tee jointhe horizontal position? a. At a 30 angle to the plate surface.
 - b. At a 45° angle to the plate surface.
 - c. Inclined 30 in the weld travel direction.
 - d. Inclined 45° in the weld travel direction.
- 43. (607) You arrange chain-intermittent fillet weldson a long horizontal tee joisso that short welds are equal in strength to
 - a. the full base metal.
 - b. the metal alloy filler.
 - c. a fillet weld along the entire jointength on both sides.
 - d. a fillet weld along the entire joint length on one side only.
- 44. (607) Using chainintermittent fillet weldson long horizontal tee jointsesults in
 - a. more cracking of the metal parts.
 - b. more warping of the metal parts.
 - c. less cracking of the metal parts.
 - d. less warping of the metal parts.
- 45. (607) How do you angle the electrode to control the molten pool when welding butt and edge joints in the horizontal position?
 - a. Up 5° to 10°.
 - b. Up 15° to 20°.
 - c. Down 5° to 10°.
 - d. Down 15° to 20°.
- 46. (608) When welding in the vertical position how do the electrode size and current setting compare to the flat position?
 - a. Smaller electrode, lower current.
 - b. Smaller electrode, higher current.
 - c. Larger electrode, reverse polarity.
 - d. Larger electrode, straight polarity.
- 47. (608) You make a filletweld in overhead weldingly making an arc
 - a. slightly longer than the electrode diameter.
 - b. slightly less than the electrode diameter.
 - c. equal to the diameter of the electrode.
 - d. equal to the thickness of the plate.
- 48. (608) To applybeadwelds verticalup, hold the electrode
 - a. 10° up.
 - b. 30° down.
 - c. 10° to the joint.
 - d. 30° to the joint.
- 49. (608) If the molten puddle becomes too fluid in the vertical welding position fillet welds,
 - a. reduce the current.
 - b. change the electrode.
 - c. stop welding and quench the plate.
 - d. whip the electrode away and then back quickly.

- 50. (608) When welding a vertical butt joint, how do you achieve fusion and penetration without undercutting?
 - a. Whip he arc back and forth.
 - b. Weave the arc in small semicircles.
 - c. Pause at the edge of the upper plate.
 - d. Hold a short arc and control its motion.
- 51. (609) What type of arc do you use to maintain control of the molten metal pool when you are welding in the overhead position
 - a. Longer than average.
 - b. Extremely long.
 - c. Extremely short.
 - d. Average.
- 52. (609) What is the recommended electrode diameter to use **by the** bead welding position? a. $\frac{3}{8}$ inch.
 - b. ⁵/₁₆ inch.
 - c. $\frac{3}{16}$ inch or less.
 - d. ¼ inch or gretær.
- 53. (609) To makefillet welds on either lap or tee joints theoverhead position, hold a
 - a. short arc, with slight weaving.
 - b. long arc, with slight weaving.
 - c. short arc, with no weaving.
 - d. long arc, with no weaving.
- 54. (609) If the molten pudded becomes too fluid in the verhead welding position fillet welds,
 - a. reduce the current.
 - b. change the electrode.
 - c. stop welding and quench the plate.
 - d. whip the electrode away and then back quickly.
- 55. (609) Which is the preferred attern forwelding butt joints in the overhead position
 - a. Diagonal.
 - b. Concave.
 - c. Weave.
 - d. Bead.
- 56. (610) What is the minimum thickness of hard surfacing deposits used to build up worn metal surfaces?
 - a. 1/32 inch.
 - b. ¹/₁₆ inch.
 - c. ³/₃₂ inch.
 - d. $^{1}/_{8}$ inch.

57. (610) What hardsurfacing pattern do you use where-studaningis desired?

- a. Parallel.
- b. Diagonal.
- c. Diamond.
- d. Perpendicular.

Argon is the most popular gas used for TIG welding. It is headwater air, so it provides a better blanket over the weld to protect it from contamensat

Helium

Helium is a colorless, odorless, nontoxic, and tasteless inert gas. Much lighter than air, it is the second lightest of all gases. Helium is nonflammable and, like argon, is placed under pressure in cylinders at pressures of 2,000 or 2,500 psiou can identify the cylinder byts distinctive color markings of gray with a buff (light brown) top. The cylinder is considered empty when the pressure is reduced to 25 psi. Helium is also much cheaper than argromy everyou use about onthind more helum because it is a lighter gasBecausehelium is several times lighter, it does not settle demond the work, and does not protect the weld as well as argometimes you will use arrgon/helium mix to weld metals that require a higher heat input.

NOTE: Make sure your follow all safety procedures for handling cylinders that you learned previously. If you are unsure, read the material safety data **\$M\$ERS** or ask your supervisor.

Gas shielded welding methods

There are various methodsedin gas shelded welding. We concentrate on twodG (fig. 2–1), and metallic inert gasMIG) (fig. 2–2). A significant difference between the two is that tungsten ignest uses a nonconsumable tungsten electrode, while UddeG a consumable alloy wire with approximately the same chemical composition as that of the metal being weldted are fusion-welding processes that use the heat produced by an electric arc between a metal electrode and the work. The principles involve the arc, or heating source, another same as those for shield the arc welding. However, in the gashielded process, an inert gas (helium or argon) flows from the orifices in the torch head past the electrode to form a protective blanket over the weld area. The gas shield's primary purpose is to keep oxygen, nitrogen, and carbon elements that are present in the air from coming in contact with the molten metal and contaminating the weld.



Figure 2 –1. Tungsten inert gas shielded pr ocess.

Figure 2 – 2. Metallic inert gas shielded process.

Gas shieldedwelding uses

Tungsten inertgasshieldedwelding is especially adapted for lightauge metathat requies the highest quality weld and/oinish. The process uses a good heat concentration, precise heat control, and the ability to weld with or without filler metals. It is also popular for welding small owntailed objects. For thicker gauge metatletallic inert gasshieldedwelding is peferred.

Gas shieldedwelding advantages

You can use the TIG welding process on a wide variety of light gauge, commercial metals up to 1/4-inch. TIG welding concentrates its low heat input from the electrode to a central point, which allows for welding on very thin metals with minimal distortion and/or alteration of the base metal properties. Gashieldedwelding produces welds that are stronger, more ductile, and more corrosion-resistant than the welds made with shieldeetal arc weldingThe protective gas shield in gas shielded welding envelops the weld and allowes joint to be made without flux; thus, eliminating flux caused corrosion and cleaning. The entire TIG welding process takes place without spatter, sparks, or fumes. MIG welding produces some spatter, but you can very easilyucle apatter from the work

612. Selecting and maintaining IG welding equipment

Before you use the TIG welding processuymust know what TIG welding equipment is needed and how it functions in order to makeigh quality welds. In this lesson, we cover the required pment along with its function.

Power source

Tungsten inert gas welding requires alternating (AC) or direct current (DC). The choice of AC or DC current depends on the metal and weld requirem Dirtsct current electrode negative (DC/EDCSP or DC-) welding is commonly used for ferrous metalsd AC highfrequency (ACHF) welding for aluminum and nonferrous metals. Direct current electrode positive (DC/EDCRPor DC+) can be used for welding both ferrous and nonferrous metals. The velding current may be supplied by an AC-DC enginedriven generator or an ADC transformerectifier (fig. 2–3). It is important that the power source providegood current control in the low current range. Stand DC welding machines are often selected because they provide good current output over a broad range. Some welding machines use a superimposed high frequency or (high frequency arc ignitigem) is tarting the arc without having the electrode contained work.

Figure 2–3. TIG welding machine.

Gas shieldedwelding torch

We use several gas shield edlding torch designs. They all operate basically the same except for the method by which they're cooled by air or by water.

Air-cooled torch

The aircooled torch(fig. 2–4) is designed to manual weld thingauge metals. It is excellent for weld-repairing aluminum and stainless steel parts. You carhiester for welding with high-frequency stabilized ternating current or straig belarity direct current, depending on the job requirements. It can perform continuously on AC or DC current up to 100 amperes.

Water-cooled torch

Watercooled torches are rated in amperes for different welding needs. If your welding task calls for using 200 amperes, we recommend that you use a **watted** torch like the one shown in figure52 It has channels th**at**low pump driven water to circulate through it to remove heat as the torch is being used. Most pumps circulate the water **to 2** pints per minute. A fuse is installed in the torch's power lead line to protect it from overheating in case of water store parts.

| Water-Cooled Torch Head Parts | | | | | |
|---|---|--|--|--|--|
| Part | Description | | | | |
| Collet body | The gas is fed to the weld zone through the collet body with the use of a gas nozzle (gas shielding cup/ceramic cup). | | | | |
| Collet or electrode holder | Goes inside the collet body. | | | | |
| | Holds the electrode into the torch. | | | | |
| | Different size collets are used for each different size electrode. | | | | |
| Tungsten electrode | | | | | |
| Gas-shielding cup (ceramic cup/gas nozzle) | Provides directional control for the shielding gas and is threaded onto the collet body. | | | | |
| | Gas nozzles are interchangeable to accommodate a variety of gas flow. | | | | |
| | Size of the gas nozzle used depends on the type and size of the torch and the diameter of the electrode used. | | | | |
| Gas-shielding cup cap | | | | | |

Figure 2-5. Water-cooled, inert gas shielded welding torch.

The shielding gas enters through a plastic hose fitted to the rear of the torch handle, passes through the body, and emerges from the gas orifices in the torch head. The glating cup directs the inert gas to the weld area.

In TIG welding, a replaceable electrode holder (collet) slides into the collet body to hold the electrode in place. The holders are made in various sizes to hold electrodes fromt0.02025inch in diameter and fror0- to 12 inches in length.

Hose

A flexible rubber or plastic hose is used to circulate water for cooling the torch and power lead cable. The bare flexible lead cable is enclosed in the water outlet hose. A separate hose is used **ter** the w inlet and another is used for feeding the shielding gas to the torch. If the water stops flowing, you must stop welding in ordeo prevent damage your equipment.

Water stoppage can also result from dirt in the torch passages. You might be **ablevie** the dirt by temporarily reversing the water hoses so that water flows in the opposite direction. Sometimes the water stoppage is due to a leak. You can usually trace waterline leaks to four possible causes:

- x Excessive water pressure.
- x Poor equipment minatenance.
- x Improperly sealed hose connections.
- x Cracks in the torch body.

You can usually stop most leaks quickly. For example, when a hose is damaged near a fitting, it is only necessary to cut away the damaged section and reattach the hose **togth& fit**quid sealant or a hose clamp should make a leak proof joint. When you shorten the water outlet hose, you must then remove equal length of electrical cable. However, cracks in the torch body can take more time. You may be able to solder it or you may have to replace it.

The argon or helium hose must be gas tight to not allow any gas leaks. If the molten pool becomes cloudy or the tungsten electrode turns blue on cooling, this indicates a leak in the hose or in the hose connections. If the platic hose is subjected to temperatures above 1725 will become soft and lose its strength. Therefore, protect and do not allow to come into contact with hot metal. Hoses also become brittle and crack as they age. These are the reasons whysy otherack your hoses before each use. If you cannot stop the leak, replace the hose.

Gas-control equipment

You can use **a**ingle or two stage regulator or a regulator with a flow meter to control the gas flow. A flow meter provides better gas flow control than the single or two stage regulators. A flow meter is calibrated to show the flow of gas in cubic feet per hour (cfh) os **biter** minute l(pm). The shielding gas flow is controlled by metering devices such as a combination regulator and flow(figne2er6). It steps down the high pressure in the cylinder or manifold cylinders to a lower working pressure. The gas flow is shown on a flowneter tube. In operations where the gas consumpting stations. The flow meter is equipped with a manual throttle valve for adjusting the gas flow allowing **setutue** flow as needed. The flowneter tube is calibrated at a positive pressure, which normally allows for back pressured give a true gas flow reading as flow is controlled by turning the adjusting screw on the flow meter. The rate of flow required depends on the metal being welded.

When a combination regulator flow meter is not available, you caa regulator that is identical in design and construction to the two experimentary oxygen regulator for argon. When only oxygen regulators are available for welding with helium, use an adapter to attach the regulator to the helium cylinder. An adapter is also necessary to attach the hose to the regulator.

You must install allow meter between the regulator and torch. It indicates gas flow to the torch in liters per minute or cubic feeter hour. You can determine gas flow in cubic feet per hour from the flow-meter setting. A flow of 1 liter per minute is equivalent to a flow of 2.12 cubic feet per hour Mount the cylindrical tube of the flow meter vertically since a lightweight the tube indicates gas flow by rising or fallingith the gas flow.

Auxiliary equipment

The foot control is a foedperated rheostat installed in the welding machine field circuit to change the arc for varying metal thickness. Thiss convenient wato make slight changes in the current settings as you weldAnother advantage toot control is that you can shut off the welding current while the gas continues to flow his protects the weld during cooling and helpes prevent crater cracking. If a machine does not have a binitwater and gas low control, you can install water gas shutoff valven sulate the valve from the grounded side of the welding circuit. On some welding machines, you can shut off water flow and gas flow to the torch by hanging the torch on a hooked arm provided for that purpose.

NOTE: You must always protect the leads of the welding machine fromsspradk damage. Make sure your move any flammable maizer from the welding area.

Protective equipment

The potective equipmentequired for inert gas welding is the same as that for metal arc welding leather sleeves or jacket, apron, gloves, safety glasses, welding helmetrith appropriate lens.

Equipment maintenance

The basic operator maintenance requients for TIG welding machines are similar to the maintenance performed on shielded metal arc welding machine mentioned in the previous unit. Always disconnect the power to the welding machine before performing any maintenance procedures. Check all the electrical circuit connections to make sure they are tight. Make sure there is not a build up of dust or debris around the connections. Check the electrical wiring for any cuts, nicks, or frays, and replace if needed. Check all water lines and gas hosesyfouts or abrasions. Check all connections for leaks using a scapsed leak detector, check all of the connections on the gas cylinder for any leaks. Replace any of these hoses as needed. TIG torch maintenance involves replacing broken gas cups and damaged collets. Inspect the torch body for any cracks or breaks in the insulation. Visually check the threaded connections for repair procedures on your particular torch. If you cannot make the repairs, contact your supervisor for contract repair or replacement.

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

611. TIG welding principles

- 1. Explain the term inert gas
- 2. What is a significant difference between TIG and MIG welding?

- 3. How does inert gas prevent weld contamination?
- 4. How do welds produced by asshielded welding compare with those made with ordinary metal arc welding?

612. Selecting and maintaining TIG welding equipment

- 1. List the two power sources available for usgais shieldedvelding.
- 2. What is the purposed using a superimposed high frequency
- 3. What are the advantages of using a waterled welding torch?
- 4. What are for possible causes of water line leakage?
- 5. If you have a gas flow of 5 liters per minute, what is the flow per hour
- 6. What protective equipmentust you weawhen TIG welding?

2–2. Application Procedures

We use tangsten inertgas welding extensively forepairs on thirgauge metal. It is also a very effective means to weld heat and corrosiensistant alloys, such as aluminum and stainless steel.

613. Job preparation

The time that you take to properly set up your inert gas welding equipment allows you to correct problems before you begin welding. By setting up your equip**foery**bur welding task, you can make high quality welds. The set up procedures that we explain are welding current, shielding gas, electrodes, and gas shielding cups.

Welding current

The welding current for TIG welding is either AC or DC. However, for certain distinctive weld characteristics, you must consider certain factors before you adjust the welding machine current. For example, the polarity you use in DC welding depends on the metal you are to weld. Direct current electrode negative (DCEN/DCSP or DGs suitable for welding stainless steel, copper, copper alloys, and low and mediumaloy steels. In straightolarity welding, the electrons flow from the electrode to the platewhich causes greater concentration of heat on the plate and produces less distortion However, in direct current electrode positive (DCEP/DCRP or DCm)

occurs; the electrons flow from the plate to the electrode causing a greater concentration of heat at the electrode, which then tends to melt off the end of the electrode. For any given current setting, DCEP/DCRP requires raelectrode that is approximately four times larger in diameter than would be used for DCEN/DCSPThese **p** poste heating effects influence not only the welding action but also the shape of the we(dig. 2–7). Welding on most commercial metals can be accomplished using DCEN/DCSP.

Figure 2-7. TIG weld contour comparis on.

By using a small diameter electrode with DCENCSP, you can produce a narrow, deep weld. By using a large diameter electrode with DCENCRP, you can produce a wide and relatively shallow weld. DCEPDCRP produces a cleaning action that removes the heavy oxide coating on metal, permitting flux-free welding on metals such as aluminand magnesium

Alternating current high frequency (ACHFi) principle, is a 50–50 combination of DCENCSP and DCEPDCRP. It reverses, in cycles, between the twantitides. In effect, the straightolarity component delivers adequate heat to the work, resulting in satisfactory penetration and speed, while the reversepolarity component breaks up the oxide film. Foreign mathetine surface of the plate such as moistre, oxides, and scaletends to prevent the current flow in the reversepolarity direction. If no current flows in the reverse direction, rectifications occurred. To prevent this, superimpose a lowntensity arc on the standard welding current (60 **bybligh** voltage (300volt), and high frequency (120,000). When high frequency is superimposed on AC current, a continual flow of electrons is jumping the gap between the electrode and the work piece, piercing the oxide film and forming a path for the weldig current to follow. This makes arc stabilization possible while maintaining a reverse polarity current flow.

Some advantages obtained from using highuency current are:

- x You can starthe arc without touching the electrode to the work piece.
- x Better ac starting and stability are obtained; a longer arc is possible.
- x Welding electrodes have a longer life.
- x Using wider current ranges is possible.

Figure 2-7 shows a typical weld contour produced with highequency stabilized ACAC produces better weld results on aluminum and magnesium than DCEP/DCRP.

Shielding gas

Gas purity may have considerable effect on welding, depending on the extent to which the metal is affected by contaminates. Consequently, stainless steel, as a rule, is not significantly **by feoted** percentages of contaminates in the shielding gas. In contrast, nonferrous metals, such as aluminum, are sensitive to impurities weld them with high-purity inert gas. The commercially available gon and helium gases average well over 99.95 percent in purity.

We generally usergon for alternating current TIG welding applications, such as welding aluminum, magnesium, and coppeln helium gas shieldinghearc is relatively hard to start whensingvery low welding current. This sue is not encountered with argon, attallow-arc voltage characteristic is particularly helpful in welding thin material because the tendency to burn through is reduced. We mainly use blium in DCENDCSP welding.

In manufacturing we make wide use of carbon dide and carbon dioxide mixtures as shielding gases. These gases give good results when use dveld carbon steel. When using carbon dioxide, make sure that your welding wire has a deoxidizer in it.

Electrodes

The electrode supples the arc required to methe base metalit is not consumed into the weld. The bead is formed by the arc melting the base metal. In inert gas shired the dg, there are two electrode types—(1) tungsten, normal electrode used in TIG welding, and (2) metal, consumable electrode used in MIG welding.

Tungsten electrodes

Electrodes may be either pure tungsten (99.4 percent pure) or a tungstenhadeyelectrode types used forgas shieldedvelding are(1) tungsten with thorium, (2) tungsten with zirconia, and (3) tungsten, 99.4 percent purAlloyed tungsten has or 2 percenthorium or zirconium.

Thoriated tungsten electrodes are superior to pure tungsten electrodes because of their better arc starting and stability, higher currectarrying capacity, and higher resiste to contamination.wo percenthorium electrodes maintain their formed point longer theoret enthorium electrodes and are primarily used in the aircraft and missile industries. One petroentum electrodes are used to weld steel.

Zirconiatedtungsten electrodes have better electrode performance for welding using alternating current. They resist contamination and retain the balled end better during welding.

The tungsten electrodes are practically consumable. However, if an electrode tousche molten pool, a small ball will form on the end of the tungsten rod. The contaminated end may cause an erratic arc, but youcan stabilize this by striking the arc on a copper placemove the excess metal pickup from the end of the electrode by grinding or breaking it off. Electrode loss **deattand** contaminates is a primary concern in TIG welding. You can prevent electrode loss by allowing the gas to flow a short time after the arc is broken gives the electrode time to cool in the electric deattand contaminent. The electrode diameter that you use depends on the electric current setting needed for welding.

Make sure the electrode extensible yound the end of the gashielding cup a distance equal to its diameter for but welding and slightly farther for fillet welding Selecting the right electrode for each job is important in preventing electrode damage (pure tungsten melts at the fight poor welds caused by a current that is too high or too low. Excessive currents **cauge** ten paintles to transfer to the weld, while insufficient current allows the arc to wander erratically over the electrode the end. T recommended electrode sizes for various welding current ranges are shown in fagure 2–

Figure 2–8. Electrode diameters, gas cup numbers, and amp settings.

NOTE: The electrode must be shaped correctly to produce a good weld. Use a sharp point with DC welding and a spherical (balled) enithwAC welding.

Filler rods

Filler rods are required/hen welding heavy gauge mețalsey can beadded to thin metals to reinforce the metal being welded. Filler rods must always be of the same composition as the base metal. Special filler rods are made for TIG welding. They contain large amounts ofiziers, id thereby producing less spattering in the weld and sounder weld joints. The diameter of the filler rod should be same as the thickness of the metal being welded.

NOTE: Oxyacetylene filler rods a meot recommended for use ith TIG weldingbecause they contaminate the electrode.

Gas-shielding cups

Gasshielding cups used with TIG welding can be made from plastic, metal, or ceramic material. They're made in various sizets sizeyou select depends on the electrode diameter that is(fugsed 2–8). The cup number indicates the cup opening diameter in multiples of the cup opening Another consideration in cup selection is the amperage used during 8-cup has a ¹/₄ nch cup opening Another consideration in cup selection is the amperage used during welding. The continued use of the torch at high amperage tends to deteriorate the shielding gas cup. For this reason, metal, or water old cups are good choices for currents above 100 amperes.

614. TIG welding procedures

There are times when you may need to weld a joint and have it match the qualities fibrenchetal that you are welding. For example, ferrous alloy and carbon steel have good heat and corrosion resistance qualities you may want your welded joint to have these qualities too. In this lesson, we discuss how you can prepare and weld edge, butt, lap, tee, and corner joints to have these qualities. We have selected stainless steel as our choice because it has good heat and corrosion resistant qualities. We also cover the procedures for welding joints of carbon steel. Let's start our discussion with some factors that can help you achieve welding success.

Stainless steel welding factors

Choosing the best welding process is important to get a weld that matches the qualities you need. The inert gas shielde velding process is the preferred way to weld stainless steel and other corrosion resistant steels and alloy velds is process extensively to fabricate and repair hospital and kitchen parts because it produces less warping, prevents oxidation, and maintains the maximum corrosion resistance in the elded part By using special fixtures, certain techniques, proper current settings, and welding speed, you can produce high quality welds.

Since the metal expansion coefficient for stainless steel is approximately 60 percent greater than carbon steels, you need to take specific procedures to correctly align, space, and tack weld the joint edges. Your goal is to keep the nhétam warping during welding. The specific procedures that you use are primarily influenced by the metal thickness. For examplegabinge metals tend to warp more than thicker gauge metals; so, you must make your tack welds at closer intervals. Carbide precipitation(carbon separation from the stainless steel) is another factor to consider in welding stainless steel. Isian unstable condition that occursainsteniticstainless steel that contains carbon in a saturated solid form. Welding causes the saturated carbon to precipitate. You can keep it to a minimum by confining the arc or heat to as small an area as potseibte also reduce carbide precipitation. Since the tungsten electrode has a very high melting point, it permits higher amperages with smaller diameter electrodes. You can also use higher welding speeds, weights in a narrow heat ffected zone and more rapid cooling.

Figure 2–9shows the right and wrong ways to grind the tungsten electrode when welding steel. We show he correct way to grind the electrode in fig2re, view B. As you can see in the figure, the grind marks run toward the point instead of across the electrode. By having the grind marks running toward the point, you get a smoother arc, less arc waver, and no current flow restrictions.

```
Figure 2 –9. Grind marks on electrodes.
```

There are two potential problem areas involving your weld joints erside. The first is controlling atmospheric contamination (oxygen, nitrogen, and carbon elements), cahicause weld porosity or a poor surface appearance. The second is conducting heat away from the joint edges to prevent the weld from melting through. There are four techniques ganues to control these potential problems:

- x A backup metal strip positioned on the joint underside
- x Flux applied to the joint underside.
- x An inert gas directed to the joint underside.
- x A backup metal strip in combination with an inert gas.

The first technique, the backup metal strip, is made from scrap steel or coppeanYostet on thick or thin metal to conduct excess heat away and prevent the weld from melting through.

Only use backing strips on flange type joi(ftg. 2–10). If the strip comes in contact with the weld underside, the penetration will be rough and uneven. On square edge butyjointe, the backup strip directly below the joint edge(sig. 2–11). This groove permits the weld metal to penetrate uniformly through the joint.

Figure 2–10. Backup plate used on a flange -type joint.

Figure 2–11. Backup plate used on square- edge butt joint.

The second technique involves applying a flux to the joint to reduce atmospheric contamination in your weld. We often usite with thin-gauge metal.

Use he third and fourth techniques when the weld must conform to extremely rigid specifications. Take extra care to exclude all atmospheric contamination from the Yoeldcan do this by introducing shielding gas into the inefigroove of the backing plate. When the joint prohibits using a backing plate, you can direct a series of hydrogen flames on the joinderside to exclude contamination from the weld.

NOTE: Set the high frequency switch to the position for steeland to the continuous position for aluminum

Welding stainless steel edge joints

The edge joint is easy to weld and is used primarily on-**bjgbuge** meta Do not use it if direct tension or bending stresses to be applied to it, because it is not track gioint and may fail at the root under relatively low stress loads

Edge joint preparation is simple. Clean the joint edges thoroughly to remove all foreign material. Make sure that the edges fit together evenly and that you remove all Abwersy close fit up is necessary for the edges to fuse together without filler rod.

Machine setting and equipment adjustment

For metal thickness from .030 .051 inch, you may alter the setting slightly to fit the metal thickness. Set the current for 15 to 30 amps DCENSP. Adjust the flow meter to allow 8 to 10 liters of gas flow per minute. Use a tungsten electrode with a diameter from 049 inch. Adjust the electrode to extend to 3/16 inches beyond the gashielding cup edge. With a water old torch, the water flow should be approximately 1 pint per minute.

Welding application

At the weld starting point, strike and hold an arc until a molten pool develops. Hold the electrode as nearly vertical to the joint as possible and **late** uthe travel speed to produce a uniform bead. A slow welding speed causes molten metal to roll off the metal edge. Irregular or rapid travel speed produces a rough or an uneven surface terminate the weld, remove your foot from the foot countr to stop the arcThe shielding gas will continue to flow over the weld area until its tood black heat.

When you must weld in the vertical, horizontal, or overhead position, there are some actions you can take to improve quality. When vertical doing on thin material, weld vertical down. This present your burning away too much of the edge. On thicker metal, weld vertical up to get better penetration. Whether you are welding up or down, add the filler rod to the puddle's leading edge.

To weld in the horizontabosition, control your speed and arc length carefully. Makeatc length approximately the same as the electrode dianaeteruse a welding speed that permits adequate penetration without undercutting the weld's upper edgeothertechnique that prevents undercutting is dipping the filler rod into the upper, leading edge of the puddle as needed.

To maintain better puddle control when overheadding, reduce the welding current by 5 to 10 percent. This eduction in welding currentives you a smaller bead, which less affected by gravity.

You can applyhese techniques to edge, butt, lap, tee, and corner joints on aluminum or steel.

Stainless steel butt joints

When using gas shield endelding to make narrow beads on stainless **state** joints, you may not need reinforcement. The reason is that the shielding gas results in a weld with high ductility and high tensile strength. Because the small electrode carries high amperage, you can make a narrow weld with a fusion quality that equals a wider weld made with oxyacetylene or shield arc welding processes.

The squareedge butt joint is easy to prepare and can be welded with or without filler metal, depending on the metal thickness being welded. When you weld thin gauge **metal wid**ding filler metal, you need to be extremely careful to avoid low spots and burn through. The thicker metal generally require filler metal to provide adequate reinforcement.

Metal preparation and setup

For all welding positions, you must perform proper cleaning of the metal to remove all oxidation, scale, oil, grease, dirt, and other foreign matteu dan do this either chemically or mechanically. The first step in preparing thin gauge sheet metal is to shear the metal to size. You must remove all burrs from the joint edges and thoroughly clean the joint area before welding. When you weld butt

joints, align the joint edges parallel, allowing a space approximately equal to the metal thickness being welded, and then tack we fig. 2–12)

Figure 2–12. Tack welding stainless steel.

Machine settings and equipment adjustment

The electrode diameter and cup size varies with the metal that you want to weld. A general guide for welding metal from .030to .051inch thick is to adjust the TIG welding machinging the sequence in the table below.

| TIG Welding Machine Adjustments | | | | |
|---------------------------------|--|--|--|--|
| Sequence | Action | | | |
| 1 | Set the electric current to weld the selected metal thickness. | | | |
| 2 | Set it to DCEN/DCSP at 15 to 30 amperes. | | | |
| 3 | Use an argon shielding gas with a 5 to 6 liter per minute flow rate. | | | |
| 4 | Use a tungsten electrode .040 to ³ / ₃₂ -inches in diameter. | | | |
| 5 | Adjust the electrode to extend slightly beyond the gas-shielding cup edge ($^{1}/_{8}$ - to $^{3}/_{16}$ -inch for flat welds and $^{1}/_{4}$ - to $^{3}/_{8}$ -inches for fillet welds). | | | |
| 6 | If the torch is water cooled, adjust the water flow to approximately 1 pint per minute. | | | |

NOTE: Different welding applications affect how far the electrode extends. The basic idea is to keep the distance as short as possible **anges**ta quality weld. We recommend following the manufacturer's guide.

Welding application

If the DC machine is equipped with a high frequency starter, the electrode does not have to touch the plate If the machine is not, you must touch the electrodbetoplate.You begin by striking an arc on a copper plate with the for potential rheostat set in the high position. Immediately after getting an arc, swing the foot control toward the low position and back again toward high, fluctuating the current intensity to steady the arc characteristics. Move the arc to the joint edges and travel steadily along (forehand), holding the electrode as nearly vertical to the joint as possible. Add filler rod to the forward edge of the molten pool to prevent contaminating the tungsten electrode and to aid in weld control

To terminate the weld, swing the foot control to the low position to break the haspermits the shielding gas to flow over the weld area until it scool a black heat. To avoid overlap in esting a weld, strike the arc ahead of the terminated weld (approximately the and then move the arc back to the end of the weld, bringing the weld to a molten state before adding filler rod.

The weld reinforcement (bead height) for the standard sta

Stainless steel lap, tee, and corner jots

You need to be familiar with how we use various joints in welding. Let's look at the three joints you most likely will use the lap, tee, and corner joints.

Lap joints

We use ap joints to join two overlapping stainless steel sheets so that one sheet is welded to the surface of the other. When the joint design does not permit welding from both sides, you can weld the joint from one side only. For some applications, such as tubular splices, aveinged lap is satisfactory; however, a singleelded lap joint in sheet metal will not develop the full base metal strength. We use p joints extensively to repair stainless steel parts because the joint is easy to prepare and easy to weld. You can use the spired ded welding process on stainless steel lap welds up to .0625 inch in thickness without having to use any filler rod. You can make the weld by directing the arc to melt the upper edge of the joint make a smooth, slightly convex weld bead.

| Making a Lap Joint | | | | | |
|--|---|--|--|--|--|
| Step | Action | | | | |
| Metal preparation and setup | Shear the pieces to be lap welded to leave a square edge that is free of burrs and warping. | | | | |
| | Clean the weld area thoroughly to remove all foreign materials. You may use steel wool for this purpose. | | | | |
| Machine setting and equipment adjustment | The machine and equipment settings for welding lap joints are similar to those used for butt welds. | | | | |
| | The difference is that you set the lap joint amperage 20 to 40 amperes higher. | | | | |
| Welding application | After the arc is struck and stabilized on a copper plate, move the arc to the joint edge and travel steadily along (forehand), melting back approximately one to two thickness of the top sheet. Failure to melt back the top sheet results in a concave undercut bead. | | | | |
| | Weaving the torch is not necessary to lap weld thin-gauge stainless steel sheets. Tilt the torch head slightly toward the root of the joint and in the weld travel direction. | | | | |
| | Take care to ensure that penetration at the root of the weld is 15 to 85 percent of T. | | | | |
| | The reinforcement should not extend above the upper sheet thickness. The bead contour should be slightly convex. The weld metal should taper smoothly into the base metal with no overlap, and the bead width should be from two to three times T. | | | | |
| | The surface appearance should be dark bronze or light purple. | | | | |

Tee and corner joints

We use the and corner joints to join two plates whose surfaces are at an approximate 90° angle to each other. You can doeleding from one or both sides, depending on the position, joint type, and strength required.

Metal preparation and setup

To make a tee or corner weld, first shear the stainless steel sheet to a square edgeetbábisrrs and warping. Thoroughly clean the joint edges. For metal up to i0625n thickness, no edge

preparation othethan cleaning and square shearing is necessary. We sometimes pretate the arbitrary over .0625 inch thick for a double evel tee or a single evel tee when we can weld the jointly from one side or when maximum strength is necessary. Despace tee or corner joints for ingets shielded arc welding because the concentrated heat of the arc permits proper fusion and penetration without spacing the jointWe also recommend that you flux the backside of tee joints and the corner joint's underside before you weld.

Machine setting and equipment adjustment

The machine and equipment settings for welding tee and corner joints are similar to the settings for butt welds. The difference for corner joints is that you adjustargon flow to 8 to 10 liters per minute The difference for tee joints is that the electrode usually extent the ³/₆ -inchesbeyond the edge of the gashielding cup.

Welding application

Strike and hold an arc on copper plate, using the **foot** rol rheostat to establish a stable atth whie required heat. Tack weld the joint edges about 1½ inches apart. Hold the torch so that the isect included angle made by the two pieces being welded and satisfies any perpendicular to the weld areas as practical. To weld sheets of une thickers, preheat the thicker sheet with a long arc and direct the heat on the thicker sheet during the actual welding oper **Attice** the filler rod at the root of the joint and the forward edge of the molten per the molten pool and end of the filler rod with the shielding gas during the entire welding operation.

The torch angle, heat input, and weld travel speed **breuek**act in welding the tee joint to ensure adequate penetration at the root of the weld without burning through **threalvsh**eet. To terminate the weld, swing the foot control to the low position to break the arc and permit the shielding gas to flow over the weld area until it cosolo a black heat. The tee wesdupper and lower legs should equal 1½ T. The corner joinstupper and lower legs should equal T. The throat of the weld for both tee and corner welds should equal approximately the sheet thickness.

Tee welds should have a face contour varying from slightly concave to slightly convex. Corner welds should have a convex face to ensure the proper throat depth. The weld surfaces must be free of welding defects and excessive contamination. Refer to the discussion in Urtitle for concedures and techniques to use when welding these joints.

Welding carbon steel joints

Welding low carbon steel joints are easily done by the TIG process, but medium and high carbon steels require extensive preheating and-presiding heat treating to get satisfactory results.

When welding carbon steels with the TIG process, the **suited** filler rods are made from low carbon steel with deoxidizers **D**xyacetylene welding rods don't contain the deoxidizers needed for the TIG process Without deoxidizers your weld becomes porous (a welding defect). For this reason, do notuse oxyacetylene welding rods.

The TIG welding process is particularly good for welding that we metals. It is not recommended and is not economically feasible for welding carbon steel joints on metal thicker times.¹/⁴Metal thicker than ¹/₄nch would require many passes to complete using TI^C outd be welded more efficiently by the shielded netal arc or metallic inert gas methods.

Since this process is used on metals less than thick, there is usually no special edge preparation required oth than cleaning the metal. Set up the butt, edge, tee, and lap joints in the same way you'd set them up for stainless steel joints. For welding procedures and techniques, review the welding stainless steel edge joints attended we discussed earlied in the 1).

Aluminum joints

You can find auminum joints in many Air Force facilities. The joints are part of such items as structural supports, doorframeend windows. The trend to use aluminwith probably continue as new aluminum alloys are developed that light weight, strong, and corrosion resistant. Because you're in the structural career field, it is your job to repair them. In the following paragreephs discuss how you prepare and weld joints to make effective repairs in aluminum and aluminem alloy

Welding aluminum joints

Aluminum and aluminum alloys that can be welded by the TIG welding process intotal de00, 3003, 3004, 5005, 5050, 5052, 5083, 5154, 6061, 6062, and 6063 alloys. Welding and an expect heater at alloys reduces their strenger or an expect heater at alloys in the "as welded condition" to develop 40 to 60 percent of their original strength.

Welding setup and application

Support he weld with a backup bar or plate when possible, except when welding from both sides. The backup bar can be copper, steel, or aluminum. Copper and steel backups should be removable. When you use an aluminum backup bar or plate, it should be compatible with the metal being welded. Backup plates are recommended to control heat for welding penetration and to permit faster welding speeds. Usenert gas backup when highuality welding is necessary

Figure 2–13 shows a tungsten electrode with grinding marks ending in a ball tip. The ball tip helps the electrode to have the best current cagramaracteristics for welding aluminum. You can form this ball by arcing the electrode on a clean aluminum or copper strip.

Figure 2–13. Ball tipped electrode for welding aluminum.

Clamp he aluminum to be wheed for alignment and spacing. Good joint fit up makes welding easier. Adjust the current setting and argon flow for the aluminum thickness. Start the arc by bringing the tungsten electrode close to the work surface. The electrode does not have to to to to the plate because the high requency current forms a path to the work plate just the arc distance to the plate to $\frac{1}{8}$ - to $\frac{3}{16}$ -inch. Hold the arc at the starting point until the metal liquefies and a molter spool made. Add the filler ord manually to the front edge of the molten pool, melting a small amount and withdrawing the rodPoint the torch in the direction of travel at a to 20° angle from the vertical position. Hold the filler rod fairly flat to the work surface between to 30° from the horizontal position. Advance steadily along the line of weld, keeping a uniform bead with evenly spaced ripples. To terminate the weld, release the foot switchile keeping the torch directed onto the molten pool. Gas and water will comute to flow for a few seconds, cooling the weld and preventing contamination and cracking ou can minimize racking during welding by using the steps shown in figure 2–14.

```
Figure 2 –14. Minimizing crac king during welding.
```

Weld specifications

The weld specifications for aluminum can vary with its thickness and the alloy used. The bead width can be two to three times the base metal's thickness. The reinforcement can range from 25 to 30 percent TTheupper and lower legs should be equal to $1\frac{1}{2}$ T and face slightly concave or convex. The following tables a guideline for work angle, travel angle, and drag/weave for flat, horizontal, vertical up, and vertical down welding positions

| | Flat | Horizontal | Vertical down | Vertical up |
|--------------|------------|--------------------|---------------|-------------|
| | Butt Lap T | All joints | All joints | All joints |
| Work Angle | 90° | 15° | | |
| Travel Angle | 15° torch | 15° push | 90° torch | 60° torch |
| | 15° filler | | 15° filler | 45° filler |
| Drag/Weave | steady | Begin ½" from side | down | up |

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

613. Job Preparation

- 1. When TIG welding with DCENDCSPand a small diameter electrochemat is the resulting bead contour?
- 2. What shielding gas do youse for TIG welding with alternating current

- 3. What desirable features dooriated tungsten electrodeave?
- 4. If the electrode becomes contaminated and erratic, what can youstabilize the arc?
- 5. How far should the electrode extend beyond the end of the highlighting cup for butt and fillet welding?
- 6. A number eight cup **saw**hat size cup opening?

614. TIG welding procedures

- 1. Why do we usenert gas shielder welding extensively for fabricating and repairing kitchen parts?
- 2. How does the coefficient of expansition stainless steedompare with that of carbon steel
- 3. How can you keep carbide precipitation a minimum?
- 4. How do you back up a weld?
- 5. What purpose does backing up a weld serve?
- 6. Under what circumstances you not usen edge joint?
- 7. Why is a very close joint fit up necessary when preparing an edge joint?
- 8. What amp setting do you use for welding .06Ch-thick stainless steel edge joints?
- 9. What type of edge joint surfacteesanirregular or rapid welding speed produce?

- 10. How do you erminate a weld?
- 11. How long do you make the archown welding in theorizontal position?
- 12. Why do you add filler rod to the forward edge of the molten pool?
- 13. Why are welded lap joints used extensively to restainless steeparts?
- 14. Explain theedge preparation for TIG welding stainless steel corner joints.
- 15. What occus if you do not melt back to sheet (lap joint) approximately the thickness of one to two sheets?
- 16. Describe how you add filler rod to a stainless steel tee joint us@gvelding.
- 17. The TIG welding process can easily weldat/carbon steetlype?
- 18. Why doesn't dow carbon steel oxyacetylene welding rod give good results wherinus welding?
- 19. What is the recommended maximum thickness for welding carbon steel DJG process?
- 20. What is the purpose of a backup bar?
- 21. What do you use when highuality aluminum welding is necessary?
- 22. What produces an arc without the electrode touching the metal?

23. Why do you allow the gasto continue to flow for a few sends after you complete the welding?

24. What is the percentage range for reinforcement used in aluminum welding?

Answers to Self -Test Questions

611

- 1. A chemically inactive gas that will not combine with any other element.
- 2. TIG uses a nonconsumable tungsten electrode, while MIG uses a consumable alloy wire with about the same composition as that of the metal being welded.
- 3. It prevents the oxygen, nitrogen, and carbon elements present in the air from coming in contact with the molten metal in youweld.
- 4. They're stronger, more ductilend more corrosion resistant.

612

- 1. (1) An AC-DC enginedriven generator.
 - (2) An AC-DC transformerrectifier.
- 2. Starting the arc without contact between the electrode and the work.
- 3. For one, you can use a highourrent, and for another, there is no danger of overheating as long as the water flows.
- 4. (1) Excessively high water pressure.
 - (2) Mistreatment of equipment.
 - (3) Improperly sealed hose connections.
 - (4) Cracks in the torch body.
- 5. 10.6 cubic feet per hour (1 dit per minute is equivalent to 2.12 cubic feet per hour).
- 6. Leather sleeves or jacket, apron, gloves, safety glasses, and welding helmet with appropriate lens.

613

- 1. A narrow, deep weld.
- 2. Argon.
- 3. Better arc starting and stability, higher curreating capacity, and higher resistance to contamination.
- 4. Strike the arc on a copper plate.
- 5. A distance equal to its diameter for bwtelding and slightly farther for fillet welding.
- 6. ¹/₂-inch cup opening(The cup number indicates the cup opendiagmeter in multiples of /₁₆-inch).

614

- 1. Because it warps less; events oxidation, and maintains the maximum of corrosion resistance in the welded part.
- 2. The coefficient for stainless steel is approximately 60 percent greater than that for carbon steel.
- 3. By confining the arc to as small an area as possible while still obtaining proper fusion.
- 4. By positioning a metastrip on the joint underside.
- 5. It conducts excess heat away **ame** vents the weld from melting through.
- 6. If direct tension or bending stresses to be applied to the finished product.
- 7. To allow the edges to fuse together without the use of a filler rod.
- 8. 15 to 30 amps DCEN/DCSP.

- 9. A rough or an uneven surface.
- 10. Remove your foot from the control to permit the shielding gas to flow over the weld area would the black heat.
- 11. Approximately the same as the electrode diameter.
- 12. To prevent contaminating the tungsten electrode and to aid in weld control.
- 13. Because lap joints are easy to prepare and weld.
- 14. Shear thetainless steel sheet to leave a square edge that is warp and burr free.
- 15. It will result in a concave undercut bead.
- 16. It is added at the root of the joint and the forward edge of the molten pool.
- 17. Low carbon steel.
- 18. It does not contain deoxidizse
- 19. ¼-inch.
- 20. To support the welccontrol heat for welding penetration, and permit faster welding speeds
- 21. Inert gas backup.
- 22. High-frequency current.
- 23. To prevent contamination and cracking of the weld.
- 24. 25 to 30 percent.

Do the unit review exercises before going to the next unit.

Unit Review Exercises

Note to Student: Consider all choices carefully, select **bee**tanswer to each question, and circle the corresponding letter. When you have completed all unit review exercises, transfer your answers to the FieldScoring Answer Sheet.

Do not return your answer sheet to the Air Force Career Development Academy (AFCDA).

- 58. (611) What characteristic of helium makes it undesirable welding thin material?
 - a. Low heat per ampere.
 - b. High heat per ampere.
 - c. Decreased penetration depth.
 - d. Presence of weld contaminates.
- 59. (611) Which welding process uses a consumable alloy with approximately the same chemical composition of the base metal?
 - a. Nonshielded gas.
 - b. Metallic inert gas.
 - c. Oxyacetylene gas.
 - d. Tungsten inert gas.
- 60. (612) What is the minimum number of amperes recommended for using acrowalted inert gas welding torch?
 - a. 100.
 - b. 150.
 - c. 200.
 - d. 250.
- 61. (612) What is indicated if the molten pool becomes cloudy or the tungsten electrode turns blue when cooling?
 - a. A leak in the hose or hose connection.
 - b. Wrong shielding gas being used.
 - c. Amperage setting is incorrect.
 - d. Polarity setting is incorrect.
- 62. (612) What do you use to make slight changes in the current **get** the tungsten inert gas (TIG) welding?
 - a. Foot control.
 - b. Current meter.
 - c. Fine adjustment knob.
 - d. Handoperated rheostat.
- 63. (613) For any given current setting, DCEP/DCRP requires an electrode approximately how many times largerin diameter than would be used for DCEN/DCSP.
 - a. 1.
 - b. 2.
 - c. 3.
 - d. 4.
- 64. (613) What machine setting produce tuagsterinert gas weld with deep penetration and a narrow bead?
 - a. Alternating current.
 - b. Direct current, reverse polarity.
 - c. Direct current, straight polarity
 - d. Alternating current, high frequency.

- 65. (613) What size opening does a number 6 cup have?
 - a. ¼inch.
 - b. ³/₁₆-inch.
 - c. ³/₈-inch.
 - d. ⁵/₁₆-inch.
- 66. (614) You must closely follow procedures to align, space, and tack weld stainless steel joints becausetainless steel in comparison to carbon steel has a metal expansion coefficient that is a. 30 percent less.
 - b. 60 percent less.
 - c. 60 percent greater.
 - d. 30 percent greater.
- 67. (614) Confining the arc to as small an area as possible and still allowing rptustion when welding austenitic stainless steel
 - a. decreases tack welds.
 - b. increases gas shielding.
 - c. increases electrode size.
 - d. decreases carbide precipitation.
- 68. (614) Tungsten inert gas welding edge jomeparation on stainless steel includes cleaning, deburring, and
 - a. polishing the edges.
 - b. rounding the edges.
 - c. fitting the edges evenly.
 - d. fitting one edge slightly higher.
- 69. (614) Approximately how many pints per minute should the water flow be for a -water detection torch?
 - a. 1.
 - b. 2.
 - c. 3.
 - d. 4.
- 70. (614) How do you prepare a stainless steel lap joint usinguting sterinert gas welding process?
 - a. V-groove the top edge only.
 - b. Square the edges and remove burrs.
 - c. Square top edge only and remove burrs.
 - d. V-groove the edges for better penetration.
- 71. (614) What color should a stainless steel joint have affeeding?
 - a. Dull silver or off white.
 - b. Flat black or light blue.
 - c. Dark blue or reddish purple.
 - d. Dark bronze or light purple.
- 72. (614) Whentungsten inert gas welding stainlessel tee joint or corner joint, the concentrated arc heat generated allows proper fusivith
 - a. no shielding gas.
 - b. no joint spacing.
 - c. extra joint spacing.
 - d. extra shielding gas.

- 73. (614) What do you do during the welding operation when youtuargesterinert gas welding stainless steel tee joints of unequal thickness?
 - a. Use a short arc.
 - b. Alternate the arc size.
 - c. Direct most of the heat on the thinner sheet.
 - d. Direct most of the heat on the thicker sheet.
- 74. (614) What filler rodtype isbestsuited to weldcarbon steelwith the tungsteinert gas process? a. Low carbon steel with deoxidizers.
 - b. High carbon steel with deoxidizers.
 - c. Low carbon steel without deoxidizers.
 - d. High carbon steel without deoxidizers.
- 75. (614) What is the arc adjustment distarfoem the arc to the plate when tungsineert gas welding aluminum?
 - a. ¹/₁₆- to ¹/₈-inch.
 - b. ¹/₈- to ³/₁₆-inch.
 - c. ³/₁₆- to ¹/₄ inch.
 - d. ¼-to ⁵/₁₆-inch.

2–26

Student Notes

Helium

Helium is a colorless, odorless, nontoxic, and tasteless inert gas. Much lighter than air, it is the second lightest of all gases. Helium is nonflammable and, like argonylitsder pressuresi2,000to 2,500 psi. The cylindes distinctive color markings are gray with a buff (light brown) top. The cylinder is considered empty when the pressure is reduced to 25 psi. Helium is also much cheaper than argon, but you use about orthird more helium because it is a lighter gas. Since helium is several times lighter, it does not settle down around the work as well as argon. The bead is wider with shallower penetration thait would be using argon, which is the opposite IG welding. Heliumis used primarily for special tasks and for welding nonferrous metals such as aluminum, magnesium, and copper.

NOTE: Make sure to follow all safety procedures for handling cylinders that you learned previously. If you are unsure, read the material safety data **MEDS** or ask your supervisor.

Gas shielded welding methods

MIG (fig. 3–1) uses a consumable ontinuously fed alloy wir¢commonly referred to as filler wire with approximately the same chemical composition as that of the metal being, wellded ungsten uses a norconsumable tungsten electrode. MIG is a fusive transfer of the work. The filler metal electrode carries produced by an electric arc between a metal electrode and the work. The filler metal electrode carries the current from the power supply unit to the base metal. An arc forms between the electrode and the base metal. The bead is produced by transfer the filler metal to the base metal he principles involve the arc, or heating source, and are the same as those for shielded metal arc welding. However, in the gasshielded process, an inert gas (helium or argon) flows the orifices in the torch head past the electrode to form a protective blanket over the weld area. The gas shield's primary purpose is to keep oxygen, nitrogen, and carbon elements that are present in the air from coming in contact with the molten metand contaminating the weld

The time that you take to properly set up your inert gas welding equipment allows you to correct problems before you begin welding. By setting up your equipment to your welding task, you can make high quality welds.

Figure 3–1. Metallic inert gas shielded process .

MIG welding advantages

MIG welding has become an accepted process for joining all types of metalsaiYeasily mechanize poduction welding by using/IG welding, thereby substantially reducing manufacturing costs. Generally, the same type of equipment and welding techniques apply to alwinetals welding with MIG.

There are several advantages to using MIG welding over other welding techniques. The avelup cle time is minimized due to lack of flux, slagnd very little spatteMIG welding is a faster welding process compared to all other options and is easily learned by workers who are proficient in other welding techniques. MIG is equally effective and more economical than TIG when welding thin stock. Gasshielded welding produces welds that are stronger, more ductile, and more corrosion-resistant than the welds made with shielded metal arc wellding protective gas shield envelops the weld and makes the joint without fluwhich eliminates flux-caused corrosion and cleaning.

616. Selecting and maintaining retallic inert gas welding equipment

In order to make high quality weld**sy** must know what MIG welding equipment is needed and how it functions before you using the MIG welding process. In this lesson, we distretes up with its function.

Power source

The most efficient current for MIG welding is direct current reverse pol@DCEP/DCRP or DC+) This contributes to better melting, deeper penetration, and excellent cleaning action. The machine we use for MIG welding is a constant potential machine whereas the machine we use for TIG and shielded metal arc welding is a constant rent machine. The constant rrent machine provides voltage that drops when the arc is struck and varies as the arc length changes. This is fine for stick and TIG welding, but with MIG welding, you've got a steady wire feed that requires steady voltage to maintain a uniform ar and bead. This need for steady voltage to development dhe constant potential machine. This machine provides steady voltage when you strike the arc and maintains a steady voltage as the arc length varies. Although other tantcurrent machine carebadapted to MIG welding, you obtain the best welding results the constant potential machines therefore constant current machines are not recommended bu can also use mactifier or motor generator. All machines used for MIG welding.

There are only two basic controls that you use for MIG welding. The first is the voltage rheostat; it is located on the welding machine and regulates the voltage. The second is the wire feed rheostat, which is also located on the machine and controls the speed of the wire feed motor.

Wire drive

The MIG welding wire drive mechanism controls the welding wire spleteds a rheostat which varies the speed t which the filler wire is supplied to the welding gun and normally contains the controls for the welding current flow and shielding gas. If you have a -watted gun, a control for the water supply will also be in the wire drive.

The wire drive can be located on the weld**ing**chine or at another location to allow more efficient equipment use. You must change **tolkers** in the wire drive or torch for different wire types and diameters. The rollers used include the "V" grooved, "U" grooved, "V" knurled, and "U" cogged. Refer to your machine's owner's manual to determine white the straightener is an accessory to the wire drive which is installed between the filler wire roll and the wire drive. The wire straightener removes the wire straightener as it comes for the wire roll. The wire straightener alsoprolongs the life of the wire drive and welding gun.

Welding gun

The welding gun is literally where everything comes together during MIG welding. The gun can be watercooled or aircooled. The aircooled gun is used on lightauge metals requiring less than 200 amps. The watercooled gun is designed for use on jobs requiring up to 200 amps or more. Both gun types are showin figure 3–2. Whether you use the straight or curved nozzledeppend on your access to the join You can changent nozzles for welding different materials. Some nozzle types include copper, ceramics, glass, and glazzated metals. The glass nozzle gives you a good view of the welding operation, but for allround use, the copper nozzle performs best.

Figure 3-2. MIG welding guns.

Squeezing the welding guiss trigger starts the electric current, the shielding gas flow, the wire drive, and the cooling water flow (r the watercooled gui). Since the welding wire is the power lead MIG welding, squeezing the trigger charge (scatuses it to become). Do not ouch the welding wire at the gun or the welding wire spool when you are handling the ground lead or are in contact with the grounded work. If the welding wire is hot and you come in contact with the ground lead or work and wire at the same time, you might get an electric shock.

You'll find that MIG welding guns are either push or pull guns. The pullhgus drive rollers in it to pull the wire from the wire drive. she if for small-diameter and soft wires such as aluminumling these types of wire prevents them from dingor kinking between the gun and the wire drive. The push gurhas the wire pushed to it by drive rollens the wire drive. Set for large diameter and hard wires such as arbon and stainless steel. These wires are less likely to be bent before they reach the gun, making the push gun more suitable. You assorbe push gun to weld with hard wires and where currents often exceed 250 amps. Both guns have a trigger switch that controls the wire feed and arc as well as the shielding gas. Wire feed, arc, and gas stop immediately when young trigger. Some equipment has a timer that permits the shielding glow for a predetermined time t protect the weld until it solidifies.

Hose

The hose usdefor MIG welding is very much like the TIG welding hose. It is a series of rubber or plastic hoses that carry the shielding gas, welding wire, and the supply and return water (if your gun is watercooled). The conduit (hose), which guides the electrode wire, is interchangeable to match the wire that you use. Astandard conduit is used for hard wire, such as steel, and alinged reonduit used for soft wire, like aluminum.

Shielding gas

Earlier, we discussed to shielding gasses that can be used for MIG weldianggon and helium. There's another inert shielding gassarbon dioxide-that can be used alone or mixed hother shielding gasses. When carbon dioxides used a shielding gas, the arc heat causes the carbon dioxide to separate into its two elements arbon monoxide and oxygen. Since oxygen is present in carbon dioxide, there is a problemince he purpose of a shielding gas is to keep certain elements such as oxygen away from the molten pool during welding. To overcome this problem, you must use a welding wire that has a deoxidizerit. This deoxidizer combines with the oxygen and keeps it out of your weld puddle. Some common deoxidizers wears manganese, silicon, aluminum, and titanium. Gas purity may also have considerable effect on welding, depending on the extent to which the metal is affected by contaminate tails less steel, as a rule, is not significantly affected by the small percetages of contaminates in the shielding gas. In contrast, nonferrous metals, such as aluminum, are sensitive to impurities youmust weld them with highurity inert gas. The commercially available rgon and helium gases average well over 99.95 percentity.

As a shielding gas, carbon dioxided carbon dioxide mixtures are good choice for industry and one you may want to consider. It is relatively inexpensive, possesses good penetration characteristics, and provides a good bead contour when welding carbon **Stake** sure that your welding wire has a deoxidizer in itwhen you use carbon dioxide

Gas-control equipment

We use a combination regulator and flow methods and show the same flow meter we use for TIG welding. Gas for the should be approximately 35 cubic feet per hour (cfh) for most welding conditions. The correct settings are governed by the type and thickness of the metal, position of the joint, the kind of shielding gas used, diameter of the electrode, and the type of joint. With the proper gas flow, the arc prodsaerapidly crackling or sizzlingound. Inadequate gas flow makes the arc produce a popping sound with sultant weld discoloration, porosity, and spatter. This may also occur with high weld speed corffr unusually drafty or windy conditions in the weld area. You must place the gas nozzle no further than 2 inches from the work. Too much spacet meduce effectiveness of the gas shield. Too little space may result in excessive pattle, which collects on the nozzle and shortens its life.

Figure 3 –3. Argon gas flow regulator /meter.

Protective equipment

When you are MIG welding, wear full protective clothing and gloves to keep hot metal spatter from burning you. The arc produced by MIG welding is more intense than the arc produced by TIG welding. To protect your eyes while MIG welding, use a lens in your welding **that** is two to four shades darker than that you use for TIG welding

Equipment maintenance

The maintenance that you do on MIG welding machines is the same as the welding machine maintenance we discussed TdG welding. You can cleamle welding leads and hoses by reversing the cooling water flow through the hoses and by using compressed blow dust and dirt out of the welding wire lead. Repair or replace damaged hoses to prevent gas and water leakage and possible shot circuits in the welding wire.

Check all electrical circuit connections and tighten any that are loose. Checking then for any loose nuts and bolts and tighten any that are loose.

Welding gun maintenance includes visually inspecting the gun,,hausesablesCleanany slag from the gun and replacthe welding tip and gun nozzle when they become worn or damaged. Check the gun for broken or cracked insulation and parts. Check the hoses and cables for cuts and frays. Inspectthe flow meter for cracks or leaks and replace itisf intot working properly or if you find its damaged. For more extensive repairs for procedures in your gun manufacturer's handbook. If you cannot make the repairs, contact your supervisor for contract repair or replacement.

NOTE: Disconnect the power to the welding machine before performingnamytenance procedures.

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

615. Metallic inert gaswelding principles

- 1. Explain the terminert gas
- 2. What is a significant difference between TIG and MIG welding?
- 3. How does inert gas prevent weld contamination?
- 4. How do welds produced by **gab**ielded welding compare with those made with ordinary metal arc welding?

616. Selecting and maintaining retallic inert gas welding equipment

- 1. What type of power source you use foMIG welding?
- 2. What piece of MIG welding equipment controls the wire speed?
- 3. What occurs when you squeeze the trigger on the MIG welding gun?
- 4. What MIG welding shielding gas requiresleoxidizer in the filler wire
- 5. If a number 10 leniss safe for TIG welding, what shade widuyou use for MIG welding?
3-2. Application procedures

This section covers the techniques used in MIG welding. The MIG weldinging increasingly used for maintenance and repair applications. If you are proficient in shielded metallic arc or TIGgweldin then learning the MIG welding process should be easy for you. The MIG welding process allows you to complete a joint without stopping, there were coming such problems as, slag inclusions, cold laps, poor penetration, crater cracking, and poor fusionthe first lesson we'll concentrate on job preparation and follow in the second lesson with the actual MIG welding procedures.

617. Job preparation

The MIG welding principles involve welding metal together with an electrical arc, a continuous consumable welding wire, a wiredispensing gun, and shielding. Before you begin welding with the MIG outfit, you need to know how to apply these principles. First, we give you information about welding currentfiller-wire selection and gun setup; and then we cthree different metal transfers you can use when MIG welding.

Welding current

The welding current for almost all MIG welding should be DCEP/DCRP (or DCgi)ves better penetration than DCEN/DCSP (or DCgind you can use to weld all metalsFigure 3–4shows the bead contour obtained with DCEP/DCRP and DCEN/DCSP. We sometimes use DCEN/DCSP when minimum penetration is required. When you compare these bead contours with ffigsed6–5, you can see that they are opposite.

Figure 3-4. MIG weld contour comparison.



The difference between TIG and MIG welding beads is the difference in metal transfer. When you are MIG welding with DCEP/DCRR or DC+), the metal transfers from the weld wire to the work in a fine spray, which penetrates easily into the work. When you are MIG welding with DCEN/(DCSP DC-), the metal transfer is globular, which results in poor penetratell G welding with AC current gives you very poor results because the current flow direction is constantly changing. This change causes the weld wire to burn unequally, resulting in an erratio accan use avide range of current values with each wirdiameterthis allows various thicknesses of metal to be welded without having to change the wire. It takes some the correct specifications.

Welding-wire selection and gun setup

The welding wire and gun are unique MIG welding features. Learning how to select the wire and use it in the gun is a critical step for you to understand. Let's start with the welding wire.

Welding wire

In MIG welding, the welding wire serves the same purpose as a welding rod does in oxyacetylene welding. There are many welding wire types and sizes available for specific purposes. They are purchased in spools to provide a continuous feed of filler metal. You must make sure that the wir compatible with the base metal for fusion to take place. Fusion must take place to have a proper weld. Base your election of wire size (diameter) on the type of metal, metal thickness and the position in which you are to due welding. There are these available that you can use determine the type of filler wire needed. Vertical and overhead welding require smaller diameter wires. Basic wire diameters are 0.0200.030, and 0.035nch. These are best used for welding thin metalewofand mediumcarbon stee We normally use 0.045and¹/₁₆ inch diameter wires on medium thickness metals and/₈- inch diameter wires on thicker metalter sure that the wire feed rollers are the size required for a particular wire. For ample: the .030-inch wire require .030-inch rollers (wire feed rollers are the size required for a particular wire. For ample: the .030-inch wire require .030-inch rollers (wire feed rollers are the size required for a particular wire. For ample: the .030-inch wire require .030-inch rollers (wire feed rollers are the size stamped on the size). Check the gun for the correct size nozzle.

Solid welding wires

Filler wires have dentifying numbers assigned by the American Welding Society (AWIS ure 3-6 lists some lectrodes along with their recommended usage. The "E" in the number indicates that it is an electrode. The first two digits of the mild steel electrodes indicate their tensile strength in thousands of psi, and the "S" indicates a solid bare Whrefinal numbers or letters specify the chemical composition. The numbers for the aluminum and stainless steel wires indicate the composition; use the top base metals of similar composition

Figure 3–6. MIG welding electrodes.

Flux-cored welding wire

Flux-cored arc welding wire is a MIG welding method in which you use a hollow wire electrode with a flux material core. Fluxcored welding forms a coating over the completed weld. Consequently, you must do more post weld cleaning, especially when you weld multiplees. Likeny arc welding wire, these wires must be compatible with the base metal. The twoofhed welding wire types described in the following table.

| Flux -cored Welding Wire | Requirements/Example | | | | |
|-----------------------------|--|--|--|--|--|
| Self-shielded | x Does not require an inert gas to protect the molten pool. | | | | |
| | x Generally used for applications that otherwise would be done by the shielded metal arc welding method. | | | | |
| | Example: Welding mild steel. | | | | |
| Gas-shielded | x Requires a shielding gas. | | | | |
| | x Generally used for applications that would otherwise be done by MIG welding with a solid wire. | | | | |
| | x Provides a higher quality weld than does self-shielded. | | | | |
| | Example. Welding stamless steel of auminum. | | | | |

Wire extension

The term extension for most welding wire extends beyond the welding gun nozzle. The recommended extension for most welding operation stips 3/4 inch(fig. 3–7) As wire extension increases, your ability to control the wire decreases. If the wire extension is too long, there do not be preheat, become soft, and whip around. If wire extensions too short the wire tends to fuse to the welding tip, which shortes tip life. To attain the correct extension greep the welding tip even with or slightly recessed inside the welding gun nozzle. Do not let the welding tip extend beyond the gun nozzle.

Figure 3–7. Welding wire extension.

Metal transfer

In an earlier lesson, we discussed wantages of direct current reverse **pip**/aYou'll recall that penetration is greater and there is also a good surface ing action on metals that have heavy surface oxides, such as aluminum. For these real Solits, DCRP(DC+) helps transfer metal the best when you are MIG welding. There awo metal transfer methods that was in MIG welding: spray arc transfer and shortcuiting transfer.

NOTE: During all welding, you must protect the leads of the welding machine from sparks or damage. Make sure **te**move any flammable material from the leads of the welding area.

Spray arc transfer

The spray arc transfer is very good for welding on thick metathis metal transfer (fig-8), you use high amperage with an argon shielding gas. Argon has a pinching affect on small molten metal pieces, and with high current, the small molten particles pass from the electrode (welding wire) to the work with a spraying effect

Figure 3–8. Spray arc transfer.

Short-circuiting transfer

The shortcircuiting transfeirs very good for welding thin materialst gives you better puddle control than the spray arc transfer. This feature makes **cincutt** transfer better for welding in the flat position.

The shortcircuiting transfer (fig. 3–9) uses currented w200 amps and welding witess than 045inch in diameter to keep the weld puddles more controllable. In this metal transfer, the molten metal does not break off the weld wire before ontacts the weld puddle. This forms a continuous path (fig. 3–9, viewB) for the weld current to follow, which shortcuits the arc. As the molten metal separates from the weld wire (fig. 3–9, view C), the arc starts again. This is bout in and arc restarting occurs between 20 and 200 times per second, dependiaghinens ettings. The starting and stopping of the arc gives you a cooler weld puddle, making this metal transfer the most suitable for welding thin metal.

Figure 3–9. Short -circuiting transfer.

618. MIG welding procedures

There are certain welding practices that you must follow to make good welds with the MIG welding process. In this lesson, we explain the techniques that you can use to weld various metals.

Before you begin welding, follow the stepsteid belowfor setting up MIG welding equipment.

| Setting Up MIG Welding Equipment | | | | | |
|----------------------------------|--|--|--|--|--|
| Step | Action | | | | |
| 1 | Select and install the filler wire. | | | | |
| 2 | 2 Select the shielding gas according to the type of material to be welded. | | | | |

| Setting Up MIG Welding Equipment | | | | | |
|----------------------------------|---|--|--|--|--|
| Step | Action | | | | |
| 3 | Set the machine to the correct voltage according to the material's thickness. | | | | |
| 4 | Set the wire feed speed. | | | | |
| 5 | Set the flow meter to the correct cfh. | | | | |

Welding techniques

The techniques that you use are partially determined by the way that you prepare the joints for welding. You can prepare butt, edge, tee, and lap joints the same as you do in other weldiology types metals that are a prepare butt, edge, tee, and lap joints the same as you do in other weldiology types metals that are a prepare butt, edge, tee, and lap joints the same as you do in other weldiology types metals that are a prepare butt, edge, tee, and lap joints the same as you do in other weldiology types metals that are a prepare butt, edge, tee, and lap joints the same as you do in other weldiology types metals that are are are are and lap joints the same as you do in other weldiology types metals that are as prepared by the transferred preparation is required, but on the transferred prepared to the area and prepared to the transferred prepared to the prepared prepared to the transferred prepared to the prepared prepared to the transferred prepared to the transferred prepared to the prepared to the prepared to the prepared to the prepared prepared to the prepared prepared to the pre

Flat butt and edge joints

When you are welding butt and edge jointemate the gun on the joint to begin welding the butt joint in the flat position, you must start by depositing the root pass; use a smooth, steady drag motion. You can use alight weave interad of the drag on otlet the wire leave the leading edge of the puddle. Maintain a work angle of 90° and drag travel angle of 5° to 15% lake your penetration for the root pass slush to slightly convex. The finished weld should equal leg dimension and fuse smoothly into both plates with no overlap or under the surface of the plates and a travel angle of 5°15° drag. Weld reinforcement should best fluto slightly convex to the surface of the base metal. The finished weld should have equal leg dimension and should fuse smoothly into both plates with no overlap dimension and should fuse smoothly into both plates with no well best fluto slightly convex to the surface of the base metal. The finished weld should have equal leg dimension and should fuse smoothly into both plates with no overlap dimension and should fuse smoothly into both plates with no overlap dimension and should fuse smoothly into both plates with no overlap dimension and should fuse smoothly into both plates with no overlap dimension and should fuse smoothly into both plates with no overlap or undercut.

If you use the forehand technique (push)ngle the gun 5° to 10° in the weld avel direction If you use the backhand technique (dragg)glethe gun 5° to 15° awafyom the welds travel direction. The bead penetration is greater with the backhand technique than the forehand technique also gives welder a better molten metal puddle view, which usually results in a better weld. For these reasons, the backhand technique is preferred.

Flat lap and tee joints

The lap and tee joints are fillet weldSenter the gun angle on the joint anglen inclue it 5° to 10° in the weld travel direction when using these handtechnique. If you are using the backhand technique, anglethe gun 5° to 15° away from the weldravel direction. It may be necessary or advantageous toocline the material 10° to 20° when welding in the flat position help flatten the bead and increase the travel spectrum welding flatposition lap joints, you must use a slight weave motion, with a work anglef 45° to the joint and a travel angle of 5° to 15° drag. Travel smoothed y evenly to ensure complete and proper penetration into both pWatks.your lead face flat to slightly convex and the finished weld should have equal leg dimension and no overlap or undercut.

When welding the flat position joint, you must deposite first pass using a slight weaving motion. Maintain a 45° work angle and smoothly maintain a 5° to 15° drag travel angle. Ensure the weld bead has equal leg dimensions. The second pass work is for the first pass work is for the drag travel angle is 5° to 15°. Make the second pass overlap the first pass 1/2 to 1/2. On the hird pass make you work angle 35° and the drag travel angle 5° to 15°. Make the drag travel angle 5° to 15°. Make third pass overlap the second pass by 1/3 to 1/2, slightly convex, and have equal leg dimension into both plates and no overlap or undercut.

Horizontal butt joint

Follow the procedure you learned earlier for setting up the machine and preparing the metal to be welded. For the root and cover passible with the same procedures as welding in the flat position Deposit the weld using a steady weaving motion. Make sure to pause at the tip of each weave to help fight the effects of gravity. Do not the wire leave the leading edge of the puddle. You must maintain a work angle of 80° to 85° and a drag traveleant of 5° to 15°. Make your potentiation for the finished weld pass flush to slightly convex and make sure is susceptibly intoboth plates with no overlap or undercut.

Horizontal lapand teejoints

Use a slight weaving motion pausing at the tip of each weak anglenust be 45 to the joint and the travel drag angle to 15°. Travel smoothly and evenly to ensure complete and proper penetration into both plates. Make your able face flat to slightly convex and have equal leg dimension, with smooth fusion into the plates with no overlap or undercut. When welding a horizontal tjoint, you must deposit the first pass using a slight weaving motion, pausing at the top of each weave. Maintain a 45° work angle of 5° to 15° to 15° the drag travel angle Ensure the well bead has equal legdimensions. Make the second passork angle 55° and the drag travel angle to 15°. Have the second pass overlap the first plasts 1⁄2. The third pass work angle 35° and the drag travel angle travel angle 5° to 15°. Have the third pass our lap the second pass to 1⁄2, and have equal leg dimensions with smooth fusion into both plates with no overlap or undercut.

Vertical down butt joint

Deposit the root pass using a steady drag motion. Stay on the leading edge of the puddle. You must maintain awork angleof 90°, with a drag travel anglef 10° to 20°. Root penetration must be flush to the underside of the plate's surface to slightly convex. Make see finished weldhas equal leg dimensions and smooth fusion into both plateish no overlap or undercut. For the cover pass, the work angleis 90° to the surface of the plates, with a drag travel aogle0° to 20°. Use a Z weave pattern to evenly deposit the cover pass onto both plates. Keep the wire located on the leading edge of the puddle as you move down the joint. Be sheef in ished weldhas equal leg dimensions with smooth fusion into both plates with no overlap or undercut.

Vertical down lap and tee joints

Use a downward Z weaving motion to maintain even fusion into both plate a ork anglemust be 45° to the joint, with a drag travel angule 10° to 20° Make sure he finished weld has equal leg dimensions and smooth fusion into both plates with no overlap or undercut.

When welding a-joint, you must use a downward Z weavimption to maintain even fusion into both plates. Maintain a 45% ork angleand a 10° to 20° drag travel ang Ensure the weld bead has equal dimensions for the second pass, the work anglest be 45° to the joint, with a 10° to 20° drag travel angle Usea wider weaving motion than on the previous pass. Make the first hed weld has equal leg dimensions with smooth fusion into both plates, with no overlap or undercut.

Vertical up butt joint

When welding the vertical up butt joint, you must move evenly up the joint with no side to side motion. Stay on the leading edge of the puddle, while maintaining a work of 100°. Travel at a speed that penetrates joint completely and produce finished bead that is slightbonvex to the surface of the plates. Make sture finished weld has equal leg dimensionerand smooth fusion into both plates with no overlap or undercut.

Vertical up lap and tee joints

Weld the vertical up lap joint upward using a slight weavinogion to maintain even fusion into both plates. The work anglemust be 45° to the joint and maintain a push travel angle to 10°. Make

sure the finished weldhas equal leg dimensions and smooth fusion into both plates with no overlap or undercut.

When welding the tjoint, you must start at the bottom of the joint and weld upward using a slight weaving motion. The work anglemust be 45°, with a 5° to 10° push travel angle ep the wire in the leading edge of the puddle. For the second, placework anglemust be 45° to the joint, with a 5° to 10° push travel angle. For the second, placework anglemust be 45° to the joint, with a 5° to 10° push travel angle. The finished must be travel angle of the motion, with a 5° to the previous pass. The finished must have equal leg dimensions, with smooth fusion into both plates with no overlap or undercut.

Overhead butt joint

Follow the procedure we described earlie for setting up the machine, preparing the metal, and starting the arc. Deposit the weld pass using a smooth, steady drag motion 1 and the other leave the leading edge of the puddle. You must maintain a work and smooth a drag travel angle f 5° to 10°. The finished weld must have equal dimensions and smooth fusion induct h plates with no overlap or undercut.

Overhead lap and tee joints

When welding the overhead lap joint, use a slight weaving motion with a work of 45° to the joint and a 5° to 10° drag travel angle ravel smoothly and evenly to ensure complete and proper penetration into both plates. The finished weld must have equal leg dimensions, with smooth fusion into both plates with no overlap undercut. Accomplishte to the total the first passing a slight weaving motion, work angle 45°, and a 5° to 10° drag travel angle must have equal leg dimensions. We weld bead has equalleg dimensions. Make the second passork angle 55°, with a 5° to 10° drag travel angle Make the third pass overlap the second passork angle 55°, with a 5° to 10° drag travel angle must have equal leg dimensions and other the third pass work angle 55°.

Beginning to weld

To begin welding, squeeze the trigger to start the arc. Keep the gun at the proper travel and work angles. If the arc is not started properly, the filler wire may **stdick** workor freeze to the tip of the gun (shut off the machine and free the wire if this happens). Use a pulling or pushing motion. Keep the wire at the leading edge of the puddle and keep the wire centered in the middle of the gas pattern to insure adequate shifting. You can use **s**light weaving motion tensure complete penetration. Release the trigger wheryou reach the end of the weld, this st**tipes** wire feed and welding current. Keep the gun over the weld until the gas stops flowing to protect the pud**idle soni**difies. When you must stop a weld midway through the joint, make sure to leave the crater unfilled. To restart, position the wire approximately ½ inch in front of the crater of the existing weld. Pull the trigger to restart the arc As you pull he trigger, move back toward the crater. Trace the outline of the crater with the wire. Resume the weaving motion and travel speed.

Welding carbon steel, stainless steel, and aluminum

The techniques that you use to weld different metals include metabtrans gas shielding. Let's see how you can use them to MIG weld.

Carbon steel

When welding carbon steel, you'll find the spray arc transfer is the best for heavy material and the short-circuiting transfer is the best for thin material. Argon is the **predeshielding** gas for either transfer method, but carbon dioxide also gives good results

When welding in the horizontal, overhead, or vertical position, you need to control your molten metal puddle very carefully. You can do this by using the shortuiting transfer to keep the weld cool. Another way to control the puddle size is by changing your travel speed. For a small puddle, make your travel speed fast. For a large puddle, make type speed slow.

Welding stainless steel by the spray arc transfer method with an argon shielding gas gives you the best results. Using a different shielding gas lowers the corrosion resistance in your weld area.

The welding techniques you used on carbon steel joints also apply to stainless steehjeints forehandtechnique is recommended for welding stainless steel. This gives you a little less penetration, but keeps the base metal cooler. By keeping the base metal cooler, you can keep corrosion resistance loss to a minimum.

When welding in the overhead, horizontal, or vertical position, you can control your bead by increasing or decreasing weld travel speed. You carhessehort circuiting transfer method when welding thin materials in the flat position to give maximum puddle control.

Aluminum

Welding aluminum with the MIG process requires you to use lower amperage settings than you use on carbon or stainless steels. The lower amperage settings are required due to the molten aluminum's flow characteristics. Argon is the best shielding gasstewhen welding aluminum. The spray arc transfer method is best for welding thick aluminum in thepftastition. The shortcircuiting transfer method is best for welding thin aluminum in the horizontal, vertical, and overhead position where the molten metal puddle control is a factor

The gun angles for welding aluminum are the same as **thoosa** room and stainless ste**E** he following table is a guideline for work angle, travel angle, and drag/weave for flat, horizontal, vertical down, vertical up, and overhead welding positions

| | Flat | | Horizontal | | | Vertical down | | | Vertical up | | | |
|--------|-------------------------|-------|-----------------------|--------|-----------------------|---------------|--------|-----------------------|-------------|------|--------------|-----|
| | Butt | Lap | Т | Butt | Lap | Т | Butt | Lap | Т | Butt | Lap | Т |
| Work | Root | | (1) 45° | | 45° | (1) 45° | Root | | (1) | | (1) | (1) |
| Angle | 90° | 45° | (2) 55° | 80-85° | | (2) 55° | 90° | 45° | 45° | 90° | 45° | 45° |
| | Cover | r | (3) 35° | | | (3) 35° | Cover | | (2) | | (2) | (2) |
| Travel | 5°-15° | | 5°-15° | | 10°-20° | | 5°-10° | | | | | |
| Angle | Drag | | Drag | | Drag | | Push | | | | | |
| | (all three positions) | | (all three positions) | | (all three positions) | | | (all three positions) | | | | |
| Drag/ | Slight weave | | Slight weave | | Drag Downward | | | Push slight weave | | | | |
| Weave | (all three positions) | | (all three positions) | | z weave | | | slight weave | | | | |
| | | | | | | | : | z weave | | | slight weave | 9 |
| | Overhead | | | | | | | | | | | |
| | Butt | Lap | Т | | | | | | | | | |
| Work | | | (1) | | | | | | | | | |
| Angle | 45° | | | | | | | | | | | |
| | 90° | 45° | (2) 50° | | | | | | | | | |
| | 40° | | (3) | | | | | | | | | |
| Travel | | 5°-10 |)° | | | | | | | | | |
| Angle | Drag | | | | | | | | | | | |
| | (all three positions) | | | | | | | | | | | |
| Drag/ | Slight weave | | | | | | | | | | | |
| Weave | e (all three positions) | | | | | | | | | | | |
| | | | | | | | | | | | | |

Common MIG welding defects

You must controMIG welding properly to produce consistently high quality welds'. **Lei**scuss some of the common defects you may encounter while MIG welding.

| Common MIG Welding Defects | | | | | |
|---|--|--|--|--|--|
| Defect | Description | | | | |
| Cold lap (overlap) | Cold lap occurs when the arc does not melt the base metal sufficiently and the molten puddle flows onto the un-melted base metal. Often this happens when the puddle is allowed to become too large. | | | | |
| | You must keep the arc at the leading edge of the puddle for proper fusion. | | | | |
| Surface porosity | Surface porosity is caused by having the shielding gas set too high or too low. | | | | |
| | If the gas is too low, the air in the arc area is not fully displaced. | | | | |
| | If the gas is set too high, air turbulence is generated; this prevents complete shielding. Occasionally this occurs when you weld in a windy area. | | | | |
| Crater porosity and cracks | The chief cause is from removing the gun and shielding gas before the puddle solidifies. | | | | |
| | The other possible cause is moisture in the gas, dirt, rust, oil or paint on the base metal, or excessive tip-to-work distance. | | | | |
| Insufficient penetration | Insufficient penetration is caused by low heat input in the weld are. | | | | |
| | It can also be caused by failing to keep the arc properly located on the leading edge of the puddle. | | | | |
| Excessive penetration (burn through) | Excessive penetration can be caused by having excessive heat in the weld zone, wire speed too fast, travel speed too slow, or improper joint design (such as the root opening being too wide). | | | | |
| Whiskers | Whiskers are short lengths of wire sticking out through the joint. | | | | |
| | These can be caused by pushing the wire past the leading edge of the puddle. | | | | |
| | To prevent whiskers, you must reduce the travel speed, increase the tip-to- work distance, or reduce the wire feed speed. | | | | |

Shut down procedures

To shut down the welding machine unise the sequence in the following table.

| Welding Un it Shut Down Procedures | | | | |
|------------------------------------|--|--|--|--|
| Step | Action | | | |
| 1 | Turn off the wire speed control. | | | |
| 2 | Shut off the gas flow at the cylinders. | | | |
| 3 | Squeeze the trigger on the welding gun to purge the gas lines. | | | |
| 4 | Hang up the welding gun in its proper location. | | | |
| 5 | Shut off the welding machine. | | | |

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

617. Job preparation

- 1. Which welding current would you use for almost all MIG welding?
- 2. What do the first two digits of a carbon steel AWS electrode number indicate?
- 3. What does the AWS number for stainless steel and aluminum welding wire indicate?
- 4. What is therecommender dvelding wire extension for MIG welding?
- 5. When you are MIG welding hast occurs if the welding wire extension ous tlong?
- 6. Which metal transfer has tiny molten metal pieces that pass from the welding wire to the work?
- 7. Which metal transfer has the arc start and stop 20 to 200 times per second?

618. MIG welding procedures

- 1. What difference in joint setup is required for MIG welding as compared to other welding types?
- 2. How do you align the welding gun with the joint when u are welding flat butt and edge joints
- 3. How do you align the elding gun with the joint when you are welding flat lap and tee joints
- 4. What two shielding gases give good results when welding carbon steels?
- 5. When you weld stainless steehattwo factors could cause a corrosion resistance loss?
- 6. What is thebest metal transfer to use hen welding aluminum in the overhead position?

Answers to Self -Test Questions

615

- 1. A chemically inactive gas that will not combine with any other element.
- 2. TIG uses a nonconsumable tungsten electrode, while MIG uses a consumable alloy wire with approximately the same composition as that of the table being welded.
- 3. It prevents the oxygen, nitrogen, and carbon elements that are present in the air from coming in contact with the molten metal in your weld.
- 4. They're stronger, more ductile, and more corrosion resistant.

616

- 1. A constantpotential welding machine.
- 2. The wire drive mechanism.
- 3. The electric current starts, the flow of shielding gas starts, the wire drive starts, and, if the gun is water cooled, the cooling water starts flowing.
- 4. Carbon dioxide.
- 5. A number 12 or 14 shade lens (24tohades darker).

617

- 1. DCEP/DCRP (DC+).
- 2. Tensile strength in thousands of psi.
- 3. The welding wire composition.
- 4. $\frac{3}{8}$ to $\frac{3}{4}$ inch.
- 5. The wire preheats, becomes soft, and whips around.
- 6. Spray arc transfer.
- 7. Short-circuiting transfer.

618

- 1. The joint setup is the same.
- 2. Centerthe gun on the jointvith a work angle of 90 and a drag travel angle of of to 15 g
- 3. Center the gun angle on the joint and anighter the veld direction for the forehand technique and 5 the travel direction for the weld travel direction for the backhand technique.
- 4. Argon and carbon dioxide.
- 5. (1) Using a shielding gas other than argon.
 - (2) Overheating the base metal.
- 6. Short-circuiting transfer.

Do the unit review exercises before going to the next unit.

Unit Rev iew Exercises

Note to Student: Consider all choices carefully, select **bes**tanswer to each question, and circle the corresponding letter. When you have completed all unit review exercises, transfer your answers to the FieldScoring Answer Sheet.

Do not return your answer sheet to the Air Force Career Development Academy (AFCDA).

76. (615) What characteristic of heliumakes it undesirable for welding thimaterial?

- a. Low heat per ampere.
- b. High heat per ampere.
- c. Weld contaminates present.
- d. Decrease penetration depth.
- 77. (615) What primarypurpose doessert gasserve in the gashielded welding process?
 - a. Cools the weld and fluxed area.
 - b. Allows for higher current settings.
 - c. Keeps contaminates out of the weld.
 - d. Provides better fusion and penetration.
- 78. (616) The watercooled metallic inert gas welding gun is designed for use on jobs requiring up to a. 50 to 100 amps.
 - b. 100 to 150 amps.
 - c. 150to 200amps.
 - d. 200 amps or more.
- 79. (616) What is the difference in the welding lens requirentiativeen metallic inert gas (MIG) and tungsten inert gas (TIG)?
 - a. TIGs is 1 to 2 shades lighter.
 - b. TIG's is2 to4 shades darker.
 - c. MIG's is 1to 2 shades lighter.
 - d. MIG's is 2to 4 shades darker.
- 80. (617) Which welding current can be used for almast MIG welding, gives better penetration, and can be used to weld all metals?
 - a. Direct current reverse polarity/DCEP (DC+).
 - b. Direct current straight polarity/DCEN (D)C
 - c. Alternating current, high frequency (ACHF).
 - d. Alternating current.
- 81. (617) When you are welding with metallineert gas, what is the result of having a wire extension that is too shoft
 - a. The arc will not start.
 - b. The arc length is doubled.
 - c. The welding wire whips around.
 - d. The welding wire fuses to the welding tip.
- 82. (618) When you weld filletoints with themetallicinert gas process, how do you position the gun on thejoint?
 - a. Centered on the joint.
 - b. Angled at 45 degrees.
 - c. Pointed toward the upper piece.
 - d. Pointed toward the lower piece.

- 83. (618) When you do mettic inert gas welding, which bead welding technigues the best penetration?
 - a. Backhand.
 - b. Forehand.
 - c. Overhand.
 - d. Underhand.

Student Notes

Cooling water pumps are required for headury cutting. The pumps circulate water through the torch to prevendamage from the extremely high plasma arc temperatures.

Setting up for plasma arc cutting is simpSeart by making lines on the metal where you want to cut. You cannot alter or adjust all of the electronic contools most machines. However, you usually have control and can adjust the work for electric current and gasThese adjustments on with gas selection are the variables that you set to make smooth cuts. To start cutting, hold the itorch 1/4 above the base metal surface at the pointer you want to begin the current press the switch on the torchto establish a high frequency pilot arc white kes a path for the plana to follow. To stop cutting, simply release the torch switch and the current and plasma flow stop.

General machine maintenance

The general maintenance for plasma arc cutting machines is similar to what we covered for SMAW, TIG, and MIGwelding machines_like the othermachines discussed lean the plasma arc one as soon as you are done using it. While cleaning it, check ivear and possible damage. Repair or replace damaged parts. Use compressed air to blow dust and dirt out of the welding machine. Check items like electrical cords and connections, hoses, machine gauges, machine oper,abiocoanse, the cutting torchCheck all electrical circuit connections and tighten any that are loose. Check all equipment for loose nuts and bolts and tighten any that are loose. For specific maintenance and schedules, follow the manufacturer's guide.

NOTE: Disconnect the power to e welding machine before you perform any maintenance procedures.

Protective equipment

When you are plasma arc cuttinger the same personal protective equipment you do for StMAW keep hot metal spatter from burning you, thateather jacket, leg cerrs, gloves, and hoodhe recommended lens shade number for plasma arc cutting is based on cutting current amperess. For u 300 ampsuse a #9 lensFor 300 -400 ampsuse a #12 lens. Fe00 800 ampsuse a #14 lens. Wear earmuffs or earplugsince this is a very noisy process.

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

619. Plasma arc cutting principles

- 1. Which cutting gases obtain the best resultsenv cutting aluminum or staters steel?
- 2. Name the two arc cutting processes.
- 3. What are the two operator adjustments you can make on most plasma arc cutting machines before cutting?
- 4. What lens shade number do you use warc cutting using 304090 amperes?

620. Arc cutting procedures

You must know what arc cutting equipment you needed how it functions before you use the arc cutting process. In this lesson, we explain the electric arc cutting processes of shielded metal arc, carbon arc, and oxygen arc, and cover the equipment needed along with its function. Let us begin with shielded metal arc cutting.

Shielded metal arc cutting

We do shielded metal arc cutting using the same equipment we use/fAtV. The shielded metal arc cutting (SMAC) process cuts metasing a thickly covered electrode with a slow burning cover Once an arc is generated be coating allows the electrode to be inserted into the molten puddle of the base metalmaking contact, and staining the cut without being shortircuited. This electrode's coating also stabilizes and intensifies the arc's action. The force of the arc ladowelten metal away, creating a gouge or kerf. Figure 14 illustrates a groove cut using shielded netal arc process.



The first step in the SMAC process to determine the thickness and type of metal to be cut. This information determines the correct electrode and welding machine adjustment

Some manufacture sell special SMAC electrodesowever, those electrodesore not always available. If a SMAC electrode is not valuable, consider a common welding electrode with deep penetrating qualities, such as 16010 or E 6011. The deep penetrating qualities were the arc to dig deep into the base metal and melt it away instead of filling it in. The state effect rode should be slightly smaller in diameter than the diameter use to whet the same thickness of metal.

NOTE: If you use regular mild steel SMAW electrodes for cutting, they **autil** a little longer if you soak themin water for a maximum of 0 minutes before ou use them

Regardless of the type of electrode used as set welding machine to Direct Current Straight Polarity (DCEN/DCSP, DC-). DCSP puts more heat on the base metal and less on the electrode. Increase the amperage a point that generate eat that is hot enough to produce a large unmanageable molten metal pool.

Use standard electrode holders for SMAC. Aftemping the electrode in the electric holder, momentarily touch the electrode to the base metah, Total the electrode a short distance away to

create a gap that causes a high resistance to theretake current. As electricity jumps the gap, it forms an electrical and atproduces the intense heat required to melt the base metal.

Guide the electrode at 7a0° angle to the metal surface and tip it backward at the top to ensure the molten metals blown forward from the kerf.

Figure 4 2. Shielded metal arc cutting.

The arc length varies sepending on the thickness f metal. For thin metals, hold an arc slightly shorter than the electrode diameter. Move the electrode down the line of cut with no up and down motion. For thick metals, move the electrode up and down with a sawing motion as youtrdown the line of cut. When you bring the electrode up and forward, it preheats the metal. When yout pesh electrode backdown, it pushes the molten metal out of the keme Electrode's movement speeds up the joband reduces heat requirements. Figure 4 lustrates ctuing with an electrode. Notice how the arc stream and gas jet blow the melted metal away.

NOTE: Remember the law of gravityHOT LIQUID falls; make sure there is nothing underyour cutting area

Carbon arc cutting

Carbon arc cutting is a process of cuttimetals with the heat of an arc between a carbon electrode and the workThe carbon electrode is used to melt the metal progressively by maintaining a steady arc length and a uniform cutting speeitheDt current straight polarity (DCEN/DCSP, DQs used because it develops a higher heat at the base metal (the positive pole). Direct current also permits a higher cutting rate and easier arc control than alternating currentirLosseled carbon electrode holders for currents up to00 amperes. West-cooled electrode holders are desirable for currents over 300 amperes.

Air carbon arc cutting

Air carbon arc cuttings another carbon electrode cutting process that is assisted with compressed air. An air jet nozzle in the electrode holder blows the molten metal out from the artigarda3).

Figure 4 3. Air carbon arc cutting.

A carbon/air carbon arc isuitable for both ferrous and not metal. However, it does not produce a cut of particularlyogd appearance. The electrodes are either carbon or graphite and are ground to a very sharp point. They are ground so that the length of the taper is equainteso the electrode diameter. The pointed end reduces arc wandering and produces lessuter affice cuts are still not satisfactory for welding and require ther preparation by grinding or chiseling.

Oxygen arccutting

Oxygenarc cutting is a progressive process where use tubular electrodin conjunction with a special oxygen arcutting torch. The tubular metal electrodination in the arc and erves as a conduit through which oxygen flow is to the cut. In this process, ystrike the arc on the base metal then press the oxygen lever on the torch. In this probest and is blown away The hollow electrode is consumed during this process. You can use both direct and alternating current welding machines

General machine maintenance

The general maintenance for shielded metal arc, carbon arc, and oxygen arc machines is similar to those discussed with SMAW, TIG, and MIG welding machines. Follow the guidelines we mentioned earlier.

Protective equipment

When you are arc cutting, wear the same personal protective equipment as you would for SMAW to keep hot metal spatter **fro**burning you. Again, that equipment consists **at ther** jacket, leg covers, gloves, and hood.

Self-Test Questions

After you complete these questions, you may check your answers at the end of the unit.

620. Arc cutting procedures

- 1. What arc cutting process uses a thickly covered electrode with a slow burning cover to generate the cutting arc?
- 2. What polaritydo we always use during the **dbi**ed metal arc cutting process?
- 3. Which arc cutting process uses carbon elects@de
- 4. Which arc cutting process usetubular electrode

Answers to Self -Test Questions

619

- 1. Argon-hydrogen on itrogen hydrogen mixtures
- 2. Transfer and notransfer
- 3. Electrical current and gas flow.
- 4. #12.

620

- 1. Shielded metal arc cuttir(SMAC).
- 2. Direct current straight polarit(DCEN/DCSP, DC).
- 3. Carbon arc cutting.
- 4. Oxygenarc cutting.

Unit Review Exercises

Note to Student: Consider all choices carefully, select betanswer to each question, and circle the corresponding letter. When you have completed all unit we is crises, transfer your answers to the Field Scoring Answer Sheet.

Do not return your answer sheet to the Air Force Career Development Academy (AFCDA).

- 84. (619) When compared to other arc cutting processes, the plasmaates the
 - a. roughest and fæsst cut.
 - b. roughest and slowest cut.
 - c. smoothest and fastest cut
 - d. smoothest and slowest cut.
- 85. (619) When cutting aluminum or stainless steel with the plasma arc process, what type of gas mixture gives the best results?
 - a. Argonhelium or argomitrogen.
 - b. Argonhydrogen or argonitrogen.
 - c. Argon-hydrogen or nitrogehydrogen
 - d. Nitrogenhelium or nitrogerhydrogen.
- 86. (619) What plasma arc cutting method oulses the heat produced by the plasma changing to gas to melt the base metal
 - a. Directarc.
 - b. Indirect arc.
 - c. Transfer arc.
 - d. Nontransfer arc.
- 87. (619) What is the recommendees shade number when using to 300 amps for plasma arc cutting?
 - a. #6.
 - b. #9.
 - c. #12.
 - d. #14.
- 88. (620) The first step in the shielded metal arc cutting process is to determine the thickness and type of metal to be cut. This information determines the correct
 - a. current and weld angle.
 - b. amperage and work angle.
 - c. electrode, work, and travel angle.
 - d. electrode and welding machine adjustment
- 89. (620) Regadless of the type of electrode used during shielded metal arc cutting, the welding machine should always be set to
 - a. direct currenteverse polarity DCRP/DCEP (DC+).
 - b. direct currenstraight polarity DCSP/DCEN (DQ.
 - c. alternating current, high frequency (ACHF).
 - d. alternating current.

- 90. (620) A low carbon electrode is used in a progressive cutting operation known as a. oxy arc cutting.b. carbon arc cutting.

 - c. ferrous arc cutting.
 - d. shielded metal arc cutting.

- **Hard surfacing**—Also known as hard facing. It is a treatment accomplished by applying hard alloys to the surface of a softer metal to increase resistance to wear, abrasion, corrosion and impact. This process is not a**bc**able to all metals and alloys.
- Heat affected zone—Part of the base metal where the hearthfiwedding, brazing, soldering, or thermal cutting has changed mechanical properties or grain structure.
- Helium—A colorless, odorlessnontoxic and tasteless integras. Muchighter than air, it is the second lightest of all gases.
- Included angle—An angle formed when two bevels are placed together. For example, two pipes with 22½degree bevels are placed together forming a butt joint, the included angle is 45 degrees.
- Inclusion—Entrapped foreign solid material, such as slag, flux, tungsten, or oxide.

Inert gas—A chemically inactive gas; it will not combine with any other element.

Joint—The junction of members or edges of members that are to be joined or have interest point

Joint root—The joint portion to be welded where the two materials are closest to each other.

Lap joint • A joint between two overlapping members in parallel planes.

- Laying surface—The mating surface of a member that is in contact with or in closenpity to another member to which it is being joined.
- Leg—A term used in shielded metal arc welding of tee joints. It refers to the distance from the root of the joint to the toe of the fillet weld.
- Padding—Welding a bead layer or layers to build up a metal surface.

Perpendicular—Forming a right angle (90 degrees).

- Plasma—A highly ionized gas that is electrically neutral.
- Plasma arc cutting—A process that uses a constricted plasma arc to quickly cut a smooth, small line through metal.
- Porosity—Gas pockets forned in a weld.
- **Preheating**—A process that heats metal to a certain temperature to prepare it for surfacing, welding, or cutting operation.
- Quenching—A process to rapidly cool an item by contacting the item with fluids or gases. For example, use oil or water cool hot metal.
- Rectification—Converting alternating current into direct current.
- Scarf—A chamfered joint surface.
- Slag inclusion—Produced during welding. It is nonetallic solid material that is trapped in the weld metal between the weld metal and thas metal.
- Surface tension—The force that keeps the molten metal and slag globules in contact with the molten base metal or weld metal in the crater.
- Tee joint—a joint between two members located approximately at right angles to each other in the form of a "T".
- Weldment—An assembly of components that are joined by welding.
- Weld metal—The weld portion that has been melted during welding.
- Weld Symbol—Shows the desired type of weld, whether it is localized or all around and if it is shop or field weld.

Abbreviations and Acronyms

| AC | alternating current |
|--------------------|--|
| AC-DC | alternating currendirect current |
| ACHF | alternating currentligh-frequency |
| AFOSH | Air Force Occupational Safety and Health |
| AWS | American Welding Society |
| CDC | career development course |
| CFETP | career feld education and training plan |
| cfh | cubic feet per hour |
| DC | direct current |
| DC- | direct current negative |
| DC+ | direct current positive |
| DCEN/DCSP (or DC-) | direct current electrode negative |
| DCEP/DCRP (or DC+) | direct current electrode positive |
| DC-RP | direct currentreverse polarity |
| DC-SP | direct currentstraight polarity |
| Ε | electric |
| GTAW | gas tungsten arc welding |
| lpm | liters per minute |
| MIG | metallic inert gas (welding) |
| MSDS | material safety data sheet |
| °F | °Fahrenheit |
| psi | pounds per square inch |
| SMAC | shielded metal arc cutting |
| SMAW | shielded metal arc welding |
| Т | thickness |
| TIG | tungsten inert gas |
| ТО | technical order |

Student Notes

Student Notes

AFSC 3E351 E3E351 04 1508 Edit Code 01